


1950

Correlation Chart



1800

1850


1900

 $\begin{array}{l} x=\\ y=\\ Const=627.402007459\\ a=-3.45388845091\;;\;b=0.00434704914682\\ c=-2.06633465198e-06\;;\;d=3.38956220464e-10 \end{array}$


2000

2050

2100



x =



y = Const = -4112.90285274 a = 6.36570634324; b = -0.00327348691916 c = 5.59485637716e-07; d = NA