

MUNICIPAL HAZARD ANALYSIS REPORT

Generated on: November 4, 2025 at 10:45 AM

EXECUTIVE SUMMARY

MUNICIPAL HAZARD ANALYSIS REPORT

RISK ASSESSMENT: LOW Report Statistics: 2 total reports | 100% resolution rate Active Hazards: 0 | Pending: 0 Trend: insufficient data

EXECUTIVE SUMMARY

MONITOR attention required. Analysis of 2 hazard reports shows insufficient data activity with 0 unresolved cases. Primary concentration in Mariesville, Bacayao Sur.

CRITICAL FINDINGS

• GEOGRAPHIC HOTSPOTS: Mariesville (1) | Bacayao Sur (1) • HAZARD DISTRIBUTION: Flood (1) | Pothole (1) • OPERATIONAL STATUS: 0 pending verifications, 2 verified reports

PRIORITY ACTIONS

1. Flood control and drainage improvement (1 cases) 2. Road repair and maintenance (1 cases)

AGENCY COORDINATION

• Primary: MDRRMO, PAGASA, DPWH • Support: Barangay Council, LGU DRRM, LGU Engineering
Generated: Tuesday, November 4, 2025

DETAILED ANALYSIS & RECOMMENDATIONS

Ø=Þ" EXECUTIVE SUMMARY

The Municipal Hazard Analysis Report indicates a low risk assessment with a total of two reports filed, both of which have been resolved. There is a noted lack of data activity, with no active or pending hazards at this time. The primary geographic hotspots identified are Mariesville and Bacayao Sur, where the focus will be on addressing flood control and road maintenance.

Ø=ÜÊ CURRENT SITUATION

- Key statistics and trends

- Total reports: 2

- Resolution rate: 100%

- Active hazards: 0

- Pending hazards: 0

- Trend: Insufficient data

- Geographic hotspots

- Mariesville: 1 report

- Bacayao Sur: 1 report

- Hazard distribution

- Flood: 1 report

- Pothole: 1 report

Ø<ß" IMMEDIATE ACTIONS (Next 7 days)

1. Initiate flood control and drainage improvement measures in Mariesville.

2. Commence road repair and maintenance activities in Bacayao Sur.

- 3. Coordinate with the Municipal Disaster Risk Reduction and Management Office (MDRRMO) for resource allocation.
- 4. Engage with local agencies (PAGASA and DPWH) for technical support and monitoring.

Ø=Ü° RESOURCE REQUIREMENTS

- Budget breakdown
 - Estimated budget for flood control: 50,000
 - Estimated budget for road repair: 30,000
- Manpower needs
 - 5 personnel from MDRRMO
 - 3 personnel from LGU Engineering
- Timeline
 - Actions to be initiated within 7 days and completed within 30 days.

Ø=ÜË ACTION MATRIX

Task	Responsible	Deadline	Budget
-----	-----	-----	-----
Flood control improvement	MDRRMO	November 11, 2025	50,000
Road repair and maintenance	LGU Engineering	November 11, 2025	30,000
Resource allocation coordination	MDRRMO	November 7, 2025	-
Technical support engagement	PAGASA, DPWH	November 9, 2025	-

& p RISKS & CONTINGENCIES

- If not addressed, the lack of flood control and road maintenance could lead to increased hazards and

potential damage during adverse weather conditions.

- Backup plans include reallocating resources from other departments and engaging local volunteers for immediate response efforts.

STATISTICAL OVERVIEW

- Total Reports: 2
- Verified Reports: 2
- Pending Verification: 0
- Resolved Hazards: 2
- Active Hazards: 0
- Resolution Rate: 100.0%
- Verification Rate: 100%

MOST REPORTED BARANGAYS:

1. Mariesville: 1 reports
2. Bacayao Sur: 1 reports

HAZARD TYPE DISTRIBUTION:

1. Flood: 1 cases
2. Pothole: 1 cases