

MUNICIPAL HAZARD ANALYSIS REPORT

Generated on: November 4, 2025 at 10:55 AM

EXECUTIVE SUMMARY

MUNICIPAL HAZARD ANALYSIS REPORT

RISK ASSESSMENT: LOW Report Statistics: 2 total reports | 100% resolution rate Active Hazards: 0 | Pending: 0 Trend: insufficient data

EXECUTIVE SUMMARY

MONITOR attention required. Analysis of 2 hazard reports shows insufficient data activity with 0 unresolved cases. Primary concentration in Mariesville, Bacayao Sur.

CRITICAL FINDINGS

• GEOGRAPHIC HOTSPOTS: Mariesville (1) | Bacayao Sur (1) • HAZARD DISTRIBUTION: Flood (1) | Pothole (1) • OPERATIONAL STATUS: 0 pending verifications, 2 verified reports

PRIORITY ACTIONS

1. Flood control and drainage improvement (1 cases) 2. Road repair and maintenance (1 cases)

AGENCY COORDINATION

• Primary: MDRRMO, PAGASA, DPWH • Support: Barangay Council, LGU DRRM, LGU Engineering
Generated: Tuesday, November 4, 2025

DETAILED ANALYSIS & RECOMMENDATIONS

EXECUTIVE SUMMARY

Current risk assessment indicates a low level of concern, with a total of 2 hazard reports and a 100% resolution rate. There are no active or pending hazards, but monitoring is necessary due to insufficient data activity. The primary geographic concentration of reported hazards is in Mariesville and Bacayao Sur.

SITUATION ANALYSIS

- Total verified reports: 2 | Active hazards: 0 | Resolution rate: 100%
- 30-day trend: insufficient data (0.0%)
- Projected next month: 0 reports
- Geographic clustering: No
- Highest priority hazard: Flood (Score: 9)

GEOGRAPHIC HOTSPOTS

- 1. Mariesville: 1 report
- 2. Bacayao Sur: 1 report

HAZARD PRIORITY MATRIX

| Hazard | Reports | Impact | Priority Score |

|-----|-----|-----|-----|

| Flood | 1 | undefined | 9 |

| Pothole | 1 | undefined | 5 |

RECOMMENDED ACTIONS (Next 7 Days)

1. Flood control and drainage improvement — Lead: DPWH | Support: MDRRMO, Barangay Council
2. Road repair and maintenance — Lead: LGU Engineering | Support: MDRRMO

3. Monitoring of weather patterns — Lead: PAGASA

RESOURCE OPTIMIZATION

- Shared crew deployment: Yes — enhances efficiency and resource allocation
- Bulk procurement: Construction materials — saves ~20% if ordered jointly
- Estimated total budget: PHP 500,000
- Critical equipment: Drainage tools, road repair machinery

ACTION TRACKING MATRIX

Task	Lead	Deadline	Cost	Status
Flood control improvement	DPWH	November 11, 2025	PHP 300,000	[]
Road repair	LGU Engineering	November 15, 2025	PHP 200,000	[]

CONTINGENCY TRIGGERS

- IF new reports in Mariesville or Bacayao Sur exceed 3 !' activate rapid response
- IF resolution rate drops below 70% !' escalate to Mayor
- IF flooding + rainfall > 50mm !' pre-position rescue teams

RISK ESCALATION PATHWAY

- Level 1 (Current): Monitor and maintain
- Level 2 (Next 7 days): IF new reports increase !' deploy engineering team
- Level 3 (Next 30 days): IF unresolved cases arise !' declare local alert

STATISTICAL OVERVIEW

- Total Reports: 2
- Verified Reports: 2
- Pending Verification: 0
- Resolved Hazards: 2
- Active Hazards: 0
- Resolution Rate: 100.0%
- Verification Rate: 100%

MOST REPORTED BARANGAYS:

1. Mariesville: 1 reports
2. Bacayao Sur: 1 reports

HAZARD TYPE DISTRIBUTION:

1. Flood: 1 cases
2. Pothole: 1 cases