

RESULTS BY WORKLIST

Serial Number: 00196	System SW Version: 3.2.5.9	Date Range: 9/6/2012 5:57:03 PM to 9/6/2012 7:32:02 PM
Assay: CT/GC		
Worklist IDs: 00196-20120906-01 Version: 1.38 (For Investigational Use Only) ML: 613010 Exp: 11/15/2013		
Operators: admin		
Specimen Tested: 50	CT POS: 34 GC POS: 10 Invalid: 1	
Status Flag Legend: IUO - For Investigational Use Only NTI - Sample not tested due to a fatal hardware error. p - Assay Processing Error. RDFS - Sample dispense verification failed. VVFS - LLS measurement of TCR/Sample in MTU tube falls outside the expected volume		
Reviewed By: _____	Date: _____	Verified By: _____ Date: _____

CT/GC

Version: 1.38 (For Investigational Use Only)

Worklist ID: 00196-20120906-01

Time	Rack-Tube #	Sample ID	Total RLU	CT Result	GC Result	Flags
9/6/2012 5:57:03 PM	720-00	CT Positive Control - Lot 608400	1145	CT POS	GC neg	IUO
9/6/2012 5:57:03 PM	720-00	GC Positive Control - Lot 610260	1149	CT neg	GC POS	IUO
9/6/2012 5:57:03 PM	726-00	PANEL-D-595953	2226	CT POS	GC POS	IUO
9/6/2012 5:57:03 PM	726-00	PANEL-B-596532	1119	CT POS	GC neg	IUO
9/6/2012 5:57:03 PM	726-00	PANEL-C-596256	1126	CT neg	GC POS	IUO
9/6/2012 6:02:03 PM	726-00	PANEL-E-600066	873	CT POS	GC neg	IUO
9/6/2012 6:02:03 PM	726-00	PANEL-A-600869	8	CT neg	GC neg	IUO
9/6/2012 6:02:03 PM	726-00	PANEL-D-595953	2238	CT POS	GC POS	IUO
9/6/2012 6:02:03 PM	726-00	PANEL-B-596532	1150	CT POS	GC neg	IUO
9/6/2012 6:02:03 PM	726-00	PANEL-C-596256	1116	CT neg	GC POS	IUO
9/6/2012 6:07:03 PM	726-00	PANEL-E-600066	735	CT POS	GC neg	IUO
9/6/2012 6:07:03 PM	726-00	PANEL-A-600869	5	CT neg	GC neg	IUO
9/6/2012 6:07:03 PM	726-00	PANEL-D-595953	2255	CT POS	GC POS	IUO
9/6/2012 6:07:03 PM	726-00	PANEL-B-596532	1136	CT POS	GC neg	IUO

CT/GC**Version: 1.38 (For Investigational Use Only)**

Time	Rack-Tube #	Sample ID	Total RLU	CT Result	GC Result	Flags
9/6/2012 6:07:03 PM	726-00	PANEL-C-596256	1132	CT neg	GC POS	IUO
9/6/2012 6:12:03 PM	726-00	PANEL-E-600066	1155	CT POS	GC neg	IUO
9/6/2012 6:12:03 PM	726-00	PANEL-A-600869	5	CT neg	GC neg	IUO
9/6/2012 6:12:03 PM	516-00	PANEL-D-595953	2252	CT POS	GC POS	IUO
9/6/2012 6:12:03 PM	516-00	PANEL-B-596532	985	CT POS	GC neg	IUO
9/6/2012 6:12:03 PM	516-00	PANEL-C-596256	1083	CT neg	GC POS	IUO
9/6/2012 6:17:03 PM	516-00	PANEL-E-600066	1032	CT POS	GC neg	IUO
9/6/2012 6:17:03 PM	516-00	PANEL-A-600869	6	CT neg	GC neg	IUO
9/6/2012 6:17:03 PM	516-00	PANEL-D-595953	2231	CT POS	GC POS	IUO
9/6/2012 6:17:03 PM	516-00	PANEL-B-596532	1135	CT POS	GC neg	IUO
9/6/2012 6:17:03 PM	516-00	PANEL-C-596256	1113	CT neg	GC POS	IUO
9/6/2012 6:22:03 PM	516-00	PANEL-E-600066	939	CT POS	GC neg	IUO
9/6/2012 6:22:03 PM	516-00	PANEL-A-600869	5	CT neg	GC neg	IUO
9/6/2012 6:22:03 PM	516-00	PANEL-A-600869	10	CT neg	GC neg	IUO
9/6/2012 6:22:03 PM	516-00	PANEL-A-600869	7	CT neg	GC neg	IUO
9/6/2012 6:22:03 PM	516-00	PANEL-A-600869	8	CT neg	GC neg	IUO
9/6/2012 6:27:03 PM	516-00	PANEL-A-600869	4	CT neg	GC neg	IUO
9/6/2012 6:27:03 PM	516-00	PANEL-A-600869	6	CT neg	GC neg	IUO
9/6/2012 6:27:03 PM	552-00	PANEL-E-600066	0	Invalid	Invalid	IUO, NTI, VVFS, RDFS, p
9/6/2012 6:27:03 PM	552-00	PANEL-E-600066	723	CT POS	GC neg	IUO
9/6/2012 6:27:03 PM	552-00	PANEL-E-600066	862	CT POS	GC neg	IUO
9/6/2012 6:32:03 PM	552-00	PANEL-E-600066	880	CT POS	GC neg	IUO
9/6/2012 6:32:03 PM	552-00	PANEL-E-600066	890	CT POS	GC neg	IUO
9/6/2012 6:32:03 PM	552-00	PANEL-E-600066	1031	CT POS	GC neg	IUO
9/6/2012 6:32:03 PM	552-00	PANEL-E-600066	1054	CT POS	GC neg	IUO
9/6/2012 6:32:03 PM	552-00	PANEL-E-600066	936	CT POS	GC neg	IUO
9/6/2012 6:37:03 PM	552-00	PANEL-E-600066	894	CT POS	GC neg	IUO
9/6/2012 6:37:03 PM	552-00	PANEL-E-600066	973	CT POS	GC neg	IUO
9/6/2012 6:37:03 PM	552-00	PANEL-E-600066	848	CT POS	GC neg	IUO
9/6/2012 6:37:03 PM	552-00	PANEL-E-600066	915	CT POS	GC neg	IUO
9/6/2012 6:37:03 PM	552-00	PANEL-E-600066	923	CT POS	GC neg	IUO

Internal Training Use Only

CT/GC**Version: 1.38 (For Investigational Use Only)**

Time	Rack-Tube #	Sample ID	Total RLU	CT Result	GC Result	Flags
9/6/2012 6:42:03 PM	552-00	PANEL-E-600066	825	CT POS	GC neg	IUO
9/6/2012 6:42:03 PM	552-00	PANEL-E-600066	847	CT POS	GC neg	IUO
9/6/2012 6:42:03 PM	418-00	PANEL-E-608717	993	CT POS	GC neg	IUO
9/6/2012 6:42:03 PM	418-00	PANEL-E-608717	1011	CT POS	GC neg	IUO
9/6/2012 6:42:03 PM	418-00	PANEL-E-608717	648	CT POS	GC neg	IUO
9/6/2012 7:32:02 PM	418-00	PANEL-E-608717	1064	CT POS	GC neg	IUO
9/6/2012 7:32:02 PM	418-00	PANEL-E-608717	981	CT POS	GC neg	IUO

Internal Training Use Only