

GRIFOLS Diagnostic Grifols, S.A.	Reference:	REGD-0000809	Version:	3.0, CURRENT
	Status:	Effective	Effective Date:	27-Jun-2011
Title:	SM DG57-DG517. PCA Robot-2 4 axis fuse status verification.			Page 2 of 4

DG-57 / DG-517 Service Manual

PCA ROBOT-2 4 AXIS FUSE STATUS VERIFICATION

Procedure description
This procedure describes how check the fuses in Robot-2 PCA. <i>Note: Document REGD-0000809_v3 replaces document REGD-0000809_v2.</i>


GRIFOLS Diagnostic Grifols, S.A.	Reference:	REGD-0000809	Version:	3.0, CURRENT
	Status:	Effective	Effective Date:	27-Jun-2011
Title:	SM DG57-DG517. PCA Robot-2 4 axis fuse status verification.			Page 3 of 4

EQUIPMENT

1. Multimeter.


SET UP

1. Turn instrument on.
2. Open the rear panel
3. Turn instrument off



CAUTION!
Short-circuit between any powered part and ground, may damage the instrument.

PROCEDURE

Process	Expected Results
Checking the 24V fuse 1. To check the fuse status, measure the voltage between TP7 (negative) and TP4 (positive) with the multimeter (see Picture 1)  2. If the measured value is not the expected, then the FUS1 is broken.	23.95 ± 0,05 V ---

GRIFOLS Diagnostic Grifols, S.A.	Reference:	REGD-0000809	Version:	3.0, CURRENT
	Status:	Effective	Effective Date:	27-Jun-2011
Title:	SM DG57-DG517. PCA Robot-2 4 axis fuse status verification.			Page 4 of 4

DOCUMENT CHANGE HISTORY

Document change history			
Version	Date	Change	Rationale
2.0	2005/05/09	Document REGD-0000809_v2 replaces document 57037V0M000.	Document reference changed.
3.0	See document header.	Added previous version 'data', 'change' and 'rationale' inside document change history section.	Update change history for previous document history modification.
3.0	See document header.	Document REGD-0000809_v3 replaces document REGD-0000809_v2.	Document version changed.
3.0	See document header.	Document title.	Commercial reference substituted by project reference.
3.0	See document header.	Document header.	Increase information to easy document search.