

GT-01 - EQUIPMENT INSPECTION REPORT

Inspection Information

Equipment ID: GT-01

Inspection Date: 04 September 2026

Inspection Type: Routine Condition Inspection

Department: Maintenance

Observed Operating Parameters

Observed turbine temperature: 587°C.

Observed vibration: 8.2 mm/s.

Observed operating condition: Equipment was running during inspection.

Visual Inspection

Abnormal vibration was detected near the bearing housing.

No visible external damage was observed on the turbine enclosure.

Temperature sensor readings were recorded successfully.

Inspector Assessment

The measured temperature is above the critical temperature threshold specified in the maintenance manual.

The measured vibration is above the specified inspection threshold.

The combination of elevated temperature and abnormal vibration requires immediate maintenance attention.

Recommended Initial Action

Initiate the applicable controlled shutdown procedure.

Notify the maintenance supervisor.

Inspect the bearing and rotor assembly after the equipment reaches a safe condition.