

GT-01 - GAS TURBINE SAFETY SOP

Purpose

This procedure defines the safe response to abnormal operating conditions involving industrial gas turbine GT-01.

Critical Temperature Procedure

If turbine temperature exceeds 580°C, treat the condition as critical.

Initiate a controlled shutdown using the approved shutdown procedure.

Notify the maintenance supervisor and control-room operator.

Record the event in the equipment incident log.

Post-Shutdown Safety

Do not open the turbine enclosure immediately after shutdown.

Allow the equipment to reach the approved safe temperature before inspection.

Follow site isolation and lockout procedures before maintenance work begins.

Only authorized maintenance personnel may inspect internal turbine components.

Abnormal Vibration Procedure

If vibration exceeds 7 mm/s, stop normal operation and initiate an inspection.

Inspect the bearing system and rotor assembly.

Check lubrication condition and relevant monitoring sensors.

Document all findings before returning equipment to service.

Documentation Requirements

All abnormal conditions, shutdown actions, inspection findings, and maintenance activities must be recorded.

The maintenance supervisor must review the completed maintenance record before the equipment is returned to normal operation.