

Conservation of Momentum

Newton's second law of motion applied to rotating frame of reference gives expression for torque.

* Rate of change in angular momentum produces torque.




Figure 5.3: A Generic Turbomachinery Flow Passage

$$T = \frac{aL}{dt}$$

Where 'T' is torque, 'L' is angular momentum and 't' is time.

Angular momentum is given by $L = mV_{\theta}r$

❖ Where 'm' is mass, r is radius and V_θ is tangential component of velocity.



Conservation of Momentum

Now applying time rate of change of momentum across inlet and exit for a turbomachinery, we obtain,

$$T = \frac{dL}{dt} = \frac{d}{dt} (m_2 V_{2\theta} r_2 - m_1 V_{1\theta} r_1)$$

$$= \frac{d}{dt} m (V_{2\theta} r_2 - V_{1\theta} r_1) \quad \text{Continuity}$$

$$= \dot{m} (V_{2\theta} r_2 - V_{1\theta} r_1)$$

Power produced is given by

$$P = T\omega = m\omega(V_{2\theta}r_2 - V_{1\theta}r_1) = \dot{m}(V_{2\theta}U_2 - V_{1\theta}U_1)$$

Power per unit mass flow rate is Euler turbomachinery eq:

$$W = \omega(V_{2\theta}r_2 - V_{1\theta}r_1) = (V_{2\theta}U_2 - V_{1\theta}U_1) = \Delta(UV_{\theta})$$



Euler Work Equation

Note that for Euler Work Equation

- Turbine work would be negative and compressor work would be positive
- Power input or power output is entirely given by change in angular momentum.
 - Essentially energy interaction is governed by flow turning.
- Change in radius affects the angular momentum (moment arm changes in moment of momentum); hence radial flow machine tend to have larger power production/absorption per stage compared to axial flow machine.



Example A turbine stage with a rotational speed of $3000 \ rpm$ is to be designed with an absolute inlet angle of 60° and an absolute exit angle of -60° at a mean radius of $0.4 \ m$. The machine is to be designed for a constant axial velocity of $450 \ m/s$. Estimate the specific work from this stage.

Indian Institute of Technology Hyderaba


Note that specific work is same as Euler work.

$$\mathcal{W} = \Delta(UV_{\theta}) = (V_{2\theta}U_2 - V_{1\theta}U_1) = U(V_{2\theta} - V_{1\theta})$$

$$U = 3000 \times \frac{2\pi}{60} \times 0.4 = 125.6 \ m/s$$

$$V_{\theta} = V_x \tan \alpha$$

 $V_{1\theta} = 450 \tan 60 = 779 \ m/s$
 $V_{2\theta} = 450 \tan -60 = -779 \ m/s$




$$W = U(V_{2\theta} - V_{1\theta}) = 125.6(-779 - 779)$$

= -195.8 kJ/kg



Cascade of Blades

Notice the difference in flow deflection for single and cascade of airfoils.



- In cascade of blades flow turning can be achieved more due to interference from adjacent blades with flow.
- Note that in Grant
 Ingram's book
 boundary layer effect
 is not included.


Figure 5.4: Isolated Aerofoil compared to a Cascade

Conservation of Energy & Rothalpy



Recall steady flow energy equation form of first law of thermodynamics.

$$\dot{q} + \dot{w} = \dot{m} \left[(h_2 - h_1) + \frac{1}{2} (V_2^2 - V_1^2) + g(z_2 - z_1) \right]$$



with negligible difference in datum head at inlet and exit of turbomachinery compare to change in velocity and enthalpy then work done is given by

$$\dot{w} = \dot{m} \left[(h_2 - h_1) + \frac{1}{2} (V_2^2 - V_1^2) \right]$$

$$\dot{w} = \dot{m} \left[\left(h_2 + \frac{V_2^2}{2} \right) - \left(h_1 + \frac{V_1^2}{2} \right) \right]$$


Conservation of Energy & Rothalpy



Recall static and stagnation/total properties of flow.

* Rate of doing work can be written as

$$\dot{w} = \dot{m} \left[h_{02} - h_{01} \right]$$



Specific work expression can be written as

$$\dot{w}/\dot{m} = w = h_{02} - h_{01}$$

Specific work is Euler's work derived previously.

$$w = U_2 V_{2\theta} - U_1 V_{1\theta} = h_{02} - h_{01} \implies h_{01} - U_1 V_{1\theta} = h_{02} - U_2 V_{2\theta}$$

i.e. $h_0 - UV_0 = Constant$



Rothalpy

Defining Rothalpy as $I = h_0 - UV_\theta$

- From rearrangement of steady flow energy equation we obtain expression for Rothalpy, which is conserved over the blade row
 - Note that inlet station rothalpy is same as rothalpy at exit station.

For stators, blade speed U = 0; hence rothalpy conservation simply changes to

$$I_1 = I_2 \implies h_{01} = h_{02}$$



 $V_{\theta} = U + W_{\theta}$

Rothalpy in Rotors

We know that,
$$V_x = W_x$$
 and $V_\theta = U + W_\theta \& V^2 = V_x^2 + V_\theta^2$
 $V^2 = V_x^2 + V_\theta^2 = W_x^2 + (W_\theta + U)^2 = W^2 + 2W_\theta U + U^2$




Figure 5.5: Generic Velocity Triangle

Rothalpy conservation across rotor gives

$$I_1 = I_2 \implies h_{01} - UV_{1\theta} = h_{02} - UV_{2\theta}$$

$$W_x$$
 i.e. $h_1 + \frac{V_1^2}{2} - UV_{1\theta} = h_2 + \frac{V_2^2}{2} - UV_{2\theta}$

Substituting expression

$$LHS = h_1 + \frac{V_1^2}{2} - UV_{1\theta} = h_1 + \frac{W_1^2}{2} - \frac{U_1^2}{2}$$



Rothalpy in Rotors

Defining relative stagnation enthalpy as follows

$$h_{0rel} = h + rac{W^2}{2}$$
 $LHS = h_1 + rac{V_1^2}{2} - UV_{1 heta} = h_1 + rac{W_1^2}{2} - rac{U_1^2}{2}$
 $h_{0rel1} - rac{U_1^2}{2} = h_{0rel2} - rac{U_2^2}{2}$

1. An industrial gas turbine operates at an 8.8:1 pressure ratio and a mass flow of $77 \, kg/s$. The exhaust temperature is at $437^{\circ}C$ and the inlet temperature to the machine is around $1000^{\circ}C$. The machine is to be designed for a constant axial velocity of $200 \, m/s$. (This data is based on the Rolls-Royce Avon, an engine that dates from the 1950s but is still used as low efficiency high reliability engine for stationary power such as pipeline pumping.)

For this gas turbine, draw to scale the meridional view with:

- (a) a constant mean radius of 0.4 m.
- (b) a constant outer diameter (to minimise cross sectional area) of 1.05 m.

1. An industrial gas turbine operates at an 8.8:1 pressure ratio and a mass flow of $77 \, kg/s$. The exhaust temperature is at $437^{\circ}C$ and the inlet temperature to the machine is around $1000^{\circ}C$. The machine is to be designed for a constant axial velocity of $200 \, m/s$. (This data is based on the Rolls-Royce Avon, an engine that dates from the 1950s but is still used as low efficiency high reliability engine for stationary power such as pipeline pumping.)

For this gas turbine, draw to scale the meridional view with:

- (a) a constant mean radius of 0.4 m.
- (b) a constant outer diameter (to minimise cross sectional area) of 1.05 m.

$$m = 77 \frac{kg}{3}$$

$$T_{2} = 437C, T_{1} = 1000C$$

$$V_{x} = 200m/s$$


$$(a) C_{1}A_{1}V_{1}N = 77$$

$$C_{1}A_{1} = \frac{77}{200}$$

$$C_{1}A_{1}V_{1}N = \frac{77}{200}$$

$$C_{1}A_{2}V_{1}N = \frac{77}{200}$$

$$C_{2}$$






1. An industrial gas turbine operates at an 8.8:1 pressure ratio and a mass flow of $77 \, kg/s$. The exhaust temperature is at $437^{\circ}C$ and the inlet temperature to the machine is around $1000^{\circ}C$. The machine is to be designed for a constant axial velocity of $200 \, m/s$. (This data is based on the Rolls-Royce Avon, an engine that dates from the 1950s but is still used as low efficiency high reliability engine for stationary power such as pipeline pumping.)

For this gas turbine, draw to scale the meridional view with:

- (a) a constant mean radius of 0.4 m.
- (b) a constant outer diameter (to minimise cross sectional area) of 1.05 m.





Indian Institute of Technology Hyderabad

$$e_{1} \times \pi = \frac{77}{200}$$

$$e_{1} \times \pi \left(82 - 82\right) = \frac{77}{200}$$

$$e_{1} \times \pi \left(1.05\right) - 82 = \frac{77}{200}$$

$$e_{2} \times \pi \left(1.05\right) - 82 = \frac{77}{200}$$

$$e_{3} \times \pi \left(1.05\right) - 82 = \frac{77}{200}$$

$$e_{4} \times \pi \left(1.05\right) - 82 = \frac{77}{200}$$

$$e_{5} \times \pi \left(1.05\right) - 82 = \frac{77}{200}$$


$$e_{7} \times \pi \left(1.05\right) - 82 = \frac{77}{$$


Consider an axial compressor rotor blade row. The inlet velocity is $150 \, m/s$ and is in the axial direction. The blade speed is $180 \, m/s$ and the relative outlet angle is $-30\circ$ to the axial. The axial velocity is constant across the row. Calculate the relative flow angle at inlet and the absolute swirl velocity at exit and the absolute flow angle. Calculate also the specific work output.

ingian institute of lechnology Hyderabad

Given Data: $V_1 = V_{1x} = 150 \text{ m/s} = V_{2x}$; U = 180 m/s; $\beta_2 = -30^{\circ}$


To Find:
$$\beta_1 = ?$$
; $V_{2\theta} = ?$; $\alpha_2 = ?$; $\mathcal{W} = ?$







Indian Institute of Technology Hyderabad








Lecture 8

Efficiency and Reaction

Problems

Efficiency of a Turbine





Note that 'station 1' is inlet and 'station 3' is exit with 'station 2' as exit of stator/entry to rotor

- Static pressure at entry to turbine is P_1 and Total pressure is P_{01}
- Similarly, static pressure at exit is P_3 and total pressure at exit is P_{03}
- Points 3s and 03s refer to static and total pressure at exit if expansion were isentropic in the turbine



Efficiency of a Turbine

Efficiency can be defined in various ways as follows:

Total to Total efficiency for turbine is given by


$$\eta_{it} = \frac{actual\ work\ done}{ideal\ work\ output} = \frac{(h_{03} - h_{01})}{(h_{03s}\ _h_{01})}$$

Total to Static efficiency

$$\eta_{it} = \frac{(h_{03} - h_{01})}{(h_{3s} - h_{1})}$$

Static to static efficiency

$$\eta_{it} = \frac{(h_3 - h_1)}{(h_{3s} \ h_1)}$$






Efficiency of a Compressor

Compressor is work absorbing turbomachines and efficiency is defined exactly opposite of a turbine.

Total to Total efficiency for turbine is given by






Example A compressor stage working on air at $1 \ bar$ and $25^{\circ}C$ has a work input of $17 \ kJ/kg$ and an isentropic efficiency of 0.9. The velocity at inlet and exit is the same. Assuming that the air properties are unchanged over the stage calculate the pressure output of the stage.

Note that there is no change in KE at inlet and exit of compressor. Also, calorically perfect gas is to be assumed

$$\Delta h = C_p \Delta T$$

$$P3/P1 = (T_{3s}/T_1)^{[\gamma/(\gamma-1)]}$$

$$\eta_{it} = \frac{(h_{3s} - h_1)}{(h_3 - h_1)}$$





Example A steam turbine stage operates with inlet conditions of 120bar and 500° , the exit pressure is $10 \ bar$. If the efficiency of the stage is 90% calculate the specific work output.

Given: $P_1 = 120$ bar; $P_3 = 10$ bar; T1 = 500°C; $\eta_{it} = 0.9$;

To Find: specific work output (Wactual)

h1:120 bar, 500C=3350KJ/Kg

h3s: 10 bar=2730KJ/kg

Either steam tables or Mollier chart

