



J6 seat, section through the servo axis (servo frame, mm)



idler horn: smallest gap 0.59 mm | overlaps not designed: 0