

[illegible]

drawing to be represented in the legend with correct line types.

s impossible to confirm whether proposed equipment falls within the lease area. Queries should be raised to DE & TL pending review of the lease boundary drawing and
nm wide cable ladder' without a cable fill/capacity check or reference to an as-built/photo verification as flagged in the annotation comments on the drawing; (2) The prop
sent. The leader callout on the G2 detail also lacks confirmation that the replacement signage positions comply with OSD-171 location requirements (1500 AGL typical n

match the correct model dimensions, constituting a FAIL for this rule check.

he referenced antenna and elevation drawings is required to make a definitive determination.

3501475, and correct address. No corrosion-specific note is required beyond Note 4 which covers corroded hardware. No missing data or empty required sections ident

ntity, or route details within the available drawings and photos.

g cannot be accepted for construction in its current state.

na system configurations (which contain the FR/schedule data), but those drawings are not included in the provided set. Without the antenna schedule/FR data showing

th sheets M8398-S4 and M8398-S8.

on details across both sheets.

