Course: Vehicle Inspection & Maintenance Course Code: MEE2043

Exam: WIN2021CAT1 Telegram Link: VIT QUESTION PAPERS

Exam: WIN2021CAT1 Telegram Link: <u>VIT QUESTION PAPERS</u>

1. An automobile engine piston has been damaged by a lack of lubrication between the piston and the cylinder wall. After dismantling the piston from the engine, scoring marks were noticed on the skirt of the piston. Describe how such a lubrication failure may have arisen. What effect would the clearance between the piston and the cylinder have on lubrication

- 2. List various causes that lead to overheating of engines? Explain any one reason in detail
- 3. Discuss the inspection and reconditioning work procedure for the cylinder block