

Final Assessment Test - November 2019 Course: MEE1005 - Materials Engineering and Technology

Class NBR(s): 1411 / 1836 / 1961

Slot: B2+TB2

Max. Marks: 100

Time: Three Hours KEEPING MOBILE PHONE/SMART WATCH, EVEN IN 'OFF' POSITION, IS EXAM MALPRACTICE

Answer ALL Questions (10 X 10 = 100 Marks)



a) Check the validity of statement with proper justification, "Slip in a single is independent of its

crystal structure". b) Consider a metal single crystal oriented such that the normal to the slip plane and the slip direction [5] are at angles of 60° and 35°, respectively, with the tensile axis. If the critical resolved shear stress is 5.4 MPa, will an applied stress of 14 MPa cause the single crystal to yield? If not, what stress will be necessary?

Elaborate the growth mechanism of pure metals and alloys. Calculate the size of the critical radius and the number of atoms in the critical nucleus when solid fon (Fe) forms by homogeneous nucleation. Given freezing temperature, heat of fusion, solid-liquid interfacial energy and undercooling as 1538 °C, 1737 J/cm³, 204 x 10⁷ J/cm², and 420 °C. Also given lattice parameter of

Fe is 0.28 nm. hear of freyor - Ou Draw Fe-Fe₃C Cementite (Fe₃C). Also define the phases present in it and invariant reactions.

Draw the continuous-cooling transformation diagram for a 0.35 wt% C iron-carbon alloy. Indicate and specify heat treatment strategies (with cooling rates) in continuous-cooling curves to yield the following microstructures:

Fine pearlite and proeutectoid ferrite

6) Martensite

8.0

Martensite and proeutectoid ferrite

Coarse pearlite and proeutectoid ferrite

Martensite, fine pearlite and proeutectoid ferrite

Elaborate the hardening technique of medium carbon steel for automotive shaft and gear. Elaborate on the case hardening techniques of low carbon steel for industries with the help of schematic sketches.

Elaborate on composition, microstructure, properties and application of different cast iron. Give

three benefits of cast iron over steel?

b) Why titanium based alloys are widely used in biomedical implants compared to stainless steel? Draw the stress strain curve of brass and indicate various regions in it. For a brass, the stress at which plastic deformation begins is 345 MPa and the modulus of elasticity is 103 GPa.

al[®] What is the maximum load that can be applied to a specimen with a cross-sectional area of 130 mm² without plastic deformation?

b) If the original specimen length is 76 mm, what is the maximum length to which it can be stretched without causing plastic deformation?

Discuss the strengthening mechanism of single phase materials and alloys with the help of schematic. Give the specific strengthening of aluminium alloys used in aerospace structures.

Classify polymers based on their thermal behaviour. Give examples of each. Also define glass [5] transition temperature in polymers.

Elaborate the powder metallurgical route involved in preparation and processing of ceramic materials with the help of schematic? metral - statement [5]



SEARCH VIT QUESTION PAPERS ON TELEGURAM TO JOIN