CS/B.TECH/ME(O)/ODD/SEM-7/ME-702/2019-20



MAULANA ABUL KALAM AZAD UNIVERSITY OF TECHNOLOGY, WEST BENGAL

Paper Code: ME-702

PUID: 07188 (To be mentioned in the main answer script)

ADVANCED MANUFACTURING TECHNOLOGY

Time Allotted: 3 Hours

Full Marks: 70

http://www.makaut.com

The figures in the margin indicate full marks.

Candidates are required to give their answers in their own words as far as practicable.

GROUP - A (Multiple Choice Type Questions)

- 1. Choose the correct alternatives for any ten of the following: $10 \times 1 = 10$
 - Jigs and fixture are used for
 - a) mass production
 - b) identical part production
 - c) both (a) and (b)
 - d) none of these.
 - ii) Material removal rate in ECM is governed by
 - a) Fleming's rule
- b) Newton's law
- Faraday's law
- d) None of these.
- iii) Which of the following is the function of jig?
 - a) Holding

- b) Guiding
- c) Locating
- , d) All of these.

\$-7409/7(O)

| Turn over

CS/B.TECH/ME(0)/ODD/SEM-7/ME-702/2019-20

iv) In USM the rate of penetration is dependent on					
a) action of sturry -					
	b) action of the abrasive grains				
	c) reduction of the chemical				
	d) all of these,				
v)	Jigs	Jigs are not used in			
	a)	Drilling	b)	Shaping '	
	c)	Milling	si)	Taping.	
V1)	Flex	Flexible manufacturing is economical for			
	production.				
	a)	batch,	b)	mass	
	c)	flow	d)	none of these.	
vii)	Work study is concerned with				
	n)	improving present	m	ethod and finding	
	standard time				
	b) motivation of workers				
	c) improving production capability				
	d) improving production planning and control.				
viii)	•				
	a)	graph paper	p)	process chart	
	_C)	planning chart	d)	•	
ix)	What does symbol 'O' imply in work study?				
	a)	Operation			
	b)	Inspection			
		Transport			
	d) Delay / temporary storage.				
x)	to the ball to imply in work study ?				
	b)	Transport		•	
	c)	Delay / temporary st	torag	je	
	di Permanent storage.				
XI)	and clamping device made by				
A-1	a)	low carbon steel	b)	High carbon steet	
	c)	high speed steel	d)	tool steel.	
	6)	1110 of all and a			

http://www.makaut.com

http://www.makaut.com

CS/B TECH/ME(O)/ODD/SEM-7/ME-702/2019-20

GROUP - B

(Short Answer Type Questions)

Answer any three of the following. 3 - 5 - 15

- 2 Write down the advantages and disadvantages wire cut EDM over conventional EDM.
- Draw the basic electrical waveform and describe spark initiation and MRR mechanism in EDM.
- 4. Write short notes on the following:
 - Cellular Manufacturing Systems
 - ii) Flexible Manufacturing System.

 $2\frac{1}{2} + 2\frac{1}{2}$

- 5. Estimate the Material removal rate (MRR) in Abrasive jet machining (AJM) of a brittle material with flow strength of 5 GPa. The abrasive flow rate is 3 gm/min, velocity is 205 m/s and density of the abrasive is 4 gm/cc. http://www.makaut.com
- Write the advantages and limitations of Ultrasonic process.

GROUP - C

(Long Answer Type Questions)

Answer any three of the following. 3 = 15 = 45

Write down the need of non-traditional machining process. Write the difference between traditional and non-traditional machining process. Explain with figure the ultrasonic machining process with its varies components.

3 + 5 + 7

◆ ● ·7409 / 7(0)


http://www.makaut.com

3

| Turn over

CS/B.TECH/ME(O)/ODD/SEM-7/ME-702/2019-20

- Describe with neat sketch the working principle of Laser beam machining process. Draw the schematic diagram of Abrasive Jet machining process set up.
- State the Faraday's law of electrolysis. Describe with figure Electrochemical Machining process. Write the advantages and limitation of it.
- 10. Explain with a neat sketch the operation of the canned cycle G81 as per ISO. Write the part programming for the component shown in the figure, keeping maximum depth of cut 2 mm. (All dimensions are in mm): 5 + 10



http://www.makaut.com

 Write part programming for the component shown in the figure. Diameter of the milling cutter is 28 mm. (All dimensions are in mm).

