DUMMY DOCUMENT - LAB TEST DATA - NOT A REAL DOLI DOCUMENT

Repair Report - RMA-2026-014

RMA number	RMA-2026-014
Device	RMCi8 controller
Serial number	RM8-11842
Fault	No power after site move
Root cause	Damaged power supply board (dummy)
Action	Board replaced, function test passed (dummy)

Returned to customer on 2026-02-02 (dummy).