

•PMRS STEP 2 : QUICK REPAIR

Repair Step Analysis (RSA)

Approve by

Checked by

Issue by

Dokument No

Revisi No

Date

Item Revisi

FR-MTC-GNP-060-00

00

11-Dec-25

-

▪ Problem :

X AXIS OVER LOAD

▪ Root Cause :

SERVO NG (RESISTANSI TIDAK SETABIL)

▪ Immediate Countermeasure :

GANTI MOTOR SERVO X

▪ Machine NO :

12GRID019

▪ Line / Area :

DAC

▪ Machine Maker :

KOYO MACHINE INDUSTRIES

▪ Process Name :

OR/RW GRINDING

▪ Start Time :

8:40 AM

▪ Stop Time :

12:00 AM

▪ Machine Rank :

▪ Problem Date :

01.12.2025

▪ Problem Analysis :

01.12.2025


▪ Prepared by Shift :

B

CURRENTLY REPAIR STEP		Duration (Mins)																				Quick6 Analysis	
No.	Process																					Min	Analysis
1	COBA MANUAL JOG MC LANGSUNG ALARM	15,0																				15,0	Q1-3
2	CEK KABEL DAN GANTI MOTOR SERVO		45,0																			45,0	Q2-3
3	CE SERVO MOTOR RESISTAN TIDAK STABIL SAAT BERPUTER			10,0																		10,0	Q5-3
4	LEPAS DAN GANTI SERVO				20,0																20,0	Q5-3	
5	GANTI KABEL ENCODER					20,0														20,0	Q5-1		
6	SETTING REPESEN AXIS X						30,0												30,0	Q5-3			
7	TCHINING BY PRODUKSI DAN TRIAL BY QC ADJUSTS OK							30,0												30,0	Q5-1		
8																							
9																							
10																							
11																							
12																							
13																							
14																							
15																							
16																							
17																							
18																							
19																							
20																							
21																							
22																							
23																							
24																							
25																							
26																							
27																							
28																							
29																							
30																							


IDEAL REPAIR [BEST STEP]		Duration (Mins)																				Quick6 Analysis		
No.	Process	0	10	20	30	40	50	60	70	80	90	100	110	120	130	140	150	160	170	180	190	200	Min	Q1-2
1	COBA MANUAL JOG MC LANGSUNG ALARM	5,0																					5,0	Q1-3
2	CEK KABEL DAN GANTI MOTOR SERVO		15,0																				15,0	Q2-3
3	CE SERVO MOTOR RESISTAN TIDAK STABIL SAAT BERPUTER			10,0																			10,0	Q5-3
4	LEPAS DAN GANTI SERVO				35,0																		35,0	Q5-3
5	GANTI KABEL ENCODER					5,0																	5,0	Q5-1
6	SETTING REPESEN AXIS X						10,0																10,0	Q5-3
7	TCHINING BY PRODUKSI DAN TRIAL OK							15,0															15,0	Q5-1
8	ANALISA PROBLEM								10														10	Q4-1
9																								
10																								
11																								
12																								
13																								
14																								
15																								
16																								
17																								
18																								
19																								
20																								
Total																						105	Min.	

If Q1 to Q5 more than
Long Time Repair (LTR) Criteria ,
Q6 (Back up) have to be considered



No.	MICRO CM for Quick Repair activity based on Quick 6 [Focus on Skill Reflection]	Quick 6	Target Date	PIC	EVA
1	MENGURANGI LANGKAH ANALISA PROBLEM	Q4-1	12/Mar/25	ROHMAT	0
2					
3					

QUICK 6		Bef	Aft
Q1 : Diagnosis		15	5
1-Diagnosis Skill		0	5
2-Human M/C interface		0	0
3-Drawing		15	0
4-Manual		0	0
Q2 : Spare Parts		45	15
1-On-hand		0	0
2-Ready to use		0	0
3-Storage codition		45	15
Q3 : Tools		0	0
1-Shop tool		0	0
2-Special tool		0	0
3-Personal tool		0	0
4-Safety tool		0	0
Q4 : Work Ability		0	10
1-Replace/Recovery skill		0	10
2-Working Environment		0	0
3-Design problem		0	0
Q5 : Setting Ability		135	75
1-Adjustment		50	20
2-Calibration		0	0
3-Data setting		85	55
4-Quality concern		0	0
5-P/D data concern		0	0
6-Interlock		0	0
Q6 : Back up		0	0
1-Switching time		0	0



Legend	
Δ	In Progress
X	Delay
O	Completed

<i>Management Comment / Feedback</i>	
--------------------------------------	--