

Factory Act - Sample Regulatory Extract

Sample regulatory extract for offline compliance lookup in Forge-Sense.

Factory Act 1948: every hazardous operation shall be controlled by a valid permit system, documented supervision, and maintained safety records.

Hot work shall not proceed without gas testing, fire watch, and accessible extinguishing equipment.

Inspection, calibration, and maintenance logs must be retained for audit review.

Compliance Notes

Restricted or high-voltage areas require controlled access, trained personnel, and emergency readiness before work starts.

Workers must receive safety instruction before engaging in hazardous tasks and emergency drills should be scheduled regularly.

Any observed non-conformance shall be corrected and recorded before the task is resumed.

This sample is intentionally concise for demo use and does not replace official legal text.