

n	function	axis	Error Location	Max_Sensitivity	Mean_Sensitivity
9	constant_1	X	E1	1.0	0.5007709703947368
9	constant_1	X	E2	0.0	0.0
9	constant_1	X	E3	0.0	0.0
9	constant_1	X	E4	1.0	0.49773848684210525
9	constant_1	Y	E1	1.0	0.49897203947368424
9	constant_1	Y	E2	1.0	0.5009251644736842
9	constant_1	Y	E3	1.0	0.49969161184210525
9	constant_1	Y	E4	1.0	0.5014391447368421
9	constant_1	Z	E1	0.0	0.0
9	constant_1	Z	E2	1.0	0.5005653782894737
9	constant_1	Z	E3	1.0	0.4973273026315789
9	constant_1	Z	E4	0.0	0.0