

Undocking
Transit
(a)
Urgency
Urgency (max 0.82)
Threshold 0.65
(b)
P(TakeoverRequest)
No takeover
Increased attention
Takeover requested
(c) evidence
nominal
degraded
worst state
not entered
SonarRange
Altitude
DVLStatus
USBLStrength
CameraQuality
ArUcoVisibility
Speed
Current
WaypointTrackingError
RangeToTarget
BatteryLevel
Fatigue
Stress
(d)
Operator
Fatigue
Stress
Mission time [s]