

(a) S1: obstacle on the transit leg



(b) S2: cross-current and loss of the USBL signal during inspection



Open loop
Closed loop
Takeover request (dashed line)
Hand-back
Contact
Manual control
Planned leg