Group 1	Barira,Abubakar Hannan, Zunaria,		BSIE Lab 07		Workstudy and Method Engineering IE223L		
Serial No	Name of Motion	Therblings Symbol	Description		Time	TMU(Time Measuring Unit) (1second=27.78 TMU)	
	Pin board 1 (Hannan, Zunaria)						
1	Transport empty	Draw TE	Move the pins from storage		1	27.78	
2	Select	Draw St	Select appropriate board and work center		2	55.56	
3	Grasp	Draw G	Pick the pins		1	27.78	
4	Transport Loaded	Draw TL	Transfer pins to board		5	138.9	
5	Position	Draw P	Starting using row method		20	555.6	
	Pin Board 2 (Abubakar, Barira)						
1	Transport loaded	Draw Tl	Move the pins from storage		5	138.9	
2	Position	Draw P	starting using column method		4	111.12	
3	Assemble	Draw A	Fix all pins		7	194.46	
4	Release Load	Draw RL	Push back hand		8	222.24	
	·						
	Prepared By	Prepared By Checked by					