INPUT:

Clock

Step1

Subtract

+

−

300

Gain

$$\frac{1}{s^2+10s+20}$$

Transfer Fcn

XY Graph

OUTPUT:

XY Graph

X Y Plot

Y Axis

5

4

3

2

1

0

-1

0   2   4   6   8   10

X Axis