

Design, firmware and software under one roof.

Acceedo builds industrial software and the IoT that feeds it — the board on the machine, the firmware inside it, the platform it reports to, and the sheet that comes out signed at the other end.

From the sensor to the signed sheet



Machines & sensors

PLCs, energy meters, biometric readers, spectrometers, crane beacons



Hardware & firmware

Our own boards and gateways — prototype through mass production



Edge & protocols

Mod bus, RS-485, TCP and MQTT; the raw frame decoded on arrival



Platform

Browser-based and multi-tenant, per-role access, an audit trail behind every edit



Screens & paperwork

Dashboards, phone consoles, Excel — and the PDF that gets signed

Our strengths



Connected IoT Ecosystems

Legacy machinery to cloud integration



Real-Time Shop Floor Visibility

Live MES analytics and machine health



Targeted Process Control

Heat treatment, melting, and machine shop tracking



Energy & Logistics Management

Smart power, warehouse, and workforce control



Custom Embedded Engineering

Hardware and firmware from prototype to scale



Inline Quality & Traceability

Automated defect prevention and pack verification

How we deliver



Study the floor ¹

We walk your shop and read the sheets you keep by hand.



Design both halves ²

Board, firmware and screens — specified together, so the data fits.



Pilot on your data ³

A month of your own data, run beside your paperwork.



Deploy and support ⁴

Installed, your people trained, the database backed up off-site.




Think it. We build it. We wire it to the machine.

Any process you can describe becomes software here — and the boards, sensors and gateways that feed it are designed under the same roof.


Every punch counts. Every rupee tracked.

Daily, weekly, monthly — side by side.

Punches arrive from a biometric reader, a QR scan on the ID card, or a supervisor's correction. The system pairs them, works out the day, counts the overtime, applies loans and deductions, and hands you a salary sheet you can defend line by line.



How the month runs, step by step



What it looks like on the floor

Sun	Mon	Tue	Wed	Thu	Fri	Sat
Sunday 	SHIFT II Duration 12h 00m In Time 6 - 08:02 PM Out Time 7 - 08:15 AM PAY ₹665 INCENTIVE ₹100 Token Deduction ₹45 Total Deduction ₹45	SHIFT II Duration 12h 00m In Time 7 - 07:54 PM Out Time 8 - 08:07 AM PAY ₹665 Token Deduction ₹35 Total Deduction ₹35	Absent  Token Deduction ₹35 Total Deduction ₹38	SHIFT II Duration 12h 00m In Time 9 - 07:54 PM Out Time 10 - 08:50 AM OT 0.5 hrs PAY ₹706.56 Token Deduction ₹25 Custom Deduction ₹131 Total Deduction ₹156	SHIFT II Duration 12h 00m In Time 10 - 07:48 PM Out Time 11 - 07:59 AM PAY ₹665 Token Deduction ₹25 Total Deduction ₹25	SHIFT II Duration 12h 00m In Time 11 - 07:53 PM Out Time 12 - 07:52 AM PAY ₹665
12	13 Present	14 Present	15 Present	16 Present	17 Present	18 Absent
Sunday 	SHIFT II Duration 12h 00m In Time 13 - 08:08 PM Out Time 14 - 08:12 AM PAY ₹665 Token Deduction ₹45 Total Deduction ₹45	SHIFT II Duration 12h 00m In Time 14 - 07:56 PM Out Time 15 - 08:03 AM PAY ₹665	SHIFT II Duration 12h 00m In Time 15 - 07:59 PM Out Time 16 - 08:14 AM PAY ₹665	SHIFT II Duration 12h 00m In Time 16 - 08:04 PM Out Time 17 - 08:06 AM PAY ₹665	SHIFT II Duration 5h 47m In Time 17 - 08:08 PM Out Time 18 - 01:55 AM OT FULL 5 hrs PAY ₹1,163.75	Absent  Token Deduction ₹25 Total Deduction ₹25
19	20 Present	21 Half Day	22 Present	23 Present	24 Present	25 Present
Sunday 	SHIFT II Duration 12h 00m In Time 20 - 07:47 PM Out Time 21 - 08:03 AM PAY ₹665	SHIFT II Duration 6h 19m In Time 21 - 07:52 PM Out Time 22 - 02:11 AM PAY ₹332.5 INCENTIVE ₹200	SHIFT II Duration 12h 00m In Time 22 - 08:01 PM Out Time 23 - 08:08 AM PAY ₹665 INCENTIVE ₹200	SHIFT II Duration 12h 00m In Time 23 - 07:53 PM Out Time 24 - 07:59 AM PAY ₹665 Token Deduction ₹35 Total Deduction ₹35	SHIFT II Duration 12h 00m In Time 24 - 08:23 PM Out Time 25 - 08:10 AM PAY ₹665	SHIFT II Duration 12h 00m In Time 25 - 07:58 PM Out Time 26 - 08:14 AM PAY ₹665 Token Deduction ₹25 Total Deduction ₹25

The attendance calendar. Every day with its status, shift, hours and pay. Fix a punch in place; the day recalculates.

Three ways to look at **the same month**

Salary Report

Month

<

07/2026

>

Search code or name...

🔍

S.NO	EMPLOYEE	RATE	SALARY DAYS	EXTRA HRS	EARNED						DEDUCTIONS				NET AMOUNT
					BASIC	HRA	ATTN. INC.	ALLOWANCE	INCENTIVE (OT)	TOTAL	EPF	ESI	OTHER	TOTAL	
1	Employee 01 ADM-demo	₹44,000.00 MONTHLY	27	0	₹25,385	₹16,923	₹3,917	₹0	₹0	₹46,225	₹1,800	₹0	₹0	₹1,800	₹44,425
2	Employee 02 ADM-admin	₹52,000.00 MONTHLY	24	0	₹26,400	₹17,600	₹0	₹0	₹0	₹44,000	₹1,800	₹0	₹0	₹1,800	₹42,200
3	Employee 03 CTR-2019	₹550.00 DAILY	3	0.5	₹660	₹440	₹0	₹0	₹34	₹1,134	₹0	₹9	₹330	₹339	₹795
4	Employee 04 NPM-1042	₹630.00 DAILY	3	1.5	₹756	₹504	₹0	₹0	₹118	₹1,378	₹91	₹10	₹285	₹386	₹992
5	Employee 05 NPM-1043	₹595.00 DAILY	2	0	₹357	₹238	₹0	₹0	₹0	₹595	₹43	₹5	₹530	₹578	₹17
6	Employee 06 CTR-2009	₹520.00 DAILY	25	20	₹7,488	₹4,992	₹1,498	₹3,300	₹1,311	₹18,588	₹0	₹94	₹355	₹449	₹18,139
7	Employee 07 NPM-1039	₹430.00 DAILY	25	0	₹6,192	₹4,128	₹25	₹0	₹0	₹10,345	₹0	₹78	₹480	₹558	₹9,787
8	Employee 08 NPM-1041	₹430.00 DAILY	27	0	₹6,837	₹4,558	₹1,055	₹600	₹0	₹13,050	₹0	₹86	₹380	₹466	₹12,584
9	Employee 09 NPM-1040	₹430.00 DAILY	24	0	₹5,934	₹3,956	₹13	₹0	₹0	₹9,903	₹0	₹75	₹638	₹713	₹9,190

The salary sheet. Basic, HRA, overtime, incentives, EPF and ESI — per employee, per month, all three wage types.

Three ways in, **one log**

DEVICE

Biometric readers

ESSL devices push each punch as it happens, matched on device code.

PHONE

QR on the ID card


A supervisor scans the code printed on the card and saves an IN or an OUT.

DESK

Manual correction

An admin types a missed punch in — permission-gated and attributed.

What it **gives back**



Excel throughout

Salary sheet, late report, van and machine cost views



Per-role access

View, add, edit, delete, export — screen by screen



Every correction signed

Timestamped, attributed, with what it replaced

And the rest of the month

Late report drillable to the day · van cost by day and by rider · machine and man cost per machine · incentive, deduction and loan registers · slips and employee cards as PDF.

Where it fits

WHO USES IT

HR, accounts and shift supervisors

IT TALKS TO

ESSL biometric readers, printed QR ID cards, Android phones

IT REPLACES

The muster register, the OT sheet and the salary workbook

DEPLOYED

Browser-based and multi-tenant — plant network or hosted

Draw the floor. Pick the oldest bin first.

Every movement logged and attributed.

Draw your warehouse, map every part to the rack cells it is allowed to live in, and let the floor run itself. Inspected stock is binned where it belongs, picked oldest-first, and routed to the operator step by step.

6

Steps — floor design to dispatch

FIFO

Oldest stock leaves first, by inspection date

2

Rack views — 3D bay or compact grid

3

QR codes — bin, cell, slip

The floor, drawn to dispatch



Build the floor

Racks, pillars and the entrance on a grid



Map the items

Each part to the cells it may live in



Put away

Bin it, follow the route, height-checked



Pick by FIFO

Load a slip, work the plan, scan the cell



Dispatch


Confirm once for the slip; every move logged

What it looks like on the floor



The floor builder. Drop racks, pillars and the entrance onto a grid. What you draw is the map the router walks.

Start at the building, **end at the shelf**



Picking at the bay. Every bin colour-coded by state. The suggested bin arrives with its quantity already filled in.

Three codes, **one camera**

BIN

Bin type QR

Every bin carries a printable code, and with it the shelf maths.

CELL

Rack cell QR


Scanning the cell is what unlocks picking — only at the bay the plan sent you to.

SLIP

Pick slip QR

The tablet camera reads the printed slip exactly as it is. No relabelling.

What it gives back



Colour-coded by state — FIFO first, available, or holding another part.

- Stock search plant-wide**
Any part, with the bays holding it outlined where they stand
- Movement dashboards**
Active stock, fast movers, dispatch calendar, item*period
- A ledger behind every figure**
Drillable down to the slips and batches that produced it

And the rest of the warehouse

Item search across every floor · per-rack summaries by item · active-stock, activity and fast-mover dashboards · dispatch calendar and item*period matrix · Excel export throughout.

Where it fits

WHO USES IT

Stores in-charge, pickers, dispatch and QA

IT TALKS TO

Tablet cameras and printed bin, cell and slip QR codes

IT REPLACES

The bin card, the location register and the hand-written pick slip

DEPLOYED

Browser-based and multi-tenant — plant network or hosted

Meter registers in. Cost per machine out.

Priced at today's tariff.

Know what every machine costs to run — even the ones without a meter of their own. Describe a meter brand once (its registers, data types and byte order), then wire the meters the way the plant is actually wired. Every reading arrives decoded, costed at today's tariff, and on a chart. Loads with no meter are worked out by difference, so the totals still add up.

6

Steps — register map to cost

4

Chart types — pie, bar, line, table

5

Ranges — day, week, month, shift, custom

2

Trees — electrical and plant

From a register, all the way to a rupee



Describe the brand

Register address, data type and byte order, once



Add the meters

Board address and meter id; the model carries the rest



Wire the tree

The electrical topology: incomer, panels, machines



Readings arrive


The gateway posts raw frames; the reply says what to read



Build the page


Charts by parameter and meter, over any range, with cost

What it looks like on the floor



Sections, with their meters on them. The plant drawn as a tree, with a meter on each section and its live parameters underneath.

Wire it the way **the plant is wired**



A page you built yourself. Pie, bar, line and table — each chart bound to one parameter, its own meters and its own range.

Three ways a load gets counted

METERED

A meter of its own

Every parameter it reports, decoded from the brand's register map.

ROLLED UP

A section totals its children

Sections nest, so a panel or a whole shop reads as one figure.

DERIVED

A virtual meter

No device at all: the parent's total less its metered siblings.

What it gives back



- Virtual meters**
A parent's total less its metered siblings, split and shown
- Today's tariff**
Each day at that day's rate
- Mailed at shift start**
The day's chart Excels, out before anyone asks

And the rest of the plant

Live section values as each reading lands · raw frame and decoded value logged side by side · day, week, month, shift or custom range on every chart · per-role access, each role on its own page.

One chart, one parameter, on its own range.

Where it fits

WHO USES IT

Maintenance, the energy cell, plant head and accounts

IT TALKS TO

Modbus RTU and TCP energy meters, through your own gateway

IT REPLACES

The monthly meter-reading round and the hand-kept kWh sheet

DEPLOYED

Browser-based — readings polled live on the plant network

Set the recipe. The furnace keeps its own record.

Job card comes out filled in, not blank.

Set the recipe once, load the basket layer by layer, and let the furnace keep its own record. Every controller is logged for the whole cycle, every stage is stamped as it passes, and the job card your QA already uses comes out at the end filled in.

All

Controllers logged, whole cycle

6

Stages, stamped as they pass

Hourly

Readings, with no clipboard

PDF

Job card in your own format

A batch, start to signed card



Set the recipe

Solutionising and precipitation, ramp and soak



Load the basket

By layer: item, heat number, quantity, cavity



Run and watch

Every controller live, the curve drawing itself



Stages stamp


Each with the clock time and how long the last took



Take the job card

Instruction against actual, ready to be signed

What it looks like on the floor



The recipe, and what the furnace did with it. The recipe on the right, the batch running on the left, with a rail that stamps every stage.

The record writes itself

Your company name
PLANT LOCATION, INDIA

HEAT TREATMENT PROCESS JOB CARD

Report Code
QR/PP09/10

Format Rev
2 / 25.10.2025

Date
29/8/2026, 02:38 PM

Furnace — USM2-PRO-HTF02 Batch No — S0662 Process Start Date: Aug 29, 2026

Solutionising Process

Instruction		Operation	Time	Ctrl 1	Ctrl 2	Ctrl 3	Operator
Temperature	510 °c +/- 5	On Time Temp	02:38:42 PM	39 °c	38 °c	39 °c	Operator 1
Soaking Time	5 hrs +/- 5	Cut off Time Temp	08:12:29 PM	507 °c	507 °c	507 °c	Operator 1
Quench Time	3 hrs 30 mins	Set Temp Reaching	08:10 PM	08:10 PM	08:10 PM	08:10 PM	diff 16s
Water Temp (before quench)	40 °c +/- 5	Every One Hour					
Quench Delay Time	20 seconds max	1	09:11:02 PM	510 °c	510 °c	510 °c	Operator 1
Water Level (before quench)	Green / Red	2	10:10:00 PM	510 °c	510 °c	510 °c	Operator 1

Quenching Duration Started: 30/08/2026, 01:09 AM · Completed: 30/08/2026, 04:17 AM · Total 3 hrs 7 mins

Precipitation Process · 165 °c +/- 5, soak 6 hrs · six hourly rows, every controller

Checked by (Operator)

Approved by (Engineering)

Verified by (QA)

The card your QA already signs. Instruction on the left, what the furnace actually did on the right. Ready to be signed.

Three things the cycle records by itself

EVERY HOUR

The hourly reading

Every controller, on the hour, against the operator on shift.

EVERY STAGE

The stage stamp


Raising, running, quenching — each with the clock time it began.

EVERY SET POINT

The reaching time

When each controller reached temperature, and the spread between them.

What it gives back



- Weight checked as you load**
The basket totalled against the furnace's own capacity
- Your own card format**
Printed to your report code and revision, exported as PDF
- Nightly off-site backup**
The whole database zipped and sent, every night

And the rest of the shop

Every furnace on one screen, side by side · skip a process or generate the next batch id from the same card · configurations saved per client and reused · items, cavities and heat numbers held as masters.

The recipe: each set point with its ramp and its soak.

Where it fits

WHO USES IT

Furnace operators, engineering and QA

IT TALKS TO

Every controller the furnace carries, for the whole cycle

IT REPLACES

The hourly clipboard round and the blank job card

DEPLOYED

Browser-based — database zipped and sent off-site nightly

Aim the chemistry. Let the heat log itself.

Set the target mix. The rest runs itself.

Set the aim chemistry — your target mix. That is the only thing anyone types. From there the heat runs itself — the charge mix is worked out against the aim, the crane weighs every lift into its bunker, the bins are weighed back against their targets, and the spectrometer fills the sheet in. The melting log sheet your QA already signs comes out complete.

1

Thing you enter — the aim chemistry

Every

Lift weighed into its bunker, on its own

Live

Chemistry, straight from the spectrometer

PDF

Log sheet, filled in and ready to sign

Set the aim, the heat runs itself


YOU
Set the aim

Product, grade and iron type, with the chemistry to hit


AUTO CHARGE MIX
The mix is worked out

Scrap and returns costed against the aim; the matrix does the arithmetic


AUTO SPECTRUM
The chemistry reports

Every spectrometer result, element by element against the aim



AUTO ALLOY ADDITION
Additions worked out

What to add and how much, so the heat comes onto aim


AUTO LOG SHEET
The sheet fills itself

Chemistry, moulds, lost time and melt details, already on it

What it looks like on the floor



The crane view, live. Beacon position, the load on the hook, every bunker's running weight, and the lifts booking themselves into the log.

Your company name PLANT LOCATION, INDIA						MELTING LOG SHEET							Date code		G-26		Date		26-07-2026				
													Cumulative heats		38		Shift		A				
CHARGE MATERIALS (KG)						ADDITIONS (KG)							MELT DETAILS - F-02										
Heel metal	Steel scrap LMS	Steel scrap HMS / MS	Tin scrap	Borings	Fdy returns	Green coke	CP C	FeSi	FeMn	FeP	FeS	FeCr	Heat No	H-1184									
													Grade	SG 500/7									
													Start · tap · end	01:42 · 02:26 · 02:38									
450	820	610	180	240	980	42	18	26	12	4	3	9	Charging sequence	R B C S R									
Total weight	3,280	%	100			Total add.		114	%	3.5			Coin sample temp	1428 °C									
CE meter C: 4.42		CHEMICAL COMPOSITION %										Wedge	OK	Slag removed						YES			
Elements	C	Si	Mn	P	S	Cr	Ni	Mo	Al	Cu	Ti	Sn	Tapped metal weight		3,180								
													Initial · final energy		83,080 · 84,320								
Live	3.62	2.41	0.32	0.041	0.012	0.06	0.03	0.01	0.008	0.05	0.012	0.004	Total units in KVH		1,240								
Aim	3.60	2.40	0.35	0.040	0.015	0.08	0.05	0.02	0.010	0.06	0.015	0.005	KVH / ton		389								
													GLD (mA)		512								
MOULD DETAILS										FURNACE STOPPAGE & OTHER DETAILS													
Fdy code						Moulds				01:58 PM		Coil water temp high				06 min							
FD-2214						126				01:12 PM		Charge bucket delay				03 min							
FD-2219						84				12:40 PM		Electrode adjustment				02 min							
FD-2231						58																	
Total moulds						268				Total downtime this heat								11 min					
Furnace operator: Operator 1 ✓						Shift supervisor: Supervisor 1 ✓						Melting in-charge: In-charge 1 pending											

Three things the heat writes for you


Every charge material and addition, with its weight, share and cost.

Each spectrometer result lands element by element, beside the aim.

Coil water, bucket delay, electrode — each with its minutes, totalled.

Cumulative heats 38 Shift A	
MELT DETAILS · F-02	
Heat No	H-1184
Grade	SG 500/7
Start · tap · end	01:42 · 02:26 · 02:38
Charging sequence	R B C S R
Coin sample temp	1428 °C
Slag removed	YES
Tapped metal weight	3,180
Initial · final energy	83,080 · 84,320
Total units in KVH	1,240
KVH / ton	389
GLD (mA)	512

Each element's recovery, so the addition is what lands



Aims per product, customer and drawing · bunker, element and lab stock · every spectrometer result kept against its heat · planning and furnace dashboards · a 2D and a 3D view of the bay.

Browser-based — live on the melting shop network

Schedule in. Inspected pieces out.

Hour by hour on the shop floor.

Schedules arrive from your own routing and queue themselves by priority. A supervisor puts a machine, an operator and a tool on a job; the machine or the operator reports quantity; and batches form on their own. Every piece moves through the inspection route its part actually needs — so nothing reaches the next stage without being checked, and you are not walking the floor to find out what is running.

6

Steps, schedule to inspected

2

Ways to count — machine or operator

Live

OEE (overall equipment effectiveness)

Per part

Inspection route, not one fixed chain

The shop floor, schedule to inspection


1

The schedule arrives

Your routing lands in the queue, ordered by priority


2

Assign the machine

Department, machine, operator and tool in one panel


3

Count the quantity

The machine reports it, or the operator enters it


4

Batches form


Split by the slowest process, clipped to a shift


5

Gate the inspection


OK and reject by reason, by shift and operator

What it looks like on the floor



One machine, one shift, one screen. The job across the top, OK and reject against target, and the hour bars against the hour.

The console, and the route



Every dimension checked. Every part signed off.

Against the drawing, not from memory.

Register the machines, instruments and customers once, then map each product operation to a machine and a pallet slot. The operator enters the drawing's own dimensions on the JSIR sheet and anything outside tolerance turns red as it is typed. Nothing moves on until a manager signs it off — and once approved, PIR opens for periodic re-checks at the frequency you set.

2

Inspection records — JSIR and PIR

4

Machine types — CNC, PAB, PDC, lathes

100%

Machine-wise data, traceable

1

Sign-off gate before the next operation

From the drawing, to a signed part


Set up the floor

Machine types, pallets, instruments and customers, once


Build the product

Part, drawing and revision, mapped to a machine and slot


Enter the JSIR

Every dimension against its instrument; out of tolerance turns red



The manager signs

Approve or reject; nothing reaches the next operation until then


PIR keeps checking

Shift-once or two-hourly, at the frequency you set

What it looks like on the floor



One screen for the whole floor. Every registered machine live: the part and operation loaded on each pallet, when it is due off, and how far it has moved through JSIR, PIR, PDIR and PMS.

The sheet, and the sign-off

View Specifications - JSIR

Imp	Description	Instrument	Dimension	Actual Value	
☐	39	Ball Diameter	Steel Ball	1.00 +/-1.00	63
☐	39	Ball Diameter	Steel Ball	1.00 +/-1.00	8
☐	40	Depth Distance on Ball 30mm	Digital Vernier Caliper	0.36-0.36 (-0.30 / +0.06)	1
☐	40	Depth Distance on Ball 30mm	Digital Vernier Caliper	0.50-0.50 (-0.30 / +0.06)	1
☐	40	Depth Distance on Ball 30mm	Digital Vernier Caliper	0.50-0.50 (-0.30 / +0.06)	2
☐	41	Chamfer Angle at 790 / 830mm	Contour	37° ±1°	31
☐	41	Chamfer Angle at 790 / 830mm	Contour	15° ±1°	28
☐	41	Chamfer Angle at 790 / 830mm	Contour	24° ±1°	25
☐	42	Radius on 253 / 136mm	Contour	0.23 ±0.15	76
☐	42	Radius on 253 / 136mm	Contour	0.23 ±0.15	52
☐	42	Radius on 253 / 136mm	Contour	0.23 ±0.15	0.26
☐	42	Radius on 253 / 136mm	Contour	0.23 ±0.15	0.27
☐	42	Radius on 253 / 136mm	Contour	0.23 ±0.15	0.24
☐	43	Radius on R0.08 / R0.18mm	CONTOUR	0.15 R0.15 Max	0.18
☐	43	Radius on R0.08 / R0.18mm	CONTOUR	0.15 R0.15 Max	0.61

close

save

submit

The drawing, dimension by dimension. Each value against its own instrument and tolerance. Out of range turns red as it is typed — not at the end of the shift.

Three things registered once

MACHINES

Types, then units

CNC, PAB, PDC and lathes; each machine with one pallet or two.

INSTRUMENTS

With their calibration

CMM, contour, vernier and every gauge, with its next-due date.

CUSTOMERS

Entered once

Name, GST and contact, then simply picked while building a product.

What it gives back

Quality Management

Request

History

Pending JSIR - 2

Operation Name	Machine Name	Machine type	Slot	Customer	Part Name	Drawing	Status
OP1	ISC-B-MS-B9	CNC	1	M/s GNUMTI CARGO	CLAMP MACHINED	10012340/01	Waiting for Manager Confirmation
							Verify and Approve / Reject uploaded JSIR
OP2	ISC-B-MS	CNC	2	M/s GNUMTI CARGO	BIKE HEAD	10012341/03	Waiting for Manager Confirmation
							Verify and Approve / Reject uploaded JSIR

View Specifications - PIR

Description	Dimension	Actual	Checking frequency	Verify
HOLE POSITION ON ø5.00mm	0.5 ø 0.5 A/B	21	SHIFT ONCE	☐
CENTER DISTANCE ON 20.05mm	42.10 42.10 / 0.15	—	SHIFT ONCE	☐
HOLE DIAMETER	20.05 ø20.05 / 0.15	—	SHIFT ONCE	☐
PROFILE OF A SURFACE	0.03 ø 0.03	—	SHIFT ONCE	☐
HOLE DIAMETER	5.00 ±0.15	—	24HRS ONCE	☐
HOLE DEPTH ON ø5.00mm	17.00 ±0.30	—	24HRS ONCE	☐

The queue a manager clears, and the PIR schedule approval unlocks.

- A gate, not a report**
A part cannot reach the next operation until a manager has approved its sheet
- Uncalibrated tools blocked**
Every instrument carries its calibration and next-due date
- Audit-ready by default**
Every JSIR and PIR entry timestamped and attributed

And the rest of the quality room

Product list with part, drawing and revision · pallet-slot mapping per operation · JSIR and PIR spec files uploaded per product · checking frequency set per dimension · machine-wise reports across every check.

Where it fits

WHO USES IT

Operators, quality engineers and the QA manager

IT TALKS TO

CMM, contour tracers, vernier calipers and every registered gauge

IT REPLACES

The paper inspection register and the manual sign-off

DEPLOYED

Browser-based — at the machine, on the desk, or hosted

OUR PREMISES · SIDCO, KURICHI, COIMBATORE

Acceedo your way to smarter solutions.

How it starts



Send us your data

One month of punches, meter readings, a charge sheet, a furnace cycle or a schedule.



We run it

Loaded into the system, configured to your rates, recipes, routings or register maps.



You see it beside your own

Half an hour on a browser call, the output next to the paperwork you produce today.

Our clients



TALK TO US

Send us one month of your own data — punches, meter readings, a charge sheet, a furnace cycle or a schedule — and we will run it and walk you through what comes out. **Half an hour over a browser call.**

Nothing to install on your end.

📍 Plot No: 9A, Private Industrial Estate, Sidco, Kurichi, Coimbatore – 641021

✉ info@acceedo.in

☎ **+91 422-4511400** Ext: 235 · **+91 9994111214**

🌐 www.acceedo.in