



Insurance

0

[Monthly Contribution > Online Challan Form](#)

Transaction Details		* Required Fields
Transaction status:	Completed Successfully	
Employer's Code No:	5200020220001099	
Employer's Name:	O S P S TELECOM SERVICES	
Challan Period:	Nov-2019	
Challan Number :	05219141747533	
Challan Created Date	13-12-2019 14:36:38	
Challan Submitted Date	13-12-2019 14:59:49	
Amount Paid:	13075.00	
Transaction Number:	193474810951	
Print		Close

DISCLAIMER: Content owned, maintained and updated by Employee's State Insurance Corporation. Copyright © 2009, ESIC, India. All Rights Reserved. Best viewed in 1024 x 768 pixels, Designed and Developed by Wipro LTD. IP Address :



कर्मचारी भविष्य निधि संगठन
Employees' Provident Fund Organization

भविष्य निधि भवन, १४, भीकाजी कामा प्लेस, नई दिल्ली - ११००६६
Bhavishya Nidhi Bhawan, 14, Bhikaji Cama Place, New Delhi - 110066

Generated On 13/12/2019 12:51:

Payment Confirmation Receipt

TRRN No :	1201912014544
Challan Status :	Payment Confirmed
Challan Generated On :	12-DEC-2019 19:59:03
Establishment ID :	APHYD0042194000
Establishment Name :	OSPS TELECOM SERVICES PVT. LTD.
Challan Type :	Monthly Contribution Challan
Total Members :	51
Wage Month :	NOV-2019
Total Amount (Rs) :	99,403
Account-1 Amount (Rs) :	66,785
Account-2 Amount (Rs) :	1,734
Account-10 Amount (Rs) :	28,891
Account-21 Amount (Rs) :	1,993
Account-22 Amount (Rs) :	0
Payment Confirmation Bank :	HDFC Bank
CRN :	240131219004970
Payment Date :	13-DEC-2019
Payment Confirmation Date :	13-DEC-2019
Total PMRKY Benefit :	0



From: M Sangameshwar [M.Sangameshwar@INDUSTOWERS.COM]
Sent: Friday, December 13, 2019 5:16 PM
To: Masthan Shaik
Cc: B.V.L.N Murthy; 'Azeem PM'; Shiva M; Mohd Abdul Majeed
Subject: RE: E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_ Upgradation (RFI pending from 3 months)

Masthan,

Clear the site Glands will be closed within a week time.

Thanks & Regards

SANGAMESHWAR.M



Indus Towers Limited
Survey No. 133, 4-51
8th Floor, SLN Terminus
Beside Botanical Gardens
Gachibowli
Hyderabad - 500 032
Telangana
www.industowers.com

we transform lives by enabling communication

E mail :m.sangameshwar@industowers.com
Mobile : +91-900-0257-456.

From: MAJEEED <majeed@ospsindia.com>
Sent: Friday, 13 December, 2019 13:20
To: M Sangameshwar <M.Sangameshwar@INDUSTOWERS.COM>
Cc: B.V.L.N Murthy <B.V.L.N.Murthy@INDUSTOWERS.COM>; Masthan Shaik <AMASTHAN.SHAIK@INDUSTOWERS.COM>; 'Azeem PM' <azeem@ospsindia.com>; Shiva M <shiva@ospsindia.com>
Subject: RE: E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_ Upgradation (RFI pending from 3 months)

Dear Sir,

As dicussed earlier , pls consider the below 3 points as per the clarification given and cleare the site.

Pls treat it urgent and clear or advice further.

A.Majeed

From: Masthan Shaik [mailto:A-MASTHAN.SHAIK@INDUSTOWERS.COM]

Sent: 27 November 2019 19:10

To: 'Azeem PM'

Cc: B.V.L.N Murthy; Mohd Abdul Majeed; M Sangameshwar; Venkataraao Pakkela; 'Shiva Kumar'; 'Ibrahim Faisal'; Madhusudana Rao; Bodla Santosh; Raghunath G A; S G Prasad

Subject: RE: E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_Upgradation (RFI pending from 3 months)

Dear team

Please find the audit status is NA

Audit month	Category	Stage	Audit/ Re-audit	Ref.no/ Lot No	IndusID	Site Name	District	Guest Opc Name	Guest Opc ID	Network	Tower Type	TSP
16-Nov-19	UPG	E1	Re-audit 1	R/RL-3484357	IN-1312538	Srinagar Colony	Prakasham	Idea	PMMKPR14	2G	GBT	osps Telecom Services Pvt Ltd



Thanks&Regards
Shaik Masthan

Mobile no: 9110359936

From: Majeed <majeed@ospsindia.com>

Sent: Wednesday, 27 November, 2019 11:57 AM

To: M Sangameshwar <M.Sangameshwar@INDUSTOWERS.COM>; Masthan Shaik <A-MASTHAN.SHAIK@INDUSTOWERS.COM>

Cc: B.V.L.N Murthy <B.V.L.N.Murthy@INDUSTOWERS.COM>; 'Azeem PM' <azeem@ospsindia.com>; Venkatarao Pakkela <venkatarao.pakkela@INDUSTOWERS.COM>; 'Shiva Kumar' <shiva@ospsindia.com>; 'Ibrahim Faisal' <faisal@ospsindia.com>; Madhusudana Rao <madhusudana@ospsindia.com>

Subject: Re: E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_Upgradation (RFI pending from 3 months)

Importance: High

Sangam Sir,

As discussed on phone, QA engn re visited completed as instructed.

Pls RFI in ISQ to create WCC and get payments.

Thanks

A.Majeed

From: Madhusudana Rao

Sent: Friday, November 15, 2019 4:45 PM

To: 'M Sangameshwar' ; 'Masthan Shaik'

Cc: 'Mohd Abdul Majeed' ; 'Sitaram B' ; 'Bodla Santosh' ; 'Raghunath G A' ; 'S G Prasad' ; 'B.V.L.N Murthy' ; 'Azeem PM' ; 'Venkatarao Pakkela' ; 'Shiva Kumar' ; 'Ibrahim Faisal'

Subject: RE: E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_Upgradation (RFI pending from 3 months)

Dear Sir,

Please find the signed layout & Rectified snaps .Kindly arrange auditor on tomorrow i.e 16-11-2019 for same site.

Project type	Technology	Customer	Site ID	ID	Req ref	SITE NAME	DIST	Major/Mi
Regular-OFC	RWDM	IDEA	PMMKPR14	IN-1312538	R/RL-3484357	Markapuram	Prakasam	Major

Thanks & Regards

Madhusudana Rao

OSPS TELECOM SERVICES PVT LTD

F-1, 4th Floor, Hyderabad Business Center

Hyderabad, Hyderabad- 500029

Mobile : +91 99 89 66 86 84

Tel:+91 040-66832324 Tel:+91 040- 23296123;

Fax No:+91 040-66832325

Website : www.ospsindia.com

From: S G Prasad [<mailto:s.prasad@INDUSTOWERS.COM>]
Sent: 06 November 2019 17:18
To: B.V.L.N Murthy
Cc: Mohd Abdul Majeed; M Sangameshwar; Madhusudana Rao; Sitaram B; Bodla Santosh; Raghunath G A; 'Azeem PM'
Subject: RE: E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_Upgradation (RFI pending from 3 months)

Sir,

I find attached signed foundation drawing for subjected idea BSC Markapur site.

Regards
Prasad

From: B.V.L.N Murthy <B.V.L.N.Murthy@INDUSTOWERS.COM>
Sent: Tuesday, 05 November, 2019 14:37
To: S G Prasad <s.prasad@INDUSTOWERS.COM>
Cc: Mohd Abdul Majeed <majeed@ospsindia.com>; M Sangameshwar <M.Sangameshwar@INDUSTOWERS.COM>;
Madhusudana Rao <madhusudana@ospsindia.com>; Sitaram B <Sita.Ram@INDUSTOWERS.COM>; Bodla Santosh
<Bodla.Kumar@INDUSTOWERS.COM>; Raghunath G A <Raghunath.ga@industowers.com>; 'Azeem PM'
<azeem@ospsindia.com>
Subject: RE: E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_Upgradation (RFI pending from 3 months)

Prasad,

As discussed, pls. verify and attest the layout

Thanks & Regards,

B.V.L.N.Murthy
Head - Quality
Mobile : 9949011075



Indus Towers Limited
Survey No. 133, 4-51
8th Floor, SLN Terminus
Beside Botanical Gardens
Gachibowli
Hyderabad - 500 032
Telangana
www.industowers.com

we transform lives by enabling communication

From: Madhusudana Rao <madhusudana@ospsindia.com>
Sent: Tuesday, 05 November, 2019 10:54
To: B.V.L.N Murthy <B.V.L.N.Murthy@INDUSTOWERS.COM>
Cc: Mohd Abdul Majeed <majeed@ospsindia.com>; M Sangameshwar <M.Sangameshwar@INDUSTOWERS.COM>; S G
Prasad <s.prasad@INDUSTOWERS.COM>; Sitaram B <Sita.Ram@INDUSTOWERS.COM>; Bodla Santosh
<Bodla.Kumar@INDUSTOWERS.COM>; Raghunath G A <Raghunath.ga@industowers.com>; 'Azeem PM'
<azeem@ospsindia.com>

Subject: FW: E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_Upgradation (RFI pending from 3 months)

Dear Sir,

Please find the attached approved layout. Arrange auditor for tomorrow to the same site without fail.

Thanks & Regards

Madhusudana Rao

OSPS TELECOM SERVICES PVT LTD

F-1, 4th Floor, Hyderabad Business Center

Hyderabad, Hyderabad- 500029

Mobile : +91 99 89 66 86 84

Tel:+91 040-66832324**Tel:+91** 040- 23296123;

Fax No:+91 040-66832325

Website : www.ospsindia.com

From: Madhusudana Rao [<mailto:madhusudana@ospsindia.com>]

Sent: 01 November 2019 15:29

To: 'S G Prasad'; 'M Sangameshwar'

Cc: 'Raghunath G A'; 'Bodla Santosh'; 'Venkatarao Pakkela'; 'Masthan Shaik'; 'Azeem PM'; 'Shiva Kumar'; 'Ibrahim Faisal'; 'B.V.L.N Murthy'; 'Mohd Abdul Majeed'; 'Surya Murthy'

Subject: RE: E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_Upgradation (RFI pending from 3 months)

Dear Sir,

As per Checklists QA team asking 2 Runs of I/P & O/P Power cables.

Checklists attached for your reference.

Please approve & Do the needful.

Note :- These checklist is for Extreme project only.

Thanks & Regards

Madhusudana Rao

OSPS TELECOM SERVICES PVT LTD

F-1, 4th Floor, Hyderabad Business Center

Hyderabad, Hyderabad- 500029

Mobile : +91 99 89 66 86 84

Tel:+91 040-66832324**Tel:+91** 040- 23296123;

Fax No:+91 040-66832325

Website : www.ospsindia.com

From: S G Prasad [<mailto:s.prasad@INDUSTOWERS.COM>]

Sent: 01 November 2019 12:17

To: Madhusudana Rao; M Sangameshwar

Cc: Raghunath G A; Bodla Santosh; Venkatarao Pakkela; Masthan Shaik; 'Azeem PM'; 'Shiva Kumar'; 'Ibrahim Faisal'; B.V.L.N Murthy; Mohd Abdul Majeed
Subject: RE: E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_Upgradation (RFI pending from 3 months)

Dear team,

Why we need to require two rows of 95sq.mm cable ? Any guidelines are available for strategic /BSC sites . Please confirm and share the documents .

Regards
Prasad

From: Madhusudana Rao <madhusudana@ospsindia.com>
Sent: Friday, 01 November, 2019 11:19
To: S G Prasad <s.prasad@INDUSTOWERS.COM>
Cc: Bodla Santosh <Bodla.Kumar@INDUSTOWERS.COM>; Venkatarao Pakkela <venkatarao.pakkela@INDUSTOWERS.COM>; Masthan Shaik <A-MASTHAN.SHAIK@INDUSTOWERS.COM>; 'Azeem PM' <azeem@ospsindia.com>; 'Shiva Kumar' <shiva@ospsindia.com>; 'Ibrahim Faisal' <faisal@ospsindia.com>; Raghunath G A <Raghunath.ga@industowers.com>; B.V.L.N Murthy <B.V.L.N.Murthy@INDUSTOWERS.COM>; Mohd Abdul Majeed <majeed@ospsindia.com>; M Sangameshwar <M.Sangameshwar@INDUSTOWERS.COM>
Subject: RE: E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_Upgradation (RFI pending from 3 months)

Dear Sir,

Please approve the same as it is Markapuram IDEA BSC Site. These specification we are using in Extreme sites.

1. As per guidelines servo I/P cables request 2 runs of 95sq.mm/4C but installed 1 run.
2. As per guidelines servo O/P cables request 2 runs of 95sq.mm/4C but installed 1 run.

Thanks & Regards
Madhusudana Rao

OSPS TELECOM SERVICES PVT LTD
F-1, 4th Floor, Hyderabad Business Center
Hyderabad, Hyderabad- 500029
Mobile : +91 99 89 66 86 84
Tel:+91 040-66832324Tel:+91 040- 23296123;
Fax No:+91 040-66832325
Website : www.ospsindia.com

From: M Sangameshwar [<mailto:M.Sangameshwar@INDUSTOWERS.COM>]
Sent: 31 October 2019 14:58
To: S G Prasad
Cc: Bodla Santosh; Venkatarao Pakkela; Masthan Shaik; 'Azeem PM'; 'Shiva Kumar'; 'Ibrahim Faisal'; Raghunath G A; Madhusudana Rao; B.V.L.N Murthy

Subject: RE: E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_Upgradation (RFI pending from 3 months)

Dear Prasad,

Please check and confirm below points required for Idea BSC where Stabilizer 82.5KVA installed at site.

1. As per guidelines servo I/P cables request 2 runs of 95sq.mm/4C but installed 1 run.
2. As per guidelines servo O/P cables request 2 runs of 95sq.mm/4C but installed 1 run.

Thanks & Regards

SANGAMESHWAR.M



Indus Towers Limited
Survey No. 133, 4-51
8th Floor, SLN Terminus
Beside Botanical Gardens
Gachibowli
Hyderabad - 500 032
Telangana
www.industowers.com

we transform lives by enabling communication

E mail :m.sangameshwar@industowers.com
Mobile : +91-900-0257-456.

From: Madhusudana Rao <madhusudana@ospsindia.com>
Sent: Wednesday, 30 October, 2019 12:18
To: B.V.L.N Murthy <B.V.L.N.Murthy@INDUSTOWERS.COM>
Cc: Bodla Santosh <Bodla.Kumar@INDUSTOWERS.COM>; Venkatarao Pakkela <venkatarao.pakkela@INDUSTOWERS.COM>; Masthan Shaik <A-MASTHAN.SHAIK@INDUSTOWERS.COM>; 'Azeem PM' <azeem@ospsindia.com>; 'Shiva Kumar' <shiva@ospsindia.com>; 'Ibrahim Faisal' <faisal@ospsindia.com>; M Sangameshwar <M.Sangameshwar@INDUSTOWERS.COM>; Raghunath G A <Raghunath.ga@industowers.com>
Subject: FW: E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_Upgradation (RFI pending from 3 months)

Dear Sir,

Please find the remarks for the punch points.

Consider the same & requesting you to provide Signed JMS to claim.

Stabilizer points:

1. Cable of armouring should be earthed but not available.(Extreme Specification, Checklist also received after complete the all work)

2. As per guidelines servo I/P cables request 2 runs of 95sq.mm/4C but installed 1 run. .(Extreme Specification, Checklist also received after complete the all work)
3. As per guidelines servo O/P cables request 2 runs of 95sq.mm/4C but installed 1 run. .(Extreme Specification, Checklist also received after complete the all work)
4. as per guidelines, heat shrink tube required on cables lugs but pvc tape used. .(Extreme Specification, Checklist also received after complete the all work)
5. As per guidelines, Servo stabilizer all around 1 Mtrs space is requested but no available. .(Extreme Specification, Checklist also received after complete the all work)

ACDB points:

6. hole saw cutter not used for gland hole in MCCB enclosure(Rectified)

7. Shelter also properly not cutted for cable entries(Rectified)

DG points

8. DG-1 & DG-2 upg cable 95*4c alarm cable gland not provided(DG plate hole not matching with Cable gland size)
9. Both DG controller side door opening issue(space issue)
10. DG-1 access properly not available(Space issue)

AMF Pannel points:

11. Door alarm not working connected from shelter-1&shalter-2(Rectified)
12. walking way properly not available to AMF panel(Space issue)
13. Flexible pipes are unsafe when walk way used to AMF panel(Space issue)

Thanks & Regards

Madhusudana Rao

OSPS TELECOM SERVICES PVT LTD

F-1, 4th Floor, Hyderabad Business Center

Hyderabad, Hyderabad- 500029

Mobile : +91 99 89 66 86 84

Tel:+91 040-66832324**Tel:+91 040- 23296123;**

Fax No:+91 040-66832325

Website : www.ospsindia.com

From: B.V.L.N Murthy [<mailto:B.V.L.N.Murthy@INDUSTOWERS.COM>]

Sent: 29 October 2019 14:53

To: Mohd Abdul Majeed

Cc: Bodla Santosh; 'Madhusudana Rao'; Venkatarao Pakkela; Masthan Shaik; Azeem PM; Shiva M; Raghunath G A; M Sangameshwar

Subject: RE: E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_Upgradation (RFI pending from 3 months)

Majeed Sir,

During discussion, it was suggested to give your comment for review and revert.,

Stabilizer points:

1. Cable of armouring should be earthed but not available.
2. As per guidelines servo I/P cables request 2 runs of 95sq.mm/4C but installed 1 run.
3. As per guidelines servo O/P cables request 2 runs of 95sq.mm/4C but installed 1 run.
4. as per guidelines, heat shrink tube required on cables lugs but pvc tape used.

5. As per guidelines, Servo stabilizer all around 1 Mtrs space is requested but no available.

ACDB points:

6. hole saw cutter not used for gland hole in MCCB enclosure
7. Shelter also properly not cutted for cable entries

DG points

8. DG-1 & DG-2 upg cable 95*4c al.arm cable gland not provided
9. Both DG controller side door opening issue(space issue)
10. DG-1 access properly not available

AMF Pannel points:

11. Door alarm not working connected from shelter-1&shalter-2
12. walking way properly not available to AMF panel
13. Flexible pipes are unsafe when walk way used to AMF panel(will broke)

Thanks & Regards,

B.V.L.N.Murthy

Head - Quality

Mobile : 9949011075



Indus Towers Limited
Survey No. 133, 4-51
8th Floor, SLN Terminus
Beside Botanical Gardens
Gachibowli
Hyderabad - 500 032
Telangana
www.industowers.com

we transform lives by enabling communication

From: Majeed <majeed@ospsindia.com>

Sent: Tuesday, 29 October, 2019 11:32

To: M Sangameshwar <M.Sangameshwar@INDUSTOWERS.COM>

Cc: B.V.L.N Murthy <B.V.L.N.Murthy@INDUSTOWERS.COM>; Bodla Santosh <Bodla.Kumar@INDUSTOWERS.COM>; 'Madhusudana Rao' <madhusudana@ospsindia.com>; Venkataraao Pakkela <venkataraao.pakkela@INDUSTOWERS.COM>; Masthan Shaik <A-MASTHAN.SHAIK@INDUSTOWERS.COM>; Azeem PM <azeem@ospsindia.com>; Shiva M <shiva@ospsindia.com>; Raghunath G A <Raghunath.ga@industowers.com>

Subject: E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_Upgradation (RFI pending from 3 months)

Importance: High

Dear Sir,

As discussed yesterday with you & Murthy Sir along with planning team, pls go through the below points and share final conclusion.

OSPS points has been rectified.

We request you to consider the above & provide RFI points as its pending from 3 months.

Thanks

A.Majeed

From: Masthan Shaik

Sent: Thursday, August 1, 2019 6:12 PM

To: Azeem


Cc: M Sangameshwar ; B.V.L.N Murthy ; Bodla Santosh ; 'Madhusudana Rao' ; Siva Velisala ; Venkatarao Pakkela ; Mohd Abdul Majeed ; Rakesh B ; ospsnaresh@gmail.com

Subject: RE: AT Request / OSPS / Upgradation / E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_Upgradation

Dear team,

Please find the audit status is NA,

Audit month	Category	Stage	Audit/ Re-audit	Ref.no/ Lot No	Indus ID	Site Name	District	Guest Opco Name	Guest Opco ID	Network	Tower Type	TSP
29-Jul-19	UPG	P1	Re-audit	R/RL-3484357	IN-1312538	Markapuram	Prakasam	IDEA	PMMKPR14	2G	GBT	osps Telecom Services



Thanks & Regards
Shaik. Masthan
Mob no; 9110359936

From: M Sangameshwar
Sent: Thursday, 01 August, 2019 17:53
To: Masthan Shaik <A-MASTHAN.SHAIK@INDUSTOWERS.COM>
Subject: Fw: AT Request / OSPS / Upgradation / E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_Upgradation

From: Azeem <azeem@opsindia.com>
Sent: 24 July 2019 20:49
To: M Sangameshwar <M.Sangameshwar@INDUSTOWERS.COM>
Cc: B.V.L.N Murthy <B.V.L.N.Murthy@INDUSTOWERS.COM>; Bodla Santosh <Bodla.Kumar@INDUSTOWERS.COM>;

'Madhusudana Rao' <madhusudana@ospsindia.com>; Siva Velisala <siva.velisala@INDUSTOWERS.COM>; Venkataraao Pakkela <venkataraao.pakkela@INDUSTOWERS.COM>; Mohd Abdul Majeed <majeed@ospsindia.com>; Rakesh B <a-rakesh.b@INDUSTOWERS.COM>; ospsnaresh@gmail.com <ospsnaresh@gmail.com>

Subject: RE: AT Request / OSPS / Upgradation / E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_Upgradation

Dear sir,

Pls. plan engineer for Re-Audit...

Thanks & Regards

M.A.Azeem

Project Manager

OSPS TELECOM SERVICES PVT LTD

Mobile +91 9000468806

From: M Sangameshwar [<mailto:M.Sangameshwar@INDUSTOWERS.COM>]

Sent: Tuesday, July 23, 2019 12:20 PM

To: Madhusudana Rao; Siva Velisala

Cc: B.V.L.N Murthy; Bodla Santosh; Venkataraao Pakkela; Mohd Abdul Majeed; azeem@ospsindia.com; Rakesh B; ospsnaresh@gmail.com

Subject: Re: AT Request / OSPS / Upgradation / E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_Upgradation

Dear team,

Please offer for Revisit

Get [Outlook for Android](#)

From: Madhusudana Rao <madhusudana@ospsindia.com>

Sent: Tuesday, July 23, 2019 11:52:34 AM

To: Siva Velisala <siva.velisala@INDUSTOWERS.COM>

Cc: M Sangameshwar <M.Sangameshwar@INDUSTOWERS.COM>; B.V.L.N Murthy <B.V.L.N.Murthy@INDUSTOWERS.COM>; Bodla Santosh <Bodla.Kumar@INDUSTOWERS.COM>; Venkataraao Pakkela <venkataraao.pakkela@INDUSTOWERS.COM>; Mohd Abdul Majeed <majeed@ospsindia.com>; azeem@ospsindia.com <azeem@ospsindia.com>; Rakesh B <a-rakesh.b@INDUSTOWERS.COM>; ospsnaresh@gmail.com <ospsnaresh@gmail.com>

Subject: RE: AT Request / OSPS / Upgradation / E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_Upgradation

Dear Sir,

Please find the attached rectified snaps & remarks for punch points. Kindly clear the site & Do the needful for RFAI.

Upgradation points:-

Stabilizer points:

1. Servo stabilizer display not working & LED indication not working. ([Rectified, Refer attached snaps](#))
2. Cable of armouring should be earthed but not available. ([Not possible as already armouring cut & lugs fixed](#))
3. As per guidelines servo I/P cables request 2 runs of 95sq.mm/4C but installed 1 run. ([It is Airtel Extreme project guide line](#))

4. As per guidelines servo O/P cables request 2 runs of 95sq.mm/4C but installed 1 run. (It is Airtel Extreme project guide line)
 5. as per guidelines, heat shrink tube required on cables lugs but used insulated tape. (It is only for Extreme project)
 6. As per guidelines, Servo stabilizer all around 1 Mtrs space is requested but no available. (Due to space constraint)

ACDB points:

7. Gland cutter not used for gland hole in MCCB enclosure (Rectified, Refer photos)
 8. In 200A MCCB, Breaking capacity not available (Breaking capacity available, Pls refer snaps)
 9. Shelter also properly not cutted for cable entries (Refer photos)

DG points

10. DG-1 & DG-2 upg cable 95*4c al.arm cable gland not provided (Rubber available)
 11. Both DG controller side door opening issue(space issue) (Due to space constraint)
 12. DG-1 access properly not available (Due to space constraint)

AMF pannel points:

13. Door alarm not working connected from shelter-1&shalter-2 (Rectified, refer attached snaps)
 14. walking way properly not availble to AMF panel (Due to space constraint)
 15. Flexible pipes are unsafe when walk way used to AMF panel(will broke) (Due to space constraint ,Suggestion require)

EB Meter points:

16. EB meter door glass not available (Rectified snaps attached)
 17. On MCCB 200A breaking capacity not available (Breaking capacity available, Pls refer snaps)

RFAI points

1. EB upgradation required from 29kw to 60kw 3ph (Madan sir will discuss with Planning team for mail)
 2. Service cable 50sqmm need to change 95sqmm al.arm cable (Transformer to EB not under TSP scope)
 3. In existing SMPS CH-3 , 80A mcb not available shelter-1 (Existing SMPS O&M using in other channel)
 4. In existing SMPS CH-3 , 80A and 32A mcb not available shelter (Existing SMPS O&M using in other channel)

Thanks & Regards

Madhusudana Rao
 OSPS-9989668684

From: Masthan Shaik [<mailto:A-MASTHAN.SHAIK@INDUSTOWERS.COM>]

Sent: Monday, July 15, 2019 12:48 PM

To: azeem@ospindia.com

Cc: M Sangameshwar; B.V.L.N Murthy; Balaji S; Bodla Santosh; Venkataraao Pakkela; Siva Velisala; Mohd Abdul Majeed; ospazeem@gmail.com; 'Madhusudana Rao'; ospnaresh@gmail.com; Rakesh B

Subject: RE: AT Request / OSPS / Upgradation / E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_Uupgradeation

Dear team

Please find the audit status is NA

Audit month	Category	Stage	Audit/ Re-audit	Ref.no/ Lot No	Indus ID	Site Name	District	Guest Opco Name	Guest Opco ID	Network	Tower Type	TSP
11-Jul-19	UPG	P1	audit	R/RL-3484357	IN-1312538	Markapuram	Prakasam	IDEA	PMMKPR14	2G	GBT	osp Telecom Services Pvt Ltd

Thanks & Regards
Shaik. Masthan
Mob no; 9110359936

From: Azeem [<mailto:azeem@ospsindia.com>]
Sent: Monday, 15 July, 2019 10:23
To: Masthan Shaik <A-MASTHAN.SHAIK@INDUSTOWERS.COM>; Balaji S <a-balaji.s2@INDUSTOWERS.COM>
Cc: M Sangameshwar <M.Sangameshwar@INDUSTOWERS.COM>; B.V.L.N Murthy <B.V.L.N.Murthy@INDUSTOWERS.COM>; Bodla Santosh <Bodla.Kumar@INDUSTOWERS.COM>; Venkataraao Pakkela <venkataraao.pakkela@INDUSTOWERS.COM>; Siva Velisala <siva.velisala@INDUSTOWERS.COM>; Mohd Abdul Majeed <majeed@ospsindia.com>; ospazeem@gmail.com; 'Madhusudana Rao' <madhusudana@ospsindia.com>; ospnaresh@gmail.com; Rakesh B <a-rakesh.b@INDUSTOWERS.COM>
Subject: RE: AT Request / OSPS / Upgradation / E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_Upgradation

Dear Mr. Masthan,

Pls. share audit status...

Thanks & Regards
M.A.Azeem
Project Manager
OSPS TELECOM SERVICES PVT LTD
Mobile +91 9000468806

From: Masthan Shaik [<mailto:A-MASTHAN.SHAIK@INDUSTOWERS.COM>]
Sent: Tuesday, July 09, 2019 6:47 PM
To: Balaji S
Cc: M Sangameshwar; B.V.L.N Murthy; Bodla Santosh; azeem@ospsindia.com; Venkataraao Pakkela; Siva Velisala; Mohd Abdul Majeed; ospazeem@gmail.com; 'Madhusudana Rao'; ospnaresh@gmail.com; Rakesh B
Subject: RE: AT Request / OSPS / Upgradation / E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_Upgradation

Balaji

Find the details and complete the audit

Thanks & Regards

Shaik. Masthan

Mob no; 9110359936

From: Azeem [<mailto:azeem@ospsindia.com>]

Sent: Tuesday, 09 July, 2019 17:43

To: Masthan Shaik <A-MASTHAN.SHAIK@INDUSTOWERS.COM>

Cc: M Sangameshwar <M.Sangameshwar@INDUSTOWERS.COM>; B.V.L.N Murthy <B.V.L.N.Murthy@INDUSTOWERS.COM>; Bodla Santosh <Bodla.Kumar@INDUSTOWERS.COM>; Venkataraao Pakkela <venkataraao.pakkela@INDUSTOWERS.COM>; Siva Velisala <siva.velisala@INDUSTOWERS.COM>; Mohd Abdul Majeed <majeed@ospsindia.com>; ospazeem@gmail.com; 'Madhusudana Rao' <madhusudana@ospsindia.com>; ospnaresh@gmail.com; Rakesh B <a-rakesh.b@INDUSTOWERS.COM>

Subject: AT Request / OSPS / Upgradation / E1/- inspection IN-1312538-R/RL-3484357-PMMKPR14-Markapuram - Idea_Upgradation

Dear Sir,

Pls. arrange engineer for E1 inspection at below site Tomorrow Contact Details – Naresh- 9966079390

Project type	Technology	Customer	Site ID	ID	Req ref	SITE NAME	DIST	Major/Mi
Regular-OFC	RWDM	IDEA	PMMKPR14	IN-1312538	R/RL-3484357	Markapuram	Prakasam	Major

Thanks & Regards

M.A.Azeem

Project Manager

OSPS TELECOM SERVICES PVT LTD

Mobile +91 9000468806

Indus Towers Limited

ATL - AP Telangana Warehouse

Survey No. 25 E,Banda Mylaram,Mulugu Mandal,Hyderabad,502336,Telangana


Tax Invoice

Original for Recipient

Source	Destination	Project Details
<p>Document No. : 11110048078 Department : Technology BOQ Req. No. : 11150087828 Internal IR : 11040126502 Internal SO : 31200049238 Consignor : Indus Towers Limited Site ID : ATL - AP Telangana Warehouse Site Name : ATL - AP Telangana Warehouse Site Address : Survey No. 25 E,Banda Mylaram,Mulugu Mandal,Hyderabad,502336,Telangana</p>	<p>Document Date : 21-JUN-2019 Internal IR Date : 21-JUN-2019 Internal ISO Date : 21-JUN-2019 Consignee : Indus Towers Limited Site ID : IN-1312538 Site Name : Site Address : Sy.No. 416 situated at Markapuram Village and Municipality, Prakasam District,Sy.No. 416 situated at Markapuram Village and Municipality, Prakasam District,Prakasham,MARK APURAM,523105,Andhra Pradesh</p>	<p>Project No. : R/RL-3484357 Move order No : 1598814 GE/GO Date : Transporter Name : TSP-OSPS Vehicle No : AP25W5902 LR No : 2109 GO/GE No : ST Form No. : M/s. INDUS TOWERS LTD Contact Person : C/o. FM India Supply Chain PVT. LTD Way bill No : 3514 Gate Entry No. : 8078 NGRP No. : No. of Pkgs. : 3 Veh. No. : AP25W5902 Date : 26/6/18</p>

GSTIN No of Consignor	36AABC17776B1ZJ	GSTIN No of Consignee	37AABC17776B1ZH	Remarks	Signature/Security Inch)					
S.No.	Item Code	Item Description	UOM	Qty.	Lot No.	Serial No.	FA. No.	MFG. No.	Tax Rate	Amount
2	11-422420-0-01-15-ZZ-000 HSN: 8537 SAC :	AMF, 82.5 KVA, 3 Phase, Dual DG, Outdoor, Make-intelux, Version 1.0	Each	1		19060005			AP - Telangana IGST -18%	Amt: 81237 Tax amt : 14622.66 Total: 95859.66
3	11-422420-0-01-15-ZZ-000 HSN: 8537 SAC :	AMF, 82.5 KVA, 3 Phase, Dual DG, Outdoor, Make-intelux, Version 1.0	Each	1		19060004			AP - Telangana IGST -18%	Amt: 81237 Tax amt : 14622.66 Total: 95859.66
1	11-51L410-0-02-01-ZZ-000 HSN: 8502 SAC :	Diesel Generator, 82.5 KVA, AC 3 phase Water Cooled, without AMF Panel with Silent Canopy, Make-MAHINDRA, Version 2.0	Each	1		10000434885			AP - Telangana IGST -18%	Amt: 482134 Tax amt : 86784.82 Total: 568918.82

Material Received in Good Condition
 Without Shortage / Damage
 Received Signature



No. 500
Mylaram
Survey No. 25 E, Banda Mylaram, Mulugu Mandal, Hyderabad, 502336, Telangana

Indus Towers Limited
ATL - AP Telangana Warehouse

Survey No. 25 E, Banda Mylaram, Mulugu Mandal, Hyderabad, 502336, Telangana

Tax Invoice

Original for Recipient

Source	Destination					Project Details		
	Document Date	Internal IR Date	Internal ISO Date	Consignee	Site ID	Project No.	Move Order No	GECO Date
Agent No. : 11110047151	Technology	29-MAY-2019	29-MAY-2019	Indus Towers Limited	IN-1312538	RRL-3484557	1561497	
Department : Internal IR	11150088073	11040123997	31200047707	Indus Towers Limited	Sy.No. 416 situated at	GEICO Date		TSP-OSPS
BOQ Req. No. : Internal SO	ATL - AP Telangana Warehouse	Survey No. 25 E, Banda Mylaram, Mulugu Mandal, Hyderabad, 502336, Telangana	Site Address	Malkapuram Village and Municipality, Prakasam District, Sy.No. 416 situated at Malkapuram Village and Municipality, Prakasam District, Prakasam, MARK DISTRICT, APURAM, 523105, Andhra Pradesh	ST Form No.	Vehicle No	AP29UB8918	OUTWARD STAMP
Consignor Site ID : Site Name	ATL - AP Telangana Warehouse	Site Address	Site Name	Site Address	Contact Person	LR No	50	INDUS TOWERS LTD.
Site Address : Site Name	Survey No. 25 E, Banda Mylaram, Mulugu Mandal, Hyderabad, 502336, Telangana	Site Address	Site Name	Site Address	Project No.	GO/GE No.		JLS. FM India Supply Chain PVT.LTD.
					Way bill No.	Gate Entry No.	2290	30/05/19
						No. of Pkgs.	715	70.5.5
						Value	No. AP29UB8918	14.50

GSTIN No of Consignor : 36AABCJ7776B1ZJ GSTIN No of Consignee : 37AABCJ7776B1ZH Remarks :
Exempted (Security Incl) : *✓*

GSTIN No of Consignor : 36AABCJ7776B1ZJ GSTIN No of Consignee : 37AABCJ7776B1ZH Remarks :
Exempted (Security Incl) : *✓*

S.No.	Item Code	Item Description	UOM	Qty.	Lot No.	Serial No.	F.A. No.	MFG. No.	Tax Rate	Amount
3	11-B32000-0-01-01-ZZ-000	Stabilizer, 82.5 KVA, 3 Phase, Make- Selvon, Version 1.0	Each	1		FXNS82.5/9050196			AP - Telangana IGST -18%	Amt : 194500 Tax amt : 35010 Total : 229510
4	11-894900-0-02-06-ZZ-0000	Battery Bank, VRLA+ 48V 600 Ah, Make- AMARA RAJA, Version 2.0	Each	1		40013601250			AP - Telangana IGST -28%	Amt : 143840 Tax amt : 40275.2 Total : 184115.2
5	HSN: 8507	SAC :							AP - Telangana IGST -28%	Amt : 143840 Tax amt : 40275.2 Total : 184115.2
	11-894900-0-02-06-ZZ-0000	Battery Bank, VRLA+ 48V 600 Ah, Make- AMARA RAJA, Version 2.0	Each	1		40013601475			AP - Telangana IGST -28%	Amt : 143840 Tax amt : 40275.2 Total : 184115.2
	HSN: 8507	SAC :								

Value : RS. 482180



Indus Towers Limited
ATL - AP Telangana Warehouse

Survey No. 25 E,Banda Mylaram,Mulugu Mandal,Hyderabad,502336,Telangana

Tax Invoice

Original for Recipient

Source		Destination		Project Details	
Document No.	: 11110047160	Document Date	: 29-MAY-2019	Project No.	: RRI-3484357
Department	: Technology	Internal IR Date	: 29-MAY-2019	Move order No	: 1561834
BOQ Req. No.	: 11150088272	Internal ISO Date	: 29-MAY-2019	GE/GO Date	:
Internal IR	: 11040124007	Consignee	: Indus Towers Limited	Transporter Name	: OSPS TELECOM SERVICES PVT LTD
Internal SO	: 31200047717	Site ID	: IN-1312538	Vehicle No	: AP29UB8918
Consignor	: Indus Towers Limited	Site Name	: Sy.No. 416 situated at Markapuram Village and Municipality, Prakasam District,Sy.No. 416 situated at Markapuram Village and Municipality, Prakasam District,Prakasham,MARK APURAM,523105,Andhra Pradesh	LR No	: TWARD STAMP
Site ID	: ATL - AP Telangana Warehouse	Site Address	: Survey No. 25 E,Banda Mylaram,Mulugu Mandal,Hyderabad,502336,Telangana	GO/GE No	: 56
Site Name	: ATL - AP Telangana Warehouse			ST Form No.	: CIE FM India Supply Chain Pvt. Ltd
Site Address	: Survey No. 25 E,Banda Mylaram,Mulugu Mandal,Hyderabad,502336,Telangana			Contact Person	: Date Entry No. 2291
				Way bill No	: NGRP NO.....2.160.....30.05.19
				No. of Pkgs.	: No. of Pkgs. 3
				Vegt. No.	: AP29UB8918
				Rate	: 14.5
				Amount	: 43.5

GSTIN No of Consignor : 36AABC1777B1ZJ GSTIN No of Consignee : 37AABC1777B1ZH Remarks :


S.No.	Item Code	Item Description	UOM	Qty.	Lot No.	Serial No.	FA. No.	MFG. No.	Tax Rate	Amount
1	11-61E5E0-0-01-02-ZZ-000	SMPS,Indoor -48V,Total Capacity 40 KW,Louding Capacity 20 KW,4000W, Make- Emerson, Version 1.0	Each	1		40013693852			AP - Telangana IGST -18%	Amt: 145351 Tax amt: 26163.18 Total: 171514.18
2	11-61E5E0-0-01-02-ZZ-000	SMPS,Indoor -48V,Total Capacity 40 KW,Louding Capacity 20 KW,4000W, Make- Emerson, Version 1.0	Each	1		40013693851			AP - Telangana IGST -18%	Amt: 145351 Tax amt: 26163.18 Total: 171514.18

Value	: Rs. 290702
Tax value	: Rs. 52326.36

Material Received
Without Storage
Loss & Damage
Good Condition

Received Signature

Authorized Signature



Indus Towers Limited
 ATL - AP Telangana Warehouse
 Survey No. 25 E,Banda Myaram,Mulugu Mandal,Hyderabad,502336,Telangana
Tax Invoice

Original for Recipient

Source		Destination		Project Details	
Department No.	11110047161	Document Date	: 29-MAY-2019	Project No.	: R/RL-3484357
Department	Technology	Internal IR Date	: 29-MAY-2019	Move order No	: 1561832
BOQ Req. No.	11150088268	Internal ISO Date	: 29-MAY-2019	GE/GO Date	:
Internal IR	11040124006	Consignee	: Indus Towers Limited	Transporter Name	: OSPS TELECOM SERVICES PVT LTD
Internal SO	31200047715	Site ID	: IN-1312538	Vehicle No	: AP29URB918
Consignor	Indus Towers Limited	Site Name	: Sy.No. 416 situated at Markapuram Village and Municipality, Prakasam District,Sy.No. 416 situated at Markapuram Village and Municipality, Prakasam District,Prakasham,MARK APURAM,523105,Andhra Pradesh	LR No	: OGD TWARD STAMP M/s. INDUS TOWERS LTD.
Site ID	ATL - AP Telangana Warehouse	Site Address	: Sy.No. 416 situated at Markapuram Village and Municipality, Prakasam District,Sy.No. 416 situated at Markapuram Village and Municipality, Prakasam District,Prakasham,MARK APURAM,523105,Andhra Pradesh	GO/GE No	: ST Form No. C16, FM India Supply Chain PTY. LTD
Site Name	Survey No. 25 E,Banda Myaram,Mulugu Mandal,Hyderabad,502336,Telangana	Contact Person	: G.C. 229.2	Way bill No	: Gate Entry No. 229.2
Site Address		No. of Pckgs.	: 161	NGRP No.	: 70105119
		Vch. No.	: AP29URB918	Vch. No.	: 3484357-1
		(Security Intry)			
GSTIN No of Consignor		GSTIN No of Consignee	37AABC17776B1ZH	Remarks	
S.No.	Item Code	Item Description	UOM	Qty.	Lot No.
1	13-152111-0-02-01-ZZ-000 HSN: 8415 SAC:	Air-Conditioner,2 X 2 TR,3 phase,Telepack,without inbuilt FCU,Fixed Temp Set 24 deg C, Make- HITACHI, Version 2.0,Design Temp 43 deg	Each	1	20007253862
2	13-152111-0-02-01-ZZ-000 HSN: 8415 SAC:	Air-Conditioner,2 X 2 TR,3 phase,Telepack,without inbuilt FCU,Fixed Temp Set 24 deg C, Make- HITACHI, Version 2.0,Design Temp 43 deg	Each	1	20007253863
		Material Received in Good Condition		Without Shortage / Damage	



Received Signature

Indus Towers Limited
ATL - AP Telangana Warehouse

Survey No. 25 E,Banda Mylaram,Mulugu Mandal,Hyderabad,502336,Telangana

Tax Invoice

Original for Recipient

SN: 8415	SAC:	11-0-02-01-ZZ-000	Air-Conditioner, 2 X 2 TR,3 phase, Telepack, without inbuilt FCU, Fixed Temp Set 24 deg C. Make- HITACHI, Version 2.0. Design Temp 43 deg	Each	1	20007253864	AP - Telangana IGST - 28%	Amnt 74154 Tax amt 20763.12 Total 94917.12
OUTWARD STAMP								

M/s. INDUS TOWER LTD.

C/o. FM India Supply Chain IT. ID

Gate Entry No.....

NGRP No....A161

No. of Pkgs....3

Vch. No.....A...TMS...

(Security No).....

Material Received in Good Condition
Without Shortage / Damage

Received Signature



India Tones Limited

卷之三

Struktur	Reaktion	Wirkung
Carboxylgruppe	Reaktion mit Alkalien	Neutralisierung
Alkoholgruppe	Reaktion mit Säuren	Neutralisierung
Aminogruppe	Reaktion mit Säuren	Neutralisierung
Phenolgruppe	Reaktion mit Säuren	Neutralisierung

RS. 15276.6
RS. 15276.5

卷之三

SITE RETURN MATERIAL CHECKLIST

GR No :

Req No. : 11150087634

Consigner :

Site Id : IN-1312538

Address : Sy.No. 416 situated at Markapuram Village and Municipality, Prakasam District, Sy.No. 416 situated at Markapuram Village and Municipality, Prakasam District, , AP

Consignee : AP Telangana Logical Warehouse - ATL

Delivery At :

Challan Date :

20 May 2019

Req Date :

20 May 2019

Vehicle No :

By Hand/Through :

Transporter Name : OSPS Telecom (AP - Telangana)

Transport Representative:

Contact No :

SNo	Src No	Item Code	Item Description	Unit	QR. Code	Qty	Remark
1	SRCA TL19052014969	11-51K430-0-02-01-ZZ-000	Diesel Generator, 62.5 KVA, AC 3 phase Water Cooled, with AMF Panel with Silent Canopy, Make- MAHINDRA, Version 2.0	EA	10000427835	1	

Prepared By : Ramakrishna Narayana

Checked By :

Contact no.	
At Site	
Handed Over.....Units with copy of challan	
Sign	
Name	
Contact No.	

Contact no.		
Warehouse		
Received By.....Units with copy of challan		
Sign		
Name		
Contact No.		

Parent QR. Code	Child QR. Code
10000427835	10000427836
10000427835	10000427837
10000427835	

① DGA 62.5 KVA

② Battery

③ AMF Panel



INWARD STAMP
 M/s. INDUS TOWERS LTD.
 C/o. FM India Supply Chain Pvt. Ltd.
 Gate Entry No. 1195 Date 21/05/19
 INVOICE NO. 7634 Date
 No. of Pckgs. 01 Pkg
 Veh. No. AP 29U 8418 Time 15:20
 Signature (Security Inch).

Page 1 of 1

AP29U
8918
12 NO. 54

(2)

SITE RETURN MATERIAL CHECKLIST

GR No : Challan Date : 24 Aug 2019
 Req No. : 11150095224 Req Date : 24 Aug 2019
 Consigner : Vehicle No :
 Site Id : IN-1312538 By Hand/Through :
 Address : Sy.No. 416 situated at Markapuram Village and Municipality, Prakasam District, Sy.No. 416 situated at Markapuram Village and Municipality, Prakasam District, AP Transporter Name : OSPS Telecom (AP - Telangana)
 Consignee : AP Telangana Logical Warehouse - ATL Transport Representative:
 Delivery At :

SNo	Src No	Item Code	Item Description	Unit	QR. Code	Qty	Remark
1	SRCACTL19082413491	11-51K410-0-01-01-ZZ-000	Diesel Generator, 62.5 KVA, AC 3 phase Water Cooled, without AMF Panel with Silent Canopy, Make-MAHINDRA, Version 1.0	EA	20010860338	1	

Prepared By : Ramakrishna Narayana

Checked By :

Contact no.	
At Site	
Handed Over.....Units with copy of challan	
Sign	
Name	
Contact No.	

Contact no.	
Warehouse	
Received By.....Units with copy of challan	
Sign	
Name	
Contact No.	

Parent QR. Code	Child QR. Code
20010860338	



INWARD STAMP
 M/s. INDUS TOWERS LTD.
 C/o. FM India Supply Chain Pvt.Ltd.
 Gate Entry No. 3969 Date 07/09/19
 INVOICE No. 5224 Date
 No.of Pkgs. 01
 Veh.No. AP 12 V 6210 Time 11.15.10
 Signature (Security Inch) *CHD*

Page 1 of 1

APPU
 6210
 LNO. 75

