

MOV AL, 82H. MOV DX, 22HI OUT DX, AL.

IN AL, 22111.

MOV DX,221H MB输入 MOV AL,0DH DUT DX,AL MOV DX,220H MOV DX,220H DX,A输出. OUT DX,AL.

MOV DX, 223H. MOV AL, OIH.
OUT DX, AL
MOV AL, ODH
OUT DX, AL
MOV AL, ODH
OUT DX, AL
MOV AL, OFH
OUT DX, AL.

