GTS1 Updates/Fixes

Client: Dan Martenson · Project ID: 68279030 · VIN/Chassis: — · Generated: Nov 4, 2026, 10:09 AM CT

Financial Summary

Measure	Amount
Current Project Value	
Parts billable	$5,608.00
Services billable	$5,695.00
Separately billable labor to date (valued, not yet invoiced)	$7,250.00
Total current billable	**$18,553.00**
Projected Value (estimate)	
Remaining estimated billable labor	$5,075.00
Total projected project value	**$23,628.00**
Invoice Position	
Finalized invoiced	$0.00
Paid	$0.00
Outstanding	$0.00
Allocated to drafts	$7,031.00
Parts & Services available to invoice	**$4,272.00**
Parts & Services Profitability (internal)	
Estimated Parts & Services cost	$7,700.15
Estimated gross profit	$3,602.85
Estimated gross margin	**31.88%**

Current project value is not the amount currently invoice-eligible. Separately billable labor is valued but not yet supported by the invoicing workflow. Projected labor is an estimate of future work, not completed work.

Parts Detail

Description / Part #	Required	Finalized	On draft	Available	Est. cost (ext.)	Actual cost (ext.)	Unit sale price	Billable	Billing status
Steering Rack Rubber Seal 964 and Early 993 964 347 333 03	1	0	0	1	$22.95	Not recorded	$40.00	$40.00	1 available
RS Engine Mount for 964 and 993 M154	2	0	0	2	$284.00	Not recorded	$213.00	$426.00	2 available
Porsche Door Panel Trim Support Left 911-555-421-00-01C	1	0	0	1	$7.00	Not recorded	$12.00	$12.00	1 available

Description / Part #	Required	Finalized	On draft	Available	Est. cost (ext.)	Actual cost (ext.)	Unit sale price	Billable	Billing status
Porsche Door Panel Trim Support Right 911-555-422-00-01C	1	0	0	1	$7.00	Not recorded	$12.00	$12.00	1 available
Mechanical Rear Decklid Strut, Carbon Fiber REN-E188-CBN	1	0	0	1	$130.00	Not recorded	$195.00	$195.00	1 available
Porsche Steering Rack Lock Nut 95910117200	1	0	0	1	$15.29	Not recorded	$27.00	$27.00	1 available
Porsche Steering Rack Bushing 96434713707	2	0	0	2	$16.78	Not recorded	$15.00	$30.00	2 available
Porsche Steering Rack Boot 96434719103	2	0	0	2	$24.98	Not recorded	$22.00	$44.00	2 available
1989 Porsche 911 Carrera 4 Porsche 911 C2 C4 Rebuilt Steering Rack 96434700902	1	0	0	1	$1,249.98	Not recorded	$1,625.00	$1,625.00	1 available
Black Oil Key Blank for Porsche 911 / 914 Black	2	0	0	2	$178.22	Not recorded	$143.00	$286.00	2 available
PLX Wideband O2 Air Fuel Ratio Sensor Module | Air/Fuel Ratio AFR	1	0	1	0	$155.76	Not recorded	$300.00	$300.00	1 on draft
Heating Pipe. Porsche 964 & 993 6 964167003 964167003	1	0	1	0	$189.00	Not recorded	$248.00	$248.00	1 on draft
Engine air duct. Porsche 964 / 993 96410640302	1	0	1	0	$72.44	Not recorded	$168.00	$168.00	1 on draft
M18X1.5 O2 Sensor Bung and Plug Notched Style (2 Bungs/ 2 Plugs)	1	0	1	0	$13.00	Not recorded	$23.00	$23.00	1 on draft
Bosch LSU4.9 Wideband Oxygen O2 Air Fuel Ratio Sensor	1	0	1	0	$169.88	Not recorded	$255.00	$255.00	1 on draft
Bosch LSU4.9 Wideband Oxygen O2 Air Fuel Ratio Sensor Harness	1	0	1	0	$56.62	Not recorded	$91.00	$91.00	1 on draft
REAR 16" Classic Windshield Wiper Arm 911 628 613 01	2	0	2	0	$12.48	Not recorded	$11.00	$22.00	2 on draft
Main Door Seal - Porsche 91153109503	1	0	1	0	$23.15	Not recorded	$41.00	$41.00	1 on draft
911 Door Panel Moisture Barrier (pair)-DPMB	1	0	1	0	$8.80	Not recorded	$15.00	$15.00	1 on draft
Porsche Fluid Reservoir - 911 89-94 964-528-019-02	1	0	1	0	$141.00	Not recorded	$272.00	$272.00	1 on draft
Washer Pump Relay 92861811303	1	0	1	0	$109.73	Not recorded	$165.00	$165.00	1 on draft
Porsche Window Channel Guide - Felt 91154290500	2	0	2	0	$63.14	Not recorded	$60.00	$120.00	2 on draft

Description / Part #	Required	Finalized	On draft	Available	Est. cost (ext.)	Actual cost (ext.)	Unit sale price	Billable	Billing status
1974-1988 Porsche 911 Front Seat Belt Kit 5052	1	0	1	0	$385.95	Not recorded	$540.00	$540.00	1 on draft
Alcantara Auto Cover - 9040 Black ALC-9040-C	2	0	2	0	$268.00	Not recorded	$201.00	$402.00	2 on draft
Alcantara Multilayer - 9040 Black ALC-9040-ML	1	0	1	0	$140.00	Not recorded	$249.00	$249.00	1 on draft
Parts subtotal	**32**	**0**	**18**	**14**	**$3,745.15**			**$5,608.00**	

Estimated and actual cost are extended (quantity × unit cost). Unit sale price is the per-unit billing price; unit prices are not totaled.

Services Detail

Description	Qty	Est. cost	Actual cost	Billable	Draft allocation	Billing status
Tune file analysis and optimization based on road tests and tune sessions	1	$1,125.00	Not recorded	$1,575.00	—	Available
Powder Coating	1	$20.00	Not recorded	$75.00	$20.00	On 1 draft(s)
Chrome Plated Solid Window door Frames	1	$2,810.00	Not recorded	$4,045.00	$4,033.00	On 1 draft(s)
Services subtotal	**3**	**$3,955.00**	**Not recorded**	**$5,695.00**	**$4,053.00**	

Draft allocation is the amount locked on a draft invoice at the time it was drafted; it can differ from the current billable price.

Labor Detail

Task	Billable logged hrs	Approved rate	Billable to date	Remaining est. hrs	Projected add'l billing	Classification
Refurbish door handle trim	0.00 h	$145.00/h	$0.00	3.00 h	$435.00	Billable (valued, not invoiced)
Order Front Steering Cover // or Find in Stock	0.00 h	$145.00/h	$0.00	0.25 h	$36.25	Billable (valued, not invoiced)
Replace Damaged Chrome Decklid Grill and Trim Pieces on Decklid	0.00 h	$145.00/h	$0.00	4.00 h	$580.00	Billable (valued, not invoiced)
Final Clean Prior to Delivery	0.00 h	$145.00/h	$0.00	2.00 h	$290.00	Billable (valued, not invoiced)
Engine Bay Cleanup	0.00 h	$145.00/h	$0.00	1.00 h	$145.00	Billable (valued, not invoiced)
Replace Trans Mount // Front	0.00 h	$145.00/h	$0.00	0.25 h	$36.25	Billable (valued, not invoiced)
Replace Rear Engine Mounts	0.00 h	$145.00/h	$0.00	2.00 h	$290.00	Billable (valued, not invoiced)
Install Door to Window Chrome Trim	0.00 h	$145.00/h	$0.00	0.50 h	$72.50	Billable (valued, not invoiced)
Steering Rack Leaking into Tie Rod Boot	0.00 h	$145.00/h	$0.00	4.00 h	$580.00	Billable (valued, not invoiced)
Install Door Panels	0.00 h	$145.00/h	$0.00	2.00 h	$290.00	Billable (valued, not invoiced)
Make Door Arrestor Cover Plates	4.00 h	$145.00/h	$580.00	0.00 h	$0.00	Billable (valued, not invoiced)
Diagnose O2 Issue and Test PLX Wideband, replace and test new	4.50 h	$145.00/h	$652.50	0.00 h	$0.00	Billable (valued, not invoiced)

Task	Billable logged hrs	Approved rate	Billable to date	Remaining est. hrs	Projected add'l billing	Classification
Drill holes and deck lid to drain water	0.50 h	$145.00/h	$72.50	0.00 h	$0.00	Billable (valued, not invoiced)
Fix Chrome on Trim/Lights	0.00 h	$145.00/h	$0.00	2.00 h	$290.00	Billable (valued, not invoiced)
Frunk hood struts, paint all black	0.75 h	$145.00/h	$108.75	0.00 h	$0.00	Billable (valued, not invoiced)
Ventelation Fan Speed not working	2.00 h	$145.00/h	$290.00	0.00 h	$0.00	Billable (valued, not invoiced)
Install new door seals (all cut up)	0.50 h	$145.00/h	$72.50	0.00 h	$0.00	Billable (valued, not invoiced)
Order Backdate Heat Parts	0.00 h	$145.00/h	$0.00	0.25 h	$36.25	Billable (valued, not invoiced)
Backdate Heat Pipe (Clamp to Motor)	0.00 h	$145.00/h	$0.00	0.25 h	$36.25	Billable (valued, not invoiced)
O2 Sensor Replace and Fix	2.00 h	$145.00/h	$290.00	0.00 h	$0.00	Billable (valued, not invoiced)
Adjust tps for idle and start	2.25 h	$145.00/h	$326.25	0.00 h	$0.00	Billable (valued, not invoiced)
Assess whole car for Pre-Sale Checklist (ADD TASKS)	0.00 h	$145.00/h	$0.00	1.00 h	$145.00	Billable (valued, not invoiced)
Engine Tune Fixes and Checks	11.00 h	$145.00/h	$1,595.00	0.00 h	$0.00	Billable (valued, not invoiced)
Need new Light Switch Cover/Knob (old pops off)	1.00 h	$145.00/h	$145.00	0.00 h	$0.00	Billable (valued, not invoiced)
Make 2 more keys for Dan // Speed Hole	0.00 h	$145.00/h	$0.00	1.00 h	$145.00	Billable (valued, not invoiced)
Look at gas cap and reset tighness	1.00 h	$145.00/h	$145.00	0.00 h	$0.00	Billable (valued, not invoiced)
Install New Seat Belts // Black	0.50 h	$145.00/h	$72.50	0.00 h	$0.00	Billable (valued, not invoiced)
Get front end alignment done pull to the left	0.00 h	$145.00/h	$0.00	1.00 h	$145.00	Billable (valued, not invoiced)
Rear Decklid / Fix lineup	0.00 h	$145.00/h	$0.00	1.00 h	$145.00	Billable (valued, not invoiced)
New/Missing Wheelwell	0.50 h	$145.00/h	$72.50	0.00 h	$0.00	Billable (valued, not invoiced)
Fix parking brake arm	1.00 h	$145.00/h	$145.00	0.00 h	$0.00	Billable (valued, not invoiced)
Recoat and fix install of sill plates // Chipped	1.50 h	$145.00/h	$217.50	0.00 h	$0.00	Billable (valued, not invoiced)
Clean Up Exterior	0.00 h	$145.00/h	$0.00	1.00 h	$145.00	Billable (valued, not invoiced)
Fix Carpet areas (Front and Rear)	0.00 h	$145.00/h	$0.00	4.00 h	$580.00	Billable (valued, not invoiced)
Replace Door Frames with Solid Chromed Ones	4.50 h	$145.00/h	$652.50	0.00 h	$0.00	Billable (valued, not invoiced)
Cover new Frunk Panels and Install	2.00 h	$145.00/h	$290.00	0.00 h	$0.00	Billable (valued, not invoiced)
Clean Roll Cage to assess damage to be covered	1.50 h	$145.00/h	$217.50	0.00 h	$0.00	Billable (valued, not invoiced)
Cover Roll Cage areas in Leather and Alcantara	8.00 h	$145.00/h	$1,160.00	0.00 h	$0.00	Billable (valued, not invoiced)
Install Center Caps	0.50 h	$145.00/h	$72.50	0.00 h	$0.00	Billable (valued, not invoiced)
New old school windshield wiper blades	0.00 h	$145.00/h	$0.00	0.50 h	$72.50	Billable (valued, not invoiced)
Fix Shifter / Losse and missing a set screw	0.50 h	$145.00/h	$72.50	0.00 h	$0.00	Billable (valued, not invoiced)
Fix Front Seat Mounts and Angles	0.00 h	$145.00/h	$0.00	4.00 h	$580.00	Billable (valued, not invoiced)
Labor subtotal (billable only)	**50.00 h**		**$7,250.00**	**35.00 h**	**$5,075.00**	

Projected Total Labor Billing	Amount
Labor billable to date	$7,250.00
+ Projected remaining labor	$5,075.00
= Projected total labor billing	**$12,325.00**

Internal labor costs are not configured; labor margin is not calculated. Only labor classified Billable is valued. Service-included, non-billable and unclassified hours are not counted as additional labor revenue. Rates are not totaled.

Invoices

Invoice	Type	Status	Issue date	Total	Paid	Balance due
5ceb88	progress	draft		$6,964.00	$0.00	$6,964.00

Financial Reconciliation

Category	Current billable	Projected additional	Projected total
Parts	$5,608.00	—	$5,608.00
Services	$5,695.00	—	$5,695.00
Labor	$7,250.00	$5,075.00	$12,325.00
TOTAL	**$18,553.00**	**$5,075.00**	**$23,628.00**

Invoice position (Parts & Services only)	Amount
Finalized invoiced	$0.00
Paid	$0.00
Outstanding	$0.00
Allocated to drafts	$7,031.00
Available to invoice	**$4,272.00**

Invoice position covers Parts & Services only. Labor is valued but not yet supported by the invoicing workflow and is not included in available-to-invoice.