24_9078_Pravi 1976 RSR

Client: Pravi Thakkar · Project ID: 89966A36 · VIN/Chassis: RSR · Generated: Nov 4, 2026, 10:07 AM CT

Financial Summary

Measure	Amount
Current Project Value	
Parts billable	$25,249.54
Services billable	$2,839.27
Separately billable labor to date (valued, not yet invoiced)	$14,312.50
Total current billable	**$42,401.31**
Projected Value (estimate)	
Remaining estimated billable labor	$0.00
Total projected project value	**$42,401.31**
Invoice Position	
Finalized invoiced	$28,332.80
Paid	$22,242.53
Outstanding	$5,808.28
Allocated to drafts	$0.00
Parts & Services available to invoice	**$254.00**
Parts & Services Profitability (internal)	
Estimated Parts & Services cost	$20,494.19
Estimated gross profit	$7,594.62
Estimated gross margin	**27.04%**

Current project value is not the amount currently invoice-eligible. Separately billable labor is valued but not yet supported by the invoicing workflow. Projected labor is an estimate of future work, not completed work.

Parts Detail

Description / Part #	Required	Finalized	On draft	Available	Est. cost (ext.)	Actual cost (ext.)	Unit sale price	Billable	Billing status
Front Tow Hooks and Tie Downs (set of 2) E03	1	0	0	1	$169.00	Not recorded	$254.00	$254.00	1 available
Oil Temperature Sensor 1976 901-641-632-00	1	1	0	0	$67.50	Not recorded	$108.00	$108.00	1 finalized
Spacer Rose for Window Crank 901-552-891-20-OEM	2	2	0	0	$14.50	Not recorded	$13.00	$26.00	2 finalized

Description / Part #	Required	Finalized	On draft	Available	Est. cost (ext.)	Actual cost (ext.)	Unit sale price	Billable	Billing status
Bosch Classic Wiper Blades - Spectrum Direct Fit 13 Inch C1301	2	2	0	0	$39.98	Not recorded	$35.00	$70.00	2 finalized
VHT SP739 Brake Caliper Spray Paint - Satin Black - 11 oz Aerosol Can VHT SP739	1	1	0	0	$16.99	Not recorded	$28.00	$28.00	1 finalized
REAR 16" Classic Windshield Wiper Arm 911 628 613 01	2	2	0	0	$12.48	Not recorded	$11.00	$22.00	2 finalized
Belt Alternator 964 9.5 X 776 999-192-338-50-M100	1	1	0	0	$23.34	Not recorded	$42.00	$42.00	1 finalized
Belt Alternator 964 9.5 X 760 (SMALLER) 999-192-343-51	1	1	0	0	$28.90	Not recorded	$46.00	$46.00	1 finalized
Obeaming 50W 12V USB Outlet Dual 25W USB-C Charger PD 3.0 Aluminum Fast Charging Socket B0FLJNSVC4	1	1	0	0	$16.00	Not recorded	$28.00	$28.00	1 finalized
Porsche Trunk Lid Buffer - Rubber hood stop 99970303650	2	2	0	0	$6.00	Not recorded	$5.00	$10.00	2 finalized
URO Rubber Door Plug 99970304050	10	10	0	0	$27.10	Not recorded	$4.00	$40.00	10 finalized
Wing Screw for Electrical Panel Cover 900-029-102-02-M350	1	1	0	0	$4.16	Not recorded	$7.00	$7.00	1 finalized
Porsche DME Relay - 911 84-89 911-618-154-01 911.618.154.01--URO	1	1	0	0	$20.60	Not recorded	$36.00	$36.00	1 finalized
Wehrle 91461830311, 54201102 Turn Signal/Flasher Relay; 4 Prong - Porsche | 111953227D 191953227A 1H0953227 90161830300 91461830311	1	1	0	0	$39.98	Not recorded	$44.00	$44.00	1 finalized
BA7S Instrument LED Light BA7S	0	0	0	0	$0.00	Not recorded	$16.00	$0.00	Nothing to bill
Bulb Socket for Dashboard Instruments 99963200700	2	2	0	0	$13.14	Not recorded	$11.00	$22.00	2 finalized
Rennline Fully Mechanical Hood Strut E187	1	1	0	0	$110.00	Not recorded	$165.00	$165.00	1 finalized
Steering Hub Spacer 12mm B0DSJ9XT8F	1	1	0	0	$10.61	Not recorded	$19.00	$19.00	1 finalized
Momo Horn Button Retainer Plate	1	1	0	0	$11.00	Not recorded	$19.00	$19.00	1 finalized
VictorReinz 99311119500, 712495330 Exhaust Manifold Gasket; Seal Ring - Porsche | 93112319500 94411120506 99311119400 W01331641252 99311119500	5	5	0	0	$27.00	Not recorded	$9.00	$45.00	5 finalized
911 // Window Vent Seal Fixed - Right 901-542-922-21	1	1	0	0	$146.00	Not recorded	$197.00	$197.00	1 finalized

Description / Part #	Required	Finalized	On draft	Available	Est. cost (ext.)	Actual cost (ext.)	Unit sale price	Billable	Billing status
Window Frame Mount Bracket - Pair 91154206100KT	1	1	0	0	$24.64	Not recorded	$54.00	$54.00	1 finalized
RCA Plug Splitter 2 Male to 4 Female Y Adapter B0BS1HVXS5	1	1	0	0	$29.00	Not recorded	$46.00	$46.00	1 finalized
RCA Level Controller Volume Control B099VXYM7Q	1	1	0	0	$13.00	Not recorded	$23.00	$23.00	1 finalized
Porsche Racing Style Rubber Tie-Downs for Front Hood TRE PEL H36 PEL.H36 PELH36 | Pelican Parts PELH36	1	1	0	0	$50.00	Not recorded	$80.00	$80.00	1 finalized
Odometer Gear, 20x30 Tooth Gear ODO-POR-20-30	1	1	0	0	$25.00	Not recorded	$40.00	$40.00	1 finalized
Porsche Plastic Door Plug Set of 14 9997031194014HBT	1	1	0	0	$21.00	Not recorded	$37.00	$37.00	1 finalized
Porsche Window Channel Guide - Felt 91154290500	2	2	0	0	$75.00	Not recorded	$60.00	$120.00	2 finalized
Porsche Plastic Expansion Rivet 99959142940	2	2	0	0	$4.50	Not recorded	$4.00	$8.00	2 finalized
Porsche Window Frame to Door Seal - Right Rear 9115317140101C	1	1	0	0	$10.43	Not recorded	$18.00	$18.00	1 finalized
Porsche Window Frame to Door Seal - Left Rear 9115317130101C	1	1	0	0	$10.43	Not recorded	$18.00	$18.00	1 finalized
Window frame to door seal, front left 9115317110201C	1	1	0	0	$12.50	Not recorded	$22.00	$22.00	1 finalized
Window frame to door seal, front right 9115317120201C	1	1	0	0	$7.26	Not recorded	$13.00	$13.00	1 finalized
Gauge bezels alloy Porsche 911 911680AB911	1	1	0	0	$85.00	Not recorded	$136.00	$136.00	1 finalized
Blower Control Cable Clamping Bolt 90121168300	3	3	0	0	$17.97	Not recorded	$13.00	$39.00	3 finalized
1.5 inch Automotive Air Duct Hose, Length 1 Meter B0DXKV5M4Q	2	2	0	0	$48.00	Not recorded	$42.00	$84.00	2 finalized
Dansk Original 90121100822, 1623200280 HVAC Heater Control Box; Black Aluminized Steel; Right SKU: 1433482-JP-90121100822 - Porsche | JP17480 JP90121100822	2	2	0	0	$285.00	Not recorded	$225.00	$450.00	2 finalized
Porsche Heater Cable Guide Tube 90142470401	2	2	0	0	$40.40	Not recorded	$35.00	$70.00	2 finalized
DOOR LATCH BOWDEN CABLE SUPPORT // RS 91153109700	2	2	0	0	$98.00	Not recorded	$78.00	$156.00	2 finalized
911 964 993 Door Handle Lever Bowden Cable 993.531.509.00	2	2	0	0	$80.00	Not recorded	$64.00	$128.00	2 finalized

Description / Part #	Required	Finalized	On draft	Available	Est. cost (ext.)	Actual cost (ext.)	Unit sale price	Billable	Billing status
911 DOOR LATCH RELAY LEVER // RS Update 911.531.083.00	2	2	0	0	$40.00	Not recorded	$35.00	$70.00	2 finalized
911 Hot Air Hose - Engine to Heat Exchanger 91121155300	4	4	0	0	$56.56	Not recorded	$25.00	$100.00	4 finalized
4x6 Speaker // Infinity Kappa 463XF 108K463XF	1	1	0	0	$250.00	Not recorded	$475.00	$475.00	1 finalized
Rennline Lower Shift Boot for Porsche 964/993 (1989-1994) - OE Style Replacement I143	1	1	0	0	$55.00	Not recorded	$88.00	$88.00	1 finalized
Backdate Dash Panels // Custom AK_BackdateDash	1	1	0	0	$100.00	Not recorded	$800.00	$800.00	1 finalized
Center Cap for Fuch Wheel (4) 90136103200	1	1	0	0	$345.00	Not recorded	$483.00	$483.00	1 finalized
Heater Control Knob / Brake Area JP91142479203	2	2	0	0	$28.00	Not recorded	$25.00	$50.00	2 finalized
Parking Brake Lever setup 911 91142405115	1	1	0	0	$150.00	Not recorded	$225.00	$225.00	1 finalized
AK Aero Bullet Mirror / Longhood LongarmAeroMirror	1	1	0	0	$175.00	Not recorded	$800.00	$800.00	1 finalized
AK // Custom Porsche Decklid Grill CustomDecklidGrill	1	1	0	0	$110.00	Not recorded	$575.00	$575.00	1 finalized
Parking Brake Lever Boot 92342459100	1	1	0	0	$27.00	Not recorded	$43.00	$43.00	1 finalized
Porsche Three Connection Tie Bar For Fuse Box - 356/911/912 50-73 SMC-612-801-00 SMC.612.801.00	5	5	0	0	$51.45	Not recorded	$18.00	$90.00	5 finalized
2pcs 2.5 Inch Stainless 40-64mm\ Hose Clamp B09XQ8RS7X	10	10	0	0	$60.00	Not recorded	$11.00	$110.00	10 finalized
Engine air duct. Porsche 964 / 993 96410640302	1	1	0	0	$112.00	Not recorded	$168.00	$168.00	1 finalized
Heating Pipe. Porsche 964 & 993 6 964167003 964167003	1	1	0	0	$165.00	Not recorded	$248.00	$248.00	1 finalized
9 Eleven Headlights / Raven Raven S	1	1	0	0	$2,500.00	Not recorded	$2,900.00	$2,900.00	1 finalized
(New) 911/912/930 Fresh Air Controller Bowden Cable - 1965-89 91157211400	1	1	0	0	$40.00	Not recorded	$64.00	$64.00	1 finalized
LEFT - Heater Control Box Hose Clamp with Cable Guide 90121105122	1	1	0	0	$30.20	Not recorded	$48.00	$48.00	1 finalized

Description / Part #	Required	Finalized	On draft	Available	Est. cost (ext.)	Actual cost (ext.)	Unit sale price	Billable	Billing status
Right - Heater Control Box Hose Clamp with Cable Guide 90121105222	1	1	0	0	$30.91	Not recorded	$49.00	$49.00	1 finalized
Car Air Intake Pipe, 2.5 inch	2	2	0	0	$20.00	Not recorded	$18.00	$36.00	2 finalized
1.5 inch Automotive Air Duct Hose, Length 1 Meter B0DXKV5M4Q	2	2	0	0	$48.00	Not recorded	$42.00	$84.00	2 finalized
Porsche 180A Alternator LMA498	1	1	0	0	$1,000.00	Not recorded	$1,300.00	$1,300.00	1 finalized
Electric Air Conditioning for Classic 911 (single condenser) AC AC	1	1	0	0	$5,100.00	Not recorded	$5,628.00	$5,628.00	1 finalized
911 Hot Air Hose - Engine to Heat Exchanger 91121155300	1	1	0	0	$14.14	Not recorded	$25.00	$25.00	1 finalized
VUBT2 Universal Bluetooth 4.0 Audio Receiver VUBT2	1	1	0	0	$39.99	Not recorded	$64.00	$64.00	1 finalized
Sound Ordnance™ M75-4 Compact 4-channel car amplifier — 75 watts RMS x 4 M75-4	1	1	0	0	$159.99	Not recorded	$240.00	$240.00	1 finalized
Porsche 911 S Coupe 911 2.7L H6 Heater Cable Wire 91142470101	2	2	0	0	$28.28	Not recorded	$25.00	$50.00	2 finalized
RennShift Performance Shifter 901/915/930/914 RSOR-EX-BST-BK	1	1	0	0	$679.00	Not recorded	$729.00	$729.00	1 finalized
Porsche Bursch Stainless Steel 1-3/4 in Header Set W/ Heat Exchangers - 911 BX-9359-SS BX.9359.SS	1	1	0	0	$2,696.00	Not recorded	$3,123.06	$3,123.06	1 finalized
Alternator bearing fan blade. Pors 96410605131	1	1	0	0	$80.00	Not recorded	$128.00	$128.00	1 finalized
Porsche Windshield Moulding Joint (Black) 9115419210170K	2	2	0	0	$16.36	Not recorded	$18.00	$36.00	2 finalized
Porsche O.E.M. Windshield Moulding (Black) 9115419110170	1	1	0	0	$86.28	Not recorded	$138.00	$138.00	1 finalized
Porsche Windshield Moulding (Black) 9115419120170K	1	1	0	0	$88.43	Not recorded	$141.49	$141.49	1 finalized
RED 4 Gauge OFC Wire (25ft) AWG Amp Battery Cable for Automotive Electrical Wiring - Oxygen Free Copper (OFC) Welding Cable 4GA - Car Amplifier Power & Ground... B01MXRVIPD	1	1	0	0	$65.00	Not recorded	$104.00	$104.00	1 finalized
Intermittent wiper relay wiring har 91161205902 91161205902	1	1	0	0	$67.00	Not recorded	$107.00	$107.00	1 finalized

Description / Part #	Required	Finalized	On draft	Available	Est. cost (ext.)	Actual cost (ext.)	Unit sale price	Billable	Billing status
Porsche 911 Door Threshold Side Sills Protectors Set BLACK FINISH 90155100010	1	1	0	0	$145.00	Not recorded	$218.00	$218.00	1 finalized
Porsche Windshield Seal - URO Parts 91154122503 91154122503	1	1	0	0	$75.00	Not recorded	$120.00	$120.00	1 finalized
16AWG Speaker Wire, GearIT Pro Series 16 Gauge OFC Speaker Wire Cable (500 Feet / 152.4 Meters) B01MA6MPBB	1	1	0	0	$63.00	Not recorded	$101.00	$101.00	1 finalized
Wing Screw for Electrical Panel Cover 900-029-102-02-M350	1	1	0	0	$4.16	Not recorded	$7.00	$7.00	1 finalized
HVAC Heater Control Cable Clip 90157191900	4	4	0	0	$23.20	Not recorded	$10.00	$40.00	4 finalized
Blower Control Cable Clamping Bolt 90121168300	2	2	0	0	$15.18	Not recorded	$13.00	$26.00	2 finalized
Door Panel // M4 x 25mm // Flat Phillips Head Screw 91698A728	2	2	0	0	$0.82	Not recorded	$1.00	$2.00	2 finalized
1974-1988 Porsche 911 Front Seat Belt Kit 5052	1	1	0	0	$385.95	Not recorded	$540.00	$540.00	1 finalized
Porsche Intermittent Wiper Relay 911-618-149-02	1	1	0	0	$119.64	Not recorded	$210.00	$210.00	1 finalized
12AWG Speaker Wire, OFC 100 Feet B00HZWYJJO	1	1	0	0	$35.00	Not recorded	$56.00	$56.00	1 finalized
Black 4 Gauge OFC Wire (25ft) AWG Amp Battery Cable for Automotive Electrical Wiring - Oxygen Free Copper (OFC) Welding Cable 4GA - Car Amplifier Power & Ground Cable, Stereo Audio Speakers, RV Trailer Wiring B0C7HCY2LC	1	1	0	0	$65.00	Not recorded	$75.00	$75.00	1 finalized
Joinfworld Fused Power Distribution Block Car Audio 4 Way MIDI(Mini-ANL) Fuse Block 12V 0/4 Gauge with Ground for Auto UTV Boat Stereo Amp B0B3X9TB8G	1	1	0	0	$19.00	Not recorded	$35.00	$35.00	1 finalized
Focal Sub 10 Slim 10" shallow-mount 4-ohm voice coil subwoofer speaker SUB10SLIM	2	2	0	0	$639.98	Not recorded	$448.00	$896.00	2 finalized
SELTERM 4 AWG Gauge Copper Lug Terminal Ring Terminal Eyelet B0CS6LZQXC	1	1	0	0	$16.00	Not recorded	$28.00	$28.00	1 finalized
JBL Club A600 // Woofer Amp 109CL600A	1	1	0	0	$340.00	Not recorded	$476.00	$476.00	1 finalized
Focal Performance 130AC Access 5-1/4" coaxial speakers 130AC	1	1	0	0	$329.99	Not recorded	$329.99	$329.99	1 finalized

Description / Part #	Required	Finalized	On draft	Available	Est. cost (ext.)	Actual cost (ext.)	Unit sale price	Billable	Billing status
Parts subtotal	**145**	**144**	**0**	**1**	**$18,532.92**			**$25,249.54**	

Estimated and actual cost are extended (quantity × unit cost). Unit sale price is the per-unit billing price; unit prices are not totaled.

Services Detail

Description	Qty	Est. cost	Actual cost	Billable	Draft allocation	Billing status
Replace 4 Tires on RSR	1	$1,394.00	Not recorded	$1,940.00	—	Finalized
Four Wheel Alignment and A/C System Charge	1	$567.27	Not recorded	$899.27	—	Finalized
Services subtotal	**2**	**$1,961.27**	**Not recorded**	**$2,839.27**	**$0.00**	

Draft allocation is the amount locked on a draft invoice at the time it was drafted; it can differ from the current billable price.

Labor Detail

Task	Billable logged hrs	Approved rate	Billable to date	Remaining est. hrs	Projected add'l billing	Classification
RSR Front Bumper Fix	8.50 h	$125.00/h	$1,062.50	0.00 h	$0.00	Billable (valued, not invoiced)
Swap to 964 oil temp gauge	0.25 h	$125.00/h	$31.25	0.00 h	$0.00	Billable (valued, not invoiced)
Engine Bay Vacumn Canister Fix	0.25 h	$125.00/h	$31.25	0.00 h	$0.00	Billable (valued, not invoiced)
Change oil sender	1.25 h	$125.00/h	$156.25	0.00 h	$0.00	Billable (valued, not invoiced)
Rust covert oil lines and paint	1.50 h	$125.00/h	$187.50	0.00 h	$0.00	Billable (valued, not invoiced)
Add metal skid sleds	0.25 h	$125.00/h	$31.25	0.00 h	$0.00	Billable (valued, not invoiced)
Driver door Pull Strap // Opening Shows (move handle up)	0.50 h	$125.00/h	$62.50	0.00 h	$0.00	Billable (valued, not invoiced)
Order New Set of Tires for RSR	0.25 h	$125.00/h	$31.25	0.00 h	$0.00	Billable (valued, not invoiced)
Test and Fix Fuel Low Light	0.75 h	$125.00/h	$93.75	0.00 h	$0.00	Billable (valued, not invoiced)
Trace wire for oil temp gauge // Not reacting to temp increase	3.00 h	$125.00/h	$375.00	0.00 h	$0.00	Billable (valued, not invoiced)
Idle Switch Adjust Stop	0.25 h	$125.00/h	$31.25	0.00 h	$0.00	Billable (valued, not invoiced)
Touchup Undercoat (Rockers/Wheelwells/Misc)	3.00 h	$125.00/h	$375.00	0.00 h	$0.00	Billable (valued, not invoiced)
Reinstall Clock/Oil Gauges	0.25 h	$125.00/h	$31.25	0.00 h	$0.00	Billable (valued, not invoiced)
Scuff pad oil lines and corroded areas	2.50 h	$125.00/h	$312.50	0.00 h	$0.00	Billable (valued, not invoiced)
Work with Classic Retrofit to Fix AC Intermitent	4.00 h	$125.00/h	$500.00	0.00 h	$0.00	Billable (valued, not invoiced)
Fix Seat Belt Rattle	0.25 h	$125.00/h	$31.25	0.00 h	$0.00	Billable (valued, not invoiced)
Install Engine Bay Cover Pieces	0.25 h	$125.00/h	$31.25	0.00 h	$0.00	Billable (valued, not invoiced)
Make and Install Seatbelt guide behind Console	2.00 h	$125.00/h	$250.00	0.00 h	$0.00	Billable (valued, not invoiced)
Wire up and test HORNS	0.50 h	$125.00/h	$62.50	0.00 h	$0.00	Billable (valued, not invoiced)

Task	Billable logged hrs	Approved rate	Billable to date	Remaining est. hrs	Projected add'l billing	Classification
Re-Glue Woven edges to panel & Re-VHB Driver door Trim	1.00 h	$125.00/h	$125.00	0.00 h	$0.00	Billable (valued, not invoiced)
Polish Gauge Glass/Remove Scratches	2.00 h	$125.00/h	$250.00	0.00 h	$0.00	Billable (valued, not invoiced)
Check why Tach Bounces (check 2nd ground wire)	0.25 h	$125.00/h	$31.25	0.00 h	$0.00	Billable (valued, not invoiced)
Install rear bumper	1.00 h	$125.00/h	$125.00	0.00 h	$0.00	Billable (valued, not invoiced)
Test and Fix Pass and Driver Pull Strap (too tight)	1.00 h	$125.00/h	$125.00	0.00 h	$0.00	Billable (valued, not invoiced)
Install Front Lights	2.00 h	$125.00/h	$250.00	0.00 h	$0.00	Billable (valued, not invoiced)
Build Front Lights	2.00 h	$125.00/h	$250.00	0.00 h	$0.00	Billable (valued, not invoiced)
Cover Frunk Panels with Leather and Carpet	1.25 h	$125.00/h	$156.25	0.00 h	$0.00	Billable (valued, not invoiced)
Repowdercoat Door Handle Plates	2.00 h	$125.00/h	$250.00	0.00 h	$0.00	Billable (valued, not invoiced)
Touchup door sills	0.25 h	$125.00/h	$31.25	0.00 h	$0.00	Billable (valued, not invoiced)
Order Grand Prix White	0.10 h	$125.00/h	$12.50	0.00 h	$0.00	Billable (valued, not invoiced)
Final Muffler Install and Testing	2.00 h	$125.00/h	$250.00	0.00 h	$0.00	Billable (valued, not invoiced)
Fix Rear Windshield	0.50 h	$125.00/h	$62.50	0.00 h	$0.00	Billable (valued, not invoiced)
Fix Gas Cable	1.00 h	$125.00/h	$125.00	0.00 h	$0.00	Billable (valued, not invoiced)
Rattle in Driver Door	0.25 h	$125.00/h	$31.25	0.00 h	$0.00	Billable (valued, not invoiced)
Re-VHB Rear Bumper Trim	1.00 h	$125.00/h	$125.00	0.00 h	$0.00	Billable (valued, not invoiced)
Alternator Light Comes on/off	2.00 h	$125.00/h	$250.00	0.00 h	$0.00	Billable (valued, not invoiced)
Install main glass trim pieces	0.50 h	$125.00/h	$62.50	0.00 h	$0.00	Billable (valued, not invoiced)
Install windshied wipers	0.15 h	$125.00/h	$18.75	0.00 h	$0.00	Billable (valued, not invoiced)
Install Muffler	1.00 h	$125.00/h	$125.00	0.00 h	$0.00	Billable (valued, not invoiced)
Clean and Touchup Brake Calipers	1.00 h	$125.00/h	$125.00	0.00 h	$0.00	Billable (valued, not invoiced)
Replace door sills	2.00 h	$125.00/h	$250.00	0.00 h	$0.00	Billable (valued, not invoiced)
Install rubber plugs for door frame bolts	1.00 h	$125.00/h	$125.00	0.00 h	$0.00	Billable (valued, not invoiced)
Upholster and Install Front Seats	8.00 h	$125.00/h	$1,000.00	0.00 h	$0.00	Billable (valued, not invoiced)
Make Appt for AC Charge and Alignment	1.00 h	$125.00/h	$125.00	0.00 h	$0.00	Billable (valued, not invoiced)
Raise Ride Height by 1/2 inch	2.50 h	$125.00/h	$312.50	0.00 h	$0.00	Billable (valued, not invoiced)
Install Final Frunk Panels	2.00 h	$125.00/h	$250.00	0.00 h	$0.00	Billable (valued, not invoiced)
Pull Rear Seat Delete and Fix Bumps	1.50 h	$125.00/h	$187.50	0.00 h	$0.00	Billable (valued, not invoiced)
Paint Horn Grill Backer/Fender Black	1.25 h	$125.00/h	$156.25	0.00 h	$0.00	Billable (valued, not invoiced)
Finish Audio Wiring	3.00 h	$125.00/h	$375.00	0.00 h	$0.00	Billable (valued, not invoiced)
Install Door Seals	0.50 h	$125.00/h	$62.50	0.00 h	$0.00	Billable (valued, not invoiced)

Task	Billable logged hrs	Approved rate	Billable to date	Remaining est. hrs	Projected add'l billing	Classification
Order RSR Porsche Badge for hood	1.00 h	$125.00/h	$125.00	0.00 h	$0.00	Billable (valued, not invoiced)
Fix Shorted Wire for Driver Turn Circuit	20.00 h	$125.00/h	$2,500.00	0.00 h	$0.00	Billable (valued, not invoiced)
Build Rear Taillights	1.00 h	$125.00/h	$125.00	0.00 h	$0.00	Billable (valued, not invoiced)
Touchup Paint	2.00 h	$125.00/h	$250.00	0.00 h	$0.00	Billable (valued, not invoiced)
Install Raven S Headlights	1.00 h	$125.00/h	$125.00	0.00 h	$0.00	Billable (valued, not invoiced)
INSTALL Door Stop Custom Mechanisms	2.00 h	$125.00/h	$250.00	0.00 h	$0.00	Billable (valued, not invoiced)
INSTALL Gauges and Test	1.00 h	$125.00/h	$125.00	0.00 h	$0.00	Billable (valued, not invoiced)
Reinstall Windshield	2.00 h	$125.00/h	$250.00	0.00 h	$0.00	Billable (valued, not invoiced)
Door Panel Installation	2.00 h	$125.00/h	$250.00	0.00 h	$0.00	Billable (valued, not invoiced)
Install Rear Lights	2.00 h	$125.00/h	$250.00	0.00 h	$0.00	Billable (valued, not invoiced)
Final Test/Confirm Function of Electric AC	2.00 h	$125.00/h	$250.00	0.00 h	$0.00	Billable (valued, not invoiced)
Mold and Build // Rear Splitter for Install	4.00 h	$125.00/h	$500.00	0.00 h	$0.00	Billable (valued, not invoiced)
Labor subtotal (billable only)	**114.50 h**		**$14,312.50**	**0.00 h**	**$0.00**	

Projected Total Labor Billing	Amount
Labor billable to date	$14,312.50
+ Projected remaining labor	$0.00
= Projected total labor billing	**$14,312.50**

Internal labor costs are not configured; labor margin is not calculated. Only labor classified Billable is valued. Service-included, non-billable and unclassified hours are not counted as additional labor revenue. Rates are not totaled.

Invoices

Invoice	Type	Status	Issue date	Total	Paid	Balance due
INV_3073	progress	sent	2026-08-25	$6,090.27	$0.00	$5,808.28
Invoice 3043	progress	paid		$2,083.00	$2,083.00	$0.00
Invoice 3043	progress	paid		$10,331.53	$10,331.53	$0.00
446125	progress	paid		$9,828.00	$9,828.00	$0.00

Financial Reconciliation

Category	Current billable	Projected additional	Projected total
Parts	$25,249.54	—	$25,249.54
Services	$2,839.27	—	$2,839.27
Labor	$14,312.50	$0.00	$14,312.50
TOTAL	**$42,401.31**	**$0.00**	**$42,401.31**

Invoice position (Parts & Services only)	Amount
Finalized invoiced	$28,332.80
Paid	$22,242.53
Outstanding	$5,808.28
Allocated to drafts	$0.00
Available to invoice	**$254.00**

Invoice position covers Parts & Services only. Labor is valued but not yet supported by the invoicing workflow and is not included in available-to-invoice.