# ATS1 // Accident Fixes

Client: Dan Martenson · Project ID: D3DF0328 · VIN/Chassis: — · Generated: Nov 4, 2026, 10:10 AM CT

Billing detail for review only. This is not an invoice and creates no payment obligation. Previously invoiced amounts are historical. Projected amounts are estimates, not amounts currently payable.

## Financial Summary

| Measure | Amount |
|---|---|
| **Current Project Value** | |
| Parts billable | $1,593.00 |
| Services billable | $5,054.00 |
| Separately billable labor to date (valued, not yet invoiced) | $5,365.00 |
| **Total current billable** | **$12,012.00** |
| **Projected Value (estimate, not currently payable)** | |
| Remaining estimated billable labor | $1,196.25 |
| **Total projected project value** | **$13,208.25** |
| **Invoice Position** | |
| Finalized invoiced (historical) | $0.00 |
| Paid | $0.00 |
| Outstanding | $0.00 |
| Allocated to drafts | $0.00 |
| **Parts & Services available to invoice** | **$6,647.00** |

*Current project value is not the amount currently invoice-eligible. Separately billable labor is valued but not yet supported by the invoicing workflow. Projected labor is an estimate of future work, not completed work.*

## Parts Detail

| Description / Part # | Required | Finalized | On draft | Available | Unit price | Billable | Billing status |
|---|---|---|---|---|---|---|---|
| 911/964/993 Oval Door Plug<br>999 703 345 400 1C | 4 | 0 | 0 | 4 | $4.00 | $16.00 | 4 available |
| SEM Low VOC Undercoating<br>SEM 40523 | 3 | 0 | 0 | 3 | $40.00 | $120.00 | 3 available |
| T25/T28 Turbo Blanket - Lava<br>FPRO35-028-01 | 1 | 0 | 0 | 1 | $270.00 | $270.00 | 1 available |
| WIX Oil Filter - WL10109<br>WL10109 | 1 | 0 | 0 | 1 | $62.00 | $62.00 | 1 available |
| Liqui Moly MoS2 Antifriction SAE 10W-40<br>P000207 | 3 | 0 | 0 | 3 | $75.00 | $225.00 | 3 available |
| Bosch Classic Wiper Blades - Spectrum Direct Fit 13 Inch<br>C1301 | 2 | 0 | 0 | 2 | $35.00 | $70.00 | 2 available |
| Victor Reinz 70-31414-40 Reinzosil RTV Silicone - 310 ml Tube<br>70-31414-40 | 1 | 0 | 0 | 1 | $38.00 | $38.00 | 1 available |
| Air Deflector - Porsche (964-564-005-01-70K)<br>964-564-005-01-70K | 1 | 0 | 0 | 1 | $472.00 | $472.00 | 1 available |
| Door Stop Lever<br>PO91153195700 | 1 | 0 | 0 | 1 | $80.00 | $80.00 | 1 available |
| Door Stay Reinforcement Kit - (each) - SKU# DH18<br>DH18 | 1 | 0 | 0 | 1 | $112.00 | $112.00 | 1 available |

| Description / Part # | Required | Finalized | On draft | Available | Unit price | Billable | Billing status |
|---|---|---|---|---|---|---|---|
| CERAKOTE Exhaust GLACIER SILVER C-7700 | 1 | 0 | 0 | 1 | $128.00 | $128.00 | 1 available |
| **Parts subtotal** | **19** | **0** | **0** | **19** | | **$1,593.00** | |

## Services Detail

| Description | Qty | Billable | Draft allocation | Billing status |
|---|---|---|---|---|
| Powder Coat and Cerakote | 1 | $1,000.00 | — | Available |
| Dry Ice Blast/Clean Engine and Suspension | 1 | $1,820.00 | — | Available |
| Fix and Paint front Fender from Accident match paint | 1 | $2,234.00 | — | Available |
| **Services subtotal** | **3** | **$5,054.00** | **$0.00** | |

*Draft allocation is the amount locked on a draft invoice at the time it was drafted; it can differ from the current billable price.*

## Separately Billable Labor

| Task | Billable logged hrs | Approved rate | Billable to date | Remaining est. hrs | Projected add'l billing | Classification |
|---|---|---|---|---|---|---|
| Steering wheel cleanup | 0.00 h | $145.00/h | $0.00 | 0.25 h | $36.25 | Billable (valued, not invoiced) |
| Adjust front light lens | 0.00 h | $145.00/h | $0.00 | 1.00 h | $145.00 | Billable (valued, not invoiced) |
| Final Exterior Prep | 0.00 h | $145.00/h | $0.00 | 2.00 h | $290.00 | Billable (valued, not invoiced) |
| Final Interior Clean | 1.00 h | $145.00/h | $145.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Engine Bay Cleanup | 0.00 h | $145.00/h | $0.00 | 1.00 h | $145.00 | Billable (valued, not invoiced) |
| CNC Front Jack Pad Adapters | 0.00 h | $145.00/h | $0.00 | 2.00 h | $290.00 | Billable (valued, not invoiced) |
| Re-install Hood Badge | 0.00 h | $145.00/h | $0.00 | 2.00 h | $290.00 | Billable (valued, not invoiced) |
| Install Skidplates | 2.00 h | $145.00/h | $290.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Repair Driver Front Mudflap | 2.00 h | $145.00/h | $290.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Touchup Paint on door Bottom (where tabs were sanded off) | 0.50 h | $145.00/h | $72.50 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Rewire Turbo Blanket on Pass Turbo | 0.25 h | $145.00/h | $36.25 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Touchup Decklid Grille Paint | 2.00 h | $145.00/h | $290.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Install Interior Door Panels and Pockets | 1.50 h | $145.00/h | $217.50 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Drain Oil and Seal Engine | 6.00 h | $145.00/h | $870.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Clean Engine Compartment and undercarriage for sale | 0.75 h | $145.00/h | $108.75 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Pull and Repaint Rear Decklid Grill | 4.00 h | $145.00/h | $580.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Put ATS1 on Lift to identify any Rusty/Bad Parts | 4.00 h | $145.00/h | $580.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Install Classic Windshield Wipers | 0.50 h | $145.00/h | $72.50 | 0.00 h | $0.00 | Billable (valued, not invoiced) |

| Task | Billable logged hrs | Approved rate | Billable to date | Remaining est. hrs | Projected add'l billing | Classification |
|---|---|---|---|---|---|---|
| Re-Powdercoat Door Sill Plates | 0.50 h | $145.00/h | $72.50 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Powder coat skid plate | 1.00 h | $145.00/h | $145.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Call ice blaster on Engine Bay | 1.00 h | $145.00/h | $145.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Fix Passenger Door Strap // Internal plate is broken, needs new strap mechanism | 4.00 h | $145.00/h | $580.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Repolish Shifter Knob | 1.50 h | $145.00/h | $217.50 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Cerakote Exhaust Twist-X, Pipes and Cookiecutter tips | 0.50 h | $145.00/h | $72.50 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Fix Sunroof deflector | 2.00 h | $145.00/h | $290.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| RePaint // Fender and Blend or full? | 2.00 h | $145.00/h | $290.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| **Labor subtotal (billable only)** | **37.00 h** | | **$5,365.00** | **8.25 h** | **$1,196.25** | |

| Projected Total Labor Billing | Amount |
|---|---|
| Labor billable to date | $5,365.00 |
| + Projected remaining labor | $1,196.25 |
| **= Projected total labor billing** | **$6,561.25** |

*Only labor classified Billable is valued. Service-included, non-billable and unclassified hours are not counted as additional labor revenue. Rates are not totaled.*

## Invoices

*No invoices recorded.*

## Financial Reconciliation

| Category | Current billable | Projected additional | Projected total |
|---|---|---|---|
| Parts | $1,593.00 | — | $1,593.00 |
| Services | $5,054.00 | — | $5,054.00 |
| Labor | $5,365.00 | $1,196.25 | $6,561.25 |
| **TOTAL** | **$12,012.00** | **$1,196.25** | **$13,208.25** |

| Invoice position (Parts & Services only) | Amount |
|---|---|
| Finalized invoiced | $0.00 |
| Paid | $0.00 |
| Outstanding | $0.00 |
| Allocated to drafts | $0.00 |
| **Available to invoice** | **$6,647.00** |

*Projected totals are estimates and are not amounts currently payable. Labor is valued but not yet invoiced.*