ATS1 // Accident Fixes

Client: Dan Martenson · Project ID: D3DF0328 · VIN/Chassis: — · Generated: Nov 4, 2026, 10:10 AM CT

Financial Summary

Measure	Amount
Current Project Value	
Parts billable	$1,593.00
Services billable	$5,054.00
Separately billable labor to date (valued, not yet invoiced)	$5,365.00
Total current billable	**$12,012.00**
Projected Value (estimate)	
Remaining estimated billable labor	$1,196.25
Total projected project value	**$13,208.25**
Invoice Position	
Finalized invoiced	$0.00
Paid	$0.00
Outstanding	$0.00
Allocated to drafts	$0.00
Parts & Services available to invoice	**$6,647.00**
Parts & Services Profitability (internal)	
Estimated Parts & Services cost	$4,613.31
Estimated gross profit	$2,033.69
Estimated gross margin	**30.6%**

Current project value is not the amount currently invoice-eligible. Separately billable labor is valued but not yet supported by the invoicing workflow. Projected labor is an estimate of future work, not completed work.

Parts Detail

Description / Part #	Required	Finalized	On draft	Available	Est. cost (ext.)	Actual cost (ext.)	Unit sale price	Billable	Billing status
911/964/993 Oval Door Plug 999 703 345 400 1C	4	0	0	4	$8.00	Not recorded	$4.00	$16.00	4 available
SEM Low VOC Undercoating SEM 40523	3	0	0	3	$67.77	Not recorded	$40.00	$120.00	3 available
T25/T28 Turbo Blanket - Lava FPRO35-028-01	1	0	0	1	$179.95	Not recorded	$270.00	$270.00	1 available
WIX Oil Filter - WL10109 WL10109	1	0	0	1	$39.02	Not recorded	$62.00	$62.00	1 available
Liqui Moly MoS2 Antifriction SAE 10W-40 P000207	3	0	0	3	$140.40	Not recorded	$75.00	$225.00	3 available
Bosch Classic Wiper Blades - Spectrum Direct Fit 13 Inch C1301	2	0	0	2	$39.98	Not recorded	$35.00	$70.00	2 available
Victor Reinz 70-31414-40 Reinzosil RTV Silicone - 310 ml Tube 70-31414-40	1	0	0	1	$21.80	Not recorded	$38.00	$38.00	1 available
Air Deflector - Porsche (964-564-005-01-70K) 964-564-005-01-70K	1	0	0	1	$337.00	Not recorded	$472.00	$472.00	1 available
Door Stop Lever PO91153195700	1	0	0	1	$50.00	Not recorded	$80.00	$80.00	1 available
Door Stay Reinforcement Kit - (each) - SKU# DH18 DH18	1	0	0	1	$70.00	Not recorded	$112.00	$112.00	1 available
CERAKOTE Exhaust GLACIER SILVER C-7700	1	0	0	1	$80.00	Not recorded	$128.00	$128.00	1 available
Parts subtotal	**19**	**0**	**0**	**19**	**$1,033.92**			**$1,593.00**	

Estimated and actual cost are extended (quantity × unit cost). Unit sale price is the per-unit billing price; unit prices are not totaled.

Services Detail

Description	Qty	Est. cost	Actual cost	Billable	Draft allocation	Billing status
Powder Coat and Cerakote	1	$695.00	Not recorded	$1,000.00	—	Available
Dry Ice Blast/Clean Engine and Suspension	1	$1,400.00	Not recorded	$1,820.00	—	Available
Fix and Paint front Fender from Accident match paint	1	$1,484.39	Not recorded	$2,234.00	—	Available
Services subtotal	**3**	**$3,579.39**	**Not recorded**	**$5,054.00**	**$0.00**	

Draft allocation is the amount locked on a draft invoice at the time it was drafted; it can differ from the current billable price.

Labor Detail

Task	Billable logged hrs	Approved rate	Billable to date	Remaining est. hrs	Projected add'l billing	Classification
Steering wheel cleanup	0.00 h	$145.00/h	$0.00	0.25 h	$36.25	Billable (valued, not invoiced)
Adjust front light lens	0.00 h	$145.00/h	$0.00	1.00 h	$145.00	Billable (valued, not invoiced)
Final Exterior Prep	0.00 h	$145.00/h	$0.00	2.00 h	$290.00	Billable (valued, not invoiced)
Final Interior Clean	1.00 h	$145.00/h	$145.00	0.00 h	$0.00	Billable (valued, not invoiced)
Engine Bay Cleanup	0.00 h	$145.00/h	$0.00	1.00 h	$145.00	Billable (valued, not invoiced)
CNC Front Jack Pad Adapters	0.00 h	$145.00/h	$0.00	2.00 h	$290.00	Billable (valued, not invoiced)
Re-install Hood Badge	0.00 h	$145.00/h	$0.00	2.00 h	$290.00	Billable (valued, not invoiced)
Install Skidplates	2.00 h	$145.00/h	$290.00	0.00 h	$0.00	Billable (valued, not invoiced)
Repair Driver Front Mudflap	2.00 h	$145.00/h	$290.00	0.00 h	$0.00	Billable (valued, not invoiced)
Touchup Paint on door Bottom (where tabs were sanded off)	0.50 h	$145.00/h	$72.50	0.00 h	$0.00	Billable (valued, not invoiced)
Rewire Turbo Blanket on Pass Turbo	0.25 h	$145.00/h	$36.25	0.00 h	$0.00	Billable (valued, not invoiced)
Touchup Decklid Grille Paint	2.00 h	$145.00/h	$290.00	0.00 h	$0.00	Billable (valued, not invoiced)
Install Interior Door Panels and Pockets	1.50 h	$145.00/h	$217.50	0.00 h	$0.00	Billable (valued, not invoiced)
Drain Oil and Seal Engine	6.00 h	$145.00/h	$870.00	0.00 h	$0.00	Billable (valued, not invoiced)
Clean Engine Compartment and undercarriage for sale	0.75 h	$145.00/h	$108.75	0.00 h	$0.00	Billable (valued, not invoiced)
Pull and Repaint Rear Decklid Grill	4.00 h	$145.00/h	$580.00	0.00 h	$0.00	Billable (valued, not invoiced)
Put ATS1 on Lift to identify any Rusty/Bad Parts	4.00 h	$145.00/h	$580.00	0.00 h	$0.00	Billable (valued, not invoiced)
Install Classic Windshield Wipers	0.50 h	$145.00/h	$72.50	0.00 h	$0.00	Billable (valued, not invoiced)
Re-Powdercoat Door Sill Plates	0.50 h	$145.00/h	$72.50	0.00 h	$0.00	Billable (valued, not invoiced)
Powder coat skid plate	1.00 h	$145.00/h	$145.00	0.00 h	$0.00	Billable (valued, not invoiced)
Call ice blaster on Engine Bay	1.00 h	$145.00/h	$145.00	0.00 h	$0.00	Billable (valued, not invoiced)
Fix Passenger Door Strap // Internal plate is broken, needs new strap mechanism	4.00 h	$145.00/h	$580.00	0.00 h	$0.00	Billable (valued, not invoiced)
Repolish Shifter Knob	1.50 h	$145.00/h	$217.50	0.00 h	$0.00	Billable (valued, not invoiced)
Cerakote Exhaust Twist-X, Pipes and Cookiecutter tips	0.50 h	$145.00/h	$72.50	0.00 h	$0.00	Billable (valued, not invoiced)
Fix Sunroof deflector	2.00 h	$145.00/h	$290.00	0.00 h	$0.00	Billable (valued, not invoiced)
RePaint // Fender and Blend or full?	2.00 h	$145.00/h	$290.00	0.00 h	$0.00	Billable (valued, not invoiced)
Labor subtotal (billable only)	**37.00 h**		**$5,365.00**	**8.25 h**	**$1,196.25**	

Projected Total Labor Billing	Amount
Labor billable to date	$5,365.00
+ Projected remaining labor	$1,196.25
= Projected total labor billing	**$6,561.25**

Internal labor costs are not configured; labor margin is not calculated. Only labor classified Billable is valued. Service-included, non-billable and unclassified hours are not counted as additional labor revenue. Rates are not totaled.

Invoices

No invoices recorded.

Financial Reconciliation

Category	Current billable	Projected additional	Projected total
Parts	$1,593.00	—	$1,593.00
Services	$5,054.00	—	$5,054.00
Labor	$5,365.00	$1,196.25	$6,561.25
TOTAL	**$12,012.00**	**$1,196.25**	**$13,208.25**

Invoice position (Parts & Services only)	Amount
Finalized invoiced	$0.00
Paid	$0.00
Outstanding	$0.00
Allocated to drafts	$0.00
Available to invoice	**$6,647.00**

Invoice position covers Parts & Services only. Labor is valued but not yet supported by the invoicing workflow and is not included in available-to-invoice.