# 24_9078_Pravi 1976 RSR

Client: Pravi Thakkar · Project ID: 89966A36 · VIN/Chassis: RSR · Generated: Nov 4, 2026, 10:10 AM CT

Billing detail for review only. This is not an invoice and creates no payment obligation. Previously invoiced amounts are historical. Projected amounts are estimates, not amounts currently payable.

## Financial Summary

| Measure | Amount |
|---|---|
| **Current Project Value** | |
| Parts billable | $25,249.54 |
| Services billable | $2,839.27 |
| Separately billable labor to date (valued, not yet invoiced) | $14,312.50 |
| **Total current billable** | **$42,401.31** |
| **Projected Value (estimate, not currently payable)** | |
| Remaining estimated billable labor | $0.00 |
| **Total projected project value** | **$42,401.31** |
| **Invoice Position** | |
| Finalized invoiced (historical) | $28,332.80 |
| Paid | $22,242.53 |
| Outstanding | $5,808.28 |
| Allocated to drafts | $0.00 |
| **Parts & Services available to invoice** | **$254.00** |

*Current project value is not the amount currently invoice-eligible. Separately billable labor is valued but not yet supported by the invoicing workflow. Projected labor is an estimate of future work, not completed work.*

## Parts Detail

| Description / Part # | Required | Finalized | On draft | Available | Unit price | Billable | Billing status |
|---|---|---|---|---|---|---|---|
| Front Tow Hooks and Tie Downs (set of 2)<br>E03 | 1 | 0 | 0 | 1 | $254.00 | $254.00 | 1 available |
| Oil Temperature Sensor 1976<br>901-641-632-00 | 1 | 1 | 0 | 0 | $108.00 | $108.00 | 1 finalized |
| Spacer Rose for Window Crank<br>901-552-891-20-OEM | 2 | 2 | 0 | 0 | $13.00 | $26.00 | 2 finalized |
| Bosch Classic Wiper Blades - Spectrum Direct Fit 13 Inch<br>C1301 | 2 | 2 | 0 | 0 | $35.00 | $70.00 | 2 finalized |
| VHT SP739 Brake Caliper Spray Paint - Satin Black - 11 oz Aerosol Can<br>VHT SP739 | 1 | 1 | 0 | 0 | $28.00 | $28.00 | 1 finalized |
| REAR 16" Classic Windshield Wiper Arm<br>911 628 613 01 | 2 | 2 | 0 | 0 | $11.00 | $22.00 | 2 finalized |
| Belt Alternator 964 9.5 X 776<br>999-192-338-50-M100 | 1 | 1 | 0 | 0 | $42.00 | $42.00 | 1 finalized |
| Belt Alternator 964 9.5 X 760 (SMALLER)<br>999-192-343-51 | 1 | 1 | 0 | 0 | $46.00 | $46.00 | 1 finalized |
| Obeaming 50W 12V USB Outlet Dual 25W USB-C Charger PD 3.0 Aluminum Fast Charging Socket<br>B0FLJNSVC4 | 1 | 1 | 0 | 0 | $28.00 | $28.00 | 1 finalized |

| Description / Part # | Required | Finalized | On draft | Available | Unit price | Billable | Billing status |
|---|---|---|---|---|---|---|---|
| Porsche Trunk Lid Buffer - Rubber hood stop<br>99970303650 | 2 | 2 | 0 | 0 | $5.00 | $10.00 | 2 finalized |
| URO Rubber Door Plug<br>99970304050 | 10 | 10 | 0 | 0 | $4.00 | $40.00 | 10 finalized |
| Wing Screw for Electrical Panel Cover<br>900-029-102-02-M350 | 1 | 1 | 0 | 0 | $7.00 | $7.00 | 1 finalized |
| Porsche DME Relay - 911 84-89<br>911-618-154-01<br>911.618.154.01--URO | 1 | 1 | 0 | 0 | $36.00 | $36.00 | 1 finalized |
| Wehrle 91461830311, 54201102 Turn Signal/Flasher Relay; 4 Prong - Porsche \| 111953227D 191953227A 1H0953227 90161830300 91461830311 | 1 | 1 | 0 | 0 | $44.00 | $44.00 | 1 finalized |
| Bulb Socket for Dashboard Instruments<br>99963200700 | 2 | 2 | 0 | 0 | $11.00 | $22.00 | 2 finalized |
| Rennline Fully Mechanical Hood Strut<br>E187 | 1 | 1 | 0 | 0 | $165.00 | $165.00 | 1 finalized |
| Steering Hub Spacer 12mm<br>B0DSJ9XT8F | 1 | 1 | 0 | 0 | $19.00 | $19.00 | 1 finalized |
| Momo Horn Button Retainer Plate | 1 | 1 | 0 | 0 | $19.00 | $19.00 | 1 finalized |
| VictorReinz 99311119500, 712495330 Exhaust Manifold Gasket; Seal Ring - Porsche \| 93112319500 94411120506 99311119400 W01331641252 99311119500 | 5 | 5 | 0 | 0 | $9.00 | $45.00 | 5 finalized |
| 911 // Window Vent Seal Fixed - Right<br>901-542-922-21 | 1 | 1 | 0 | 0 | $197.00 | $197.00 | 1 finalized |
| Window Frame Mount Bracket - Pair<br>91154206100KT | 1 | 1 | 0 | 0 | $54.00 | $54.00 | 1 finalized |
| RCA Plug Splitter 2 Male to 4 Female Y Adapter<br>B0BS1HVXS5 | 1 | 1 | 0 | 0 | $46.00 | $46.00 | 1 finalized |
| RCA Level Controller Volume Control<br>B099VXYM7Q | 1 | 1 | 0 | 0 | $23.00 | $23.00 | 1 finalized |
| Porsche Racing Style Rubber Tie-Downs for Front Hood TRE PEL H36 PEL.H36 PELH36 \| Pelican Parts PELH36 | 1 | 1 | 0 | 0 | $80.00 | $80.00 | 1 finalized |
| Odometer Gear, 20x30 Tooth Gear<br>ODO-POR-20-30 | 1 | 1 | 0 | 0 | $40.00 | $40.00 | 1 finalized |
| Porsche Plastic Door Plug Set of 14<br>9997031194014HBT | 1 | 1 | 0 | 0 | $37.00 | $37.00 | 1 finalized |
| Porsche Window Channel Guide - Felt<br>91154290500 | 2 | 2 | 0 | 0 | $60.00 | $120.00 | 2 finalized |
| Porsche Plastic Expansion Rivet<br>99959142940 | 2 | 2 | 0 | 0 | $4.00 | $8.00 | 2 finalized |
| Porsche Window Frame to Door Seal - Right Rear<br>9115317140101C | 1 | 1 | 0 | 0 | $18.00 | $18.00 | 1 finalized |
| Porsche Window Frame to Door Seal - Left Rear<br>9115317130101C | 1 | 1 | 0 | 0 | $18.00 | $18.00 | 1 finalized |
| Window frame to door seal, front left<br>9115317110201C | 1 | 1 | 0 | 0 | $22.00 | $22.00 | 1 finalized |
| Window frame to door seal, front right<br>9115317120201C | 1 | 1 | 0 | 0 | $13.00 | $13.00 | 1 finalized |

| Description / Part # | Required | Finalized | On draft | Available | Unit price | Billable | Billing status |
|---|---|---|---|---|---|---|---|
| Gauge bezels alloy Porsche 911<br>911680AB911 | 1 | 1 | 0 | 0 | $136.00 | $136.00 | 1 finalized |
| Blower Control Cable Clamping Bolt<br>90121168300 | 3 | 3 | 0 | 0 | $13.00 | $39.00 | 3 finalized |
| 1.5 inch Automotive Air Duct Hose, Length 1 Meter<br>B0DXKV5M4Q | 2 | 2 | 0 | 0 | $42.00 | $84.00 | 2 finalized |
| Dansk Original 90121100822, 1623200280 HVAC Heater Control Box; Black Aluminized Steel; Right SKU: 1433482-JP-90121100822 - Porsche \| JP17480<br>JP90121100822 | 2 | 2 | 0 | 0 | $225.00 | $450.00 | 2 finalized |
| Porsche Heater Cable Guide Tube<br>90142470401 | 2 | 2 | 0 | 0 | $35.00 | $70.00 | 2 finalized |
| DOOR LATCH BOWDEN CABLE SUPPORT // RS<br>91153109700 | 2 | 2 | 0 | 0 | $78.00 | $156.00 | 2 finalized |
| 911 964 993 Door Handle Lever Bowden Cable<br>993.531.509.00 | 2 | 2 | 0 | 0 | $64.00 | $128.00 | 2 finalized |
| 911 DOOR LATCH RELAY LEVER // RS Update<br>911.531.083.00 | 2 | 2 | 0 | 0 | $35.00 | $70.00 | 2 finalized |
| 911 Hot Air Hose - Engine to Heat Exchanger<br>91121155300 | 4 | 4 | 0 | 0 | $25.00 | $100.00 | 4 finalized |
| 4x6 Speaker // Infinity Kappa 463XF<br>108K463XF | 1 | 1 | 0 | 0 | $475.00 | $475.00 | 1 finalized |
| Rennline Lower Shift Boot for Porsche 964/993 (1989-1994) - OE Style Replacement<br>I143 | 1 | 1 | 0 | 0 | $88.00 | $88.00 | 1 finalized |
| Backdate Dash Panels // Custom<br>AK_BackdateDash | 1 | 1 | 0 | 0 | $800.00 | $800.00 | 1 finalized |
| Center Cap for Fuch Wheel (4)<br>90136103200 | 1 | 1 | 0 | 0 | $483.00 | $483.00 | 1 finalized |
| Heater Control Knob / Brake Area<br>JP91142479203 | 2 | 2 | 0 | 0 | $25.00 | $50.00 | 2 finalized |
| Parking Brake Lever setup 911<br>91142405115 | 1 | 1 | 0 | 0 | $225.00 | $225.00 | 1 finalized |
| AK Aero Bullet Mirror / Longhood<br>LongarmAeroMirror | 1 | 1 | 0 | 0 | $800.00 | $800.00 | 1 finalized |
| AK // Custom Porsche Decklid Grill<br>CustomDecklidGrill | 1 | 1 | 0 | 0 | $575.00 | $575.00 | 1 finalized |
| Parking Brake Lever Boot<br>92342459100 | 1 | 1 | 0 | 0 | $43.00 | $43.00 | 1 finalized |
| Porsche Three Connection Tie Bar For Fuse Box - 356/911/912 50-73<br>SMC-612-801-00<br>SMC.612.801.00 | 5 | 5 | 0 | 0 | $18.00 | $90.00 | 5 finalized |
| 2pcs 2.5 Inch Stainless 40-64mm\ Hose Clamp<br>B09XQ8RS7X | 10 | 10 | 0 | 0 | $11.00 | $110.00 | 10 finalized |
| Engine air duct. Porsche<br>96410640302<br>96410640302 | 1 | 1 | 0 | 0 | $168.00 | $168.00 | 1 finalized |

| Description / Part # | Required | Finalized | On draft | Available | Unit price | Billable | Billing status |
|---|---|---|---|---|---|---|---|
| Heating Pipe. Porsche 964 & 993 6-8 H P M o r e 'm 9 6 4 1 6 7 0 0 3<br>964167003 | 1 | 1 | 0 | 0 | $248.00 | $248.00 | 1 finalized |
| 9 Eleven Headlights / Raven<br>Raven S | 1 | 1 | 0 | 0 | $2,900.00 | $2,900.00 | 1 finalized |
| (New) 911/912/930 Fresh Air Controller Bowden Cable - 1965-89<br>91157211400 | 1 | 1 | 0 | 0 | $64.00 | $64.00 | 1 finalized |
| LEFT - Heater Control Box Hose Clamp with Cable Guide<br>90121105122 | 1 | 1 | 0 | 0 | $48.00 | $48.00 | 1 finalized |
| Right - Heater Control Box Hose Clamp with Cable Guide<br>90121105222 | 1 | 1 | 0 | 0 | $49.00 | $49.00 | 1 finalized |
| Car Air Intake Pipe, 2.5 inch | 2 | 2 | 0 | 0 | $18.00 | $36.00 | 2 finalized |
| 1.5 inch Automotive Air Duct Hose, Length 1 Meter<br>B0DXKV5M4Q | 2 | 2 | 0 | 0 | $42.00 | $84.00 | 2 finalized |
| Porsche 180A Alternator<br>LMA498 | 1 | 1 | 0 | 0 | $1,300.00 | $1,300.00 | 1 finalized |
| Electric Air Conditioning for Classic 911 (single condenser) AC<br>AC | 1 | 1 | 0 | 0 | $5,628.00 | $5,628.00 | 1 finalized |
| 911 Hot Air Hose - Engine to Heat Exchanger<br>91121155300 | 1 | 1 | 0 | 0 | $25.00 | $25.00 | 1 finalized |
| VUBT2 Universal Bluetooth 4.0 Audio Receiver<br>VUBT2 | 1 | 1 | 0 | 0 | $64.00 | $64.00 | 1 finalized |
| Sound Ordnance™ M75-4 Compact 4-channel car amplifier — 75 watts RMS x 4<br>M75-4 | 1 | 1 | 0 | 0 | $240.00 | $240.00 | 1 finalized |
| Porsche 911 S Coupe 911 2.7L H6 Heater Cable Wire<br>91142470101 | 2 | 2 | 0 | 0 | $25.00 | $50.00 | 2 finalized |
| RennShift Performance Shifter 901/915/930/914<br>RSOR-EX-BST-BK | 1 | 1 | 0 | 0 | $729.00 | $729.00 | 1 finalized |
| Porsche Bursch Stainless Steel 1-3/4 in Header Set W/ Heat Exchangers - 911<br>BX-9359-SS<br>BX.9359.SS | 1 | 1 | 0 | 0 | $3,123.06 | $3,123.06 | 1 finalized |
| Alternator bearing fan blade. Porsche 9 6 4 / 9 9 3 'm<br>96410605131 | 1 | 1 | 0 | 0 | $128.00 | $128.00 | 1 finalized |
| Porsche Windshield Moulding Joint (Black)<br>9115419210170K | 2 | 2 | 0 | 0 | $18.00 | $36.00 | 2 finalized |
| Porsche O.E.M. Windshield Moulding (Black)<br>9115419110170 | 1 | 1 | 0 | 0 | $138.00 | $138.00 | 1 finalized |
| Porsche Windshield Moulding (Black)<br>9115419120170K | 1 | 1 | 0 | 0 | $141.49 | $141.49 | 1 finalized |
| RED 4 Gauge OFC Wire (25ft) AWG Amp Battery Cable for Automotive Electrical Wiring - Oxygen Free Copper (OFC) Welding Cable 4GA - Car Amplifier Power & Ground...<br>B01MXRVIPD | 1 | 1 | 0 | 0 | $104.00 | $104.00 | 1 finalized |

| Description / Part # | Required | Finalized | On draft | Available | Unit price | Billable | Billing status |
|---|---|---|---|---|---|---|---|
| Intermittent wiper relay wiring harness. Porsche 911 'm 911612059 91161205902 | 1 | 1 | 0 | 0 | $107.00 | $107.00 | 1 finalized |
| Porsche 911 Door Threshold Side Sills Protectors Set BLACK FINISH 90155100010 | 1 | 1 | 0 | 0 | $218.00 | $218.00 | 1 finalized |
| Porsche Windshield Seal - URO Parts 91154122503 91154122503 | 1 | 1 | 0 | 0 | $120.00 | $120.00 | 1 finalized |
| 16AWG Speaker Wire, GearIT Pro Series 16 Gauge OFC Speaker Wire Cable (500 Feet / 152.4 Meters) B01MA6MPBB | 1 | 1 | 0 | 0 | $101.00 | $101.00 | 1 finalized |
| Wing Screw for Electrical Panel Cover 900-029-102-02-M350 | 1 | 1 | 0 | 0 | $7.00 | $7.00 | 1 finalized |
| HVAC Heater Control Cable Clip 90157191900 | 4 | 4 | 0 | 0 | $10.00 | $40.00 | 4 finalized |
| Blower Control Cable Clamping Bolt 90121168300 | 2 | 2 | 0 | 0 | $13.00 | $26.00 | 2 finalized |
| Door Panel // M4 x 25mm // Flat Phillips Head Screw 91698A728 | 2 | 2 | 0 | 0 | $1.00 | $2.00 | 2 finalized |
| 1974-1988 Porsche 911 Front Seat Belt Kit 5052 | 1 | 1 | 0 | 0 | $540.00 | $540.00 | 1 finalized |
| Porsche Intermittent Wiper Relay 911-618-149-02 | 1 | 1 | 0 | 0 | $210.00 | $210.00 | 1 finalized |
| 12AWG Speaker Wire, OFC 100 Feet B00HZWYJJO | 1 | 1 | 0 | 0 | $56.00 | $56.00 | 1 finalized |
| Black 4 Gauge OFC Wire (25ft) AWG Amp Battery Cable for Automotive Electrical Wiring - Oxygen Free Copper (OFC) Welding Cable 4GA - Car Amplifier Power & Ground Cable, Stereo Audio Speakers, RV Trailer Wiring B0C7HCY2LC | 1 | 1 | 0 | 0 | $75.00 | $75.00 | 1 finalized |
| Joinfworld Fused Power Distribution Block Car Audio 4 Way MIDI(Mini-ANL) Fuse Block 12V 0/4 Gauge with Ground for Auto UTV Boat Stereo Amp B0B3X9TB8G | 1 | 1 | 0 | 0 | $35.00 | $35.00 | 1 finalized |
| Focal Sub 10 Slim 10" shallow-mount 4-ohm voice coil subwoofer speaker SUB10SLIM | 2 | 2 | 0 | 0 | $448.00 | $896.00 | 2 finalized |
| SELTERM 4 AWG Gauge Copper Lug Terminal Ring Terminal Eyelet B0CS6LZQXC | 1 | 1 | 0 | 0 | $28.00 | $28.00 | 1 finalized |
| JBL Club A600 // Woofer Amp 109CL600A | 1 | 1 | 0 | 0 | $476.00 | $476.00 | 1 finalized |
| Focal Performance 130AC Access 5-1/4" coaxial speakers 130AC | 1 | 1 | 0 | 0 | $329.99 | $329.99 | 1 finalized |
| **Parts subtotal** | **145** | **144** | **0** | **1** | | **$25,249.54** | |

## Services Detail

| Description | Qty | Billable | Draft allocation | Billing status |
|---|---|---|---|---|
| Replace 4 Tires on RSR | 1 | $1,940.00 | — | Finalized |
| Four Wheel Alignment and A/C System Charge | 1 | $899.27 | — | Finalized |
| **Services subtotal** | **2** | **$2,839.27** | **$0.00** | |

*Draft allocation is the amount locked on a draft invoice at the time it was drafted; it can differ from the current billable price.*

## Separately Billable Labor

| Task | Billable logged hrs | Approved rate | Billable to date | Remaining est. hrs | Projected add'l billing | Classification |
|---|---|---|---|---|---|---|
| RSR Front Bumper Fix | 8.50 h | $125.00/h | $1,062.50 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Swap to 964 oil temp gauge | 0.25 h | $125.00/h | $31.25 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Engine Bay Vacumn Canister Fix | 0.25 h | $125.00/h | $31.25 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Change oil sender | 1.25 h | $125.00/h | $156.25 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Rust covert oil lines and paint | 1.50 h | $125.00/h | $187.50 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Add metal skid sleds | 0.25 h | $125.00/h | $31.25 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Driver door Pull Strap // Opening Shows (move handle up) | 0.50 h | $125.00/h | $62.50 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Order New Set of Tires for RSR | 0.25 h | $125.00/h | $31.25 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Test and Fix Fuel Low Light | 0.75 h | $125.00/h | $93.75 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Trace wire for oil temp gauge // Not reacting to temp increase | 3.00 h | $125.00/h | $375.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Idle Switch Adjust Stop | 0.25 h | $125.00/h | $31.25 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Touchup Undercoat (Rockers/Wheelwells/Misc) | 3.00 h | $125.00/h | $375.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Reinstall Clock/Oil Gauges | 0.25 h | $125.00/h | $31.25 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Scuff pad oil lines and corroded areas | 2.50 h | $125.00/h | $312.50 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Work with Classic Retrofit to Fix AC Intermitent | 4.00 h | $125.00/h | $500.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Fix Seat Belt Rattle | 0.25 h | $125.00/h | $31.25 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Install Engine Bay Cover Pieces | 0.25 h | $125.00/h | $31.25 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Make and Install Seatbelt guide behind Console | 2.00 h | $125.00/h | $250.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Wire up and test HORNS | 0.50 h | $125.00/h | $62.50 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Re-Glue Woven edges to panel & Re-VHB Driver door Trim | 1.00 h | $125.00/h | $125.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Polish Gauge Glass/Remove Scratches | 2.00 h | $125.00/h | $250.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |

| Task | Billable logged hrs | Approved rate | Billable to date | Remaining est. hrs | Projected add'l billing | Classification |
|---|---|---|---|---|---|---|
| Check why Tach Bounces (check 2nd ground wire) | 0.25 h | $125.00/h | $31.25 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Install rear bumper | 1.00 h | $125.00/h | $125.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Test and Fix Pass and Driver Pull Strap (too tight) | 1.00 h | $125.00/h | $125.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Install Front Lights | 2.00 h | $125.00/h | $250.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Build Front Lights | 2.00 h | $125.00/h | $250.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Cover Frunk Panels with Leather and Carpet | 1.25 h | $125.00/h | $156.25 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Repowdercoat Door Handle Plates | 2.00 h | $125.00/h | $250.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Touchup door sills | 0.25 h | $125.00/h | $31.25 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Order Grand Prix White | 0.10 h | $125.00/h | $12.50 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Final Muffler Install and Testing | 2.00 h | $125.00/h | $250.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Fix Rear Windshield | 0.50 h | $125.00/h | $62.50 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Fix Gas Cable | 1.00 h | $125.00/h | $125.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Rattle in Driver Door | 0.25 h | $125.00/h | $31.25 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Re-VHB Rear Bumper Trim | 1.00 h | $125.00/h | $125.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Alternator Light Comes on/off | 2.00 h | $125.00/h | $250.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Install main glass trim pieces | 0.50 h | $125.00/h | $62.50 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Install windshied wipers | 0.15 h | $125.00/h | $18.75 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Install Muffler | 1.00 h | $125.00/h | $125.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Clean and Touchup Brake Calipers | 1.00 h | $125.00/h | $125.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Replace door sills | 2.00 h | $125.00/h | $250.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Install rubber plugs for door frame bolts | 1.00 h | $125.00/h | $125.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Upholster and Install Front Seats | 8.00 h | $125.00/h | $1,000.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Make Appt for AC Charge and Alignment | 1.00 h | $125.00/h | $125.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Raise Ride Height by 1/2 inch | 2.50 h | $125.00/h | $312.50 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Install Final Frunk Panels | 2.00 h | $125.00/h | $250.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Pull Rear Seat Delete and Fix Bumps | 1.50 h | $125.00/h | $187.50 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Paint Horn Grill Backer/Fender Black | 1.25 h | $125.00/h | $156.25 | 0.00 h | $0.00 | Billable (valued, not invoiced) |

| Task | Billable logged hrs | Approved rate | Billable to date | Remaining est. hrs | Projected add'l billing | Classification |
|---|---|---|---|---|---|---|
| Finish Audio Wiring | 3.00 h | $125.00/h | $375.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Install Door Seals | 0.50 h | $125.00/h | $62.50 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Order RSR Porsche Badge for hood | 1.00 h | $125.00/h | $125.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Fix Shorted Wire for Driver Turn Circuit | 20.00 h | $125.00/h | $2,500.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Build Rear Taillights | 1.00 h | $125.00/h | $125.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Touchup Paint | 2.00 h | $125.00/h | $250.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Install Raven S Headlights | 1.00 h | $125.00/h | $125.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| INSTALL Door Stop Custom Mechanisms | 2.00 h | $125.00/h | $250.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| INSTALL Gauges and Test | 1.00 h | $125.00/h | $125.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Reinstall Windshield | 2.00 h | $125.00/h | $250.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Door Panel Installation | 2.00 h | $125.00/h | $250.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Install Rear Lights | 2.00 h | $125.00/h | $250.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Final Test/Confirm Function of Electric AC | 2.00 h | $125.00/h | $250.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| Mold and Build // Rear Splitter for Install | 4.00 h | $125.00/h | $500.00 | 0.00 h | $0.00 | Billable (valued, not invoiced) |
| **Labor subtotal (billable only)** | **114.50 h** | | **$14,312.50** | **0.00 h** | **$0.00** | |

| Projected Total Labor Billing | Amount |
|---|---|
| Labor billable to date | $14,312.50 |
| + Projected remaining labor | $0.00 |
| **= Projected total labor billing** | **$14,312.50** |

*Only labor classified Billable is valued. Service-included, non-billable and unclassified hours are not counted as additional labor revenue. Rates are not totaled.*

## Invoices

| Invoice | Type | Status | Issue date | Total | Paid | Balance due |
|---|---|---|---|---|---|---|
| INV_3073 | progress | sent | 2026-08-25 | $6,090.27 | $0.00 | $5,808.28 |
| Invoice 3043 | progress | paid | | $2,083.00 | $2,083.00 | $0.00 |
| Invoice 3043 | progress | paid | | $10,331.53 | $10,331.53 | $0.00 |
| 446125 | progress | paid | | $9,828.00 | $9,828.00 | $0.00 |

## Financial Reconciliation

| Category | Current billable | Projected additional | Projected total |
|---|---|---|---|
| Parts | $25,249.54 | — | $25,249.54 |
| Services | $2,839.27 | — | $2,839.27 |
| Labor | $14,312.50 | $0.00 | $14,312.50 |
| **TOTAL** | **$42,401.31** | **$0.00** | **$42,401.31** |

| Invoice position (Parts & Services only) | Amount |
|---|---|
| Finalized invoiced | $28,332.80 |
| Paid | $22,242.53 |
| Outstanding | $5,808.28 |
| Allocated to drafts | $0.00 |
| **Available to invoice** | **$254.00** |

*Projected totals are estimates and are not amounts currently payable. Labor is valued but not yet invoiced.*