ATS1 // Accident Fixes

Client: Dan Martenson VIN / Chassis: — Project ID: 695e7e2885f6d1c4d3df0328
Generated: 11/4/2026, 9:32:04 AM (Central) Report: Billing Detail — Not an Invoice

This document is a billing detail for review. It is not an invoice and creates no payment obligation. Previously invoiced amounts are shown for reference only.

Financial summary

Measure	Amount
Parts billable (current)	$1,593.00
Services billable (current)	$5,054.00
Labor billable to date (valued, not invoiced)	$5,365.00
Total current billable	$12,012.00
Projected remaining labor	$1,196.25
Total projected billable	$13,208.25
Already finalized / invoiced (historical)	$0.00
Outstanding balance on finalized invoices	$0.00
Allocated to draft invoices	$0.00
Parts & Services available to invoice	$6,647.00

Parts

Part	Part #	Qty	Finalized	On draft	Available	Unit price	Billable	Status
911/964/993 Oval Door Plug	999 703 345 400 1C	4	0	0	4	$4.00	$16.00	4 available
SEM Low VOC Undercoating	SEM 40523	3	0	0	3	$40.00	$120.00	3 available
T25/T28 Turbo Blanket - Lava	FPRO35-028-01	1	0	0	1	$270.00	$270.00	1 available
WIX Oil Filter - WL10109	WL10109	1	0	0	1	$62.00	$62.00	1 available
Liqui Moly MoS2 Antifriction SAE 10W-40	P000207	3	0	0	3	$75.00	$225.00	3 available
Bosch Classic Wiper Blades - Spectrum Direct Fit 13 Inch	C1301	2	0	0	2	$35.00	$70.00	2 available
Victor Reinz 70-31414-40 Reinzosil RTV Silicone - 310 ml Tube	70-31414-40	1	0	0	1	$38.00	$38.00	1 available
Air Deflector - Porsche (964-564-005-01-70K)	964-564-005-01-70K	1	0	0	1	$472.00	$472.00	1 available
Door Stop Lever	PO91153195700	1	0	0	1	$80.00	$80.00	1 available
Door Stay Reinforcement Kit - (each) - SKU# DH18	DH18	1	0	0	1	$112.00	$112.00	1 available
CERAKOTE Exhaust GLACIER SILVER	C-7700	1	0	0	1	$128.00	$128.00	1 available
Parts subtotal							**$1,593.00**	

Services

Service	Qty	Billable	On draft	Status
Powder Coat and Cerakote	1	$1,000.00	—	Available
Dry Ice Blast/Clean Engine and Suspension	1	$1,820.00	—	Available
Fix and Paint front Fender from Accident match paint	1	$2,234.00	—	Available
Services subtotal		**$5,054.00**		

Separately billable labor (valued, not yet invoice-eligible)

Task	Billable hrs	Rate	Billable to date	Remaining hrs	Projected add'l	Classification
Steering wheel cleanup	0.00 h	$145.00/h	$0.00	0.25 h	$36.25	Billable — valued, not invoiced
Adjust front light lens	0.00 h	$145.00/h	$0.00	1.00 h	$145.00	Billable — valued, not invoiced
Final Exterior Prep	0.00 h	$145.00/h	$0.00	2.00 h	$290.00	Billable — valued, not invoiced
Final Interior Clean	1.00 h	$145.00/h	$145.00	0.00 h	$0.00	Billable — valued, not invoiced
Engine Bay Cleanup	0.00 h	$145.00/h	$0.00	1.00 h	$145.00	Billable — valued, not invoiced
CNC Front Jack Pad Adapters	0.00 h	$145.00/h	$0.00	2.00 h	$290.00	Billable — valued, not invoiced
Re-install Hood Badge	0.00 h	$145.00/h	$0.00	2.00 h	$290.00	Billable — valued, not invoiced
Install Skidplates	2.00 h	$145.00/h	$290.00	0.00 h	$0.00	Billable — valued, not invoiced
Repair Driver Front Mudflap	2.00 h	$145.00/h	$290.00	0.00 h	$0.00	Billable — valued, not invoiced
Touchup Paint on door Bottom (where tabs were sanded off)	0.50 h	$145.00/h	$72.50	0.00 h	$0.00	Billable — valued, not invoiced
Rewire Turbo Blanket on Pass Turbo	0.25 h	$145.00/h	$36.25	0.00 h	$0.00	Billable — valued, not invoiced
Touchup Decklid Grille Paint	2.00 h	$145.00/h	$290.00	0.00 h	$0.00	Billable — valued, not invoiced
Install Interior Door Panels and Pockets	1.50 h	$145.00/h	$217.50	0.00 h	$0.00	Billable — valued, not invoiced
Drain Oil and Seal Engine	6.00 h	$145.00/h	$870.00	0.00 h	$0.00	Billable — valued, not invoiced
Clean Engine Compartment and undercarriage for sale	0.75 h	$145.00/h	$108.75	0.00 h	$0.00	Billable — valued, not invoiced
Pull and Repaint Rear Decklid Grill	4.00 h	$145.00/h	$580.00	0.00 h	$0.00	Billable — valued, not invoiced
Put ATS1 on Lift to identify any Rusty/Bad Parts	4.00 h	$145.00/h	$580.00	0.00 h	$0.00	Billable — valued, not invoiced
Install Classic Windshield Wipers	0.50 h	$145.00/h	$72.50	0.00 h	$0.00	Billable — valued, not invoiced
Re-Powdercoat Door Sill Plates	0.50 h	$145.00/h	$72.50	0.00 h	$0.00	Billable — valued, not invoiced
Powder coat skid plate	1.00 h	$145.00/h	$145.00	0.00 h	$0.00	Billable — valued, not invoiced
Call ice blaster on Engine Bay	1.00 h	$145.00/h	$145.00	0.00 h	$0.00	Billable — valued, not invoiced
Fix Passenger Door Strap // Internal plate is broken, needs new strap mechanism	4.00 h	$145.00/h	$580.00	0.00 h	$0.00	Billable — valued, not invoiced
Repolish Shifter Knob	1.50 h	$145.00/h	$217.50	0.00 h	$0.00	Billable — valued, not invoiced
Cerakote Exhaust Twist-X, Pipes and Cookiecutter tips	0.50 h	$145.00/h	$72.50	0.00 h	$0.00	Billable — valued, not invoiced
Fix Sunroof deflector	2.00 h	$145.00/h	$290.00	0.00 h	$0.00	Billable — valued, not invoiced

Task	Billable hrs	Rate	Billable to date	Remaining hrs	Projected add'l	Classification
RePaint // Fender and Blend or full?	2.00 h	$145.00/h	$290.00	0.00 h	$0.00	Billable — valued, not invoiced
Labor subtotal	**37.00 h**		**$5,365.00**	**8.25 h**	**$1,196.25**	

Invoice summary

Invoice	Type	Status	Issue date	Total	Paid	Balance due

Total selected billable scope

Measure	Amount
Parts	$1,593.00
Services	$5,054.00
Labor billable to date	$5,365.00
Total current billable	$12,012.00
Total projected billable	$13,208.25
Already invoiced (historical, not newly payable)	$0.00
Allocated to drafts	$0.00
Parts & Services available to invoice	$6,647.00