

BP7S Function

Note: Api call must be serial call, that is, after the end of a Api, you can call the next Api, otherwise it will appear Api function failure.



BP7S Function A - Setting Before Offline Measurement

Note: BP7S (A-1) must be called before using the offline measurement function of Api, otherwise the time of the off-line data may be incorrect.




A-1: commandFounction: errorBlock:

A-2: commandSetUnit: errorBlock:


A-3: commandSetAngle: errorBlock:

BP7S Function B – Upload Offline Data



B-1: commandTransferMemoryDataWithUser: clientID:


BP7S Function C -Query Function



C-1: commandFounction: errorBlock:

C-2: commandEnergy: errorBlock:

BP7S Function D -Disconnect Device



D-1: commandDisconnectDevice