

HS3 Function

Note: serial call Api calls must be, that is, when the end of an Api, can call an Api, Otherwise it will appear the Api function failure.




Note: the three functions of parallel relationship, there is no order

HS3 Function A On-line measurement and get offline data




A-1: commandInitWithUser:Authentication: TransferMemorryData: UploadDataNum: DisposeProgress: MemorryData: FinishTransmission: StableWeight: DisposeErrorBlock:

HS3 Function B TurnOnBTConnectAuto



B-1: commandTurnOnBTConnectAutoResult: DisposeErrorBlock:

HS3 Function C TurnOffBTConnectAuto



C-1: commandTurnOffBTConnectAutoResult DisposeErrorBlock: