Monitor PMT linearity vs PD current

Fit: $y = ax + b$
$a = 0.322 \pm 0.026$
$b = -2.27 \pm 0.21$
Data (Monitor PMT)

X-axis: PD current [pA]
Y-axis: Monitor PMT Max-Min [V]