Version	A0
Material Code	200515005870



Technical requirements:

1. Wiring should be connected firmly according to the diagram.
2. Soldering should be neat and tidy.
3. Crimping should be secure.
4. The wire harness can pass through only one wire connected to the electronic connector.
5. The terminal clamp should be tightly crimped and cannot fall out.
6. The ribbon cable support board must be tightly attached to prevent it from loosening.

Wiring diagram

	Connect or A																							
	1	2	3	4	5	6	7	8	9	10	11	12	13	14	15	16	17	18	19	20	21	22	23	24
Connect or B	1	2	3	4																				
					1	2																		
							7+8+9			10+11+12														
Connect or C													1	2										
Connect or D															1	2	3	4	5					
Connect or E																				1	2	3		
Connect or F																							1	2

Design	Liu Ye	2023.1.11	Shenzhen jiexinhua technology co., ltd				material	
check							model	JXHSV06P
approve			Phase marker quantity		weight	proportion	figure number	JXHSV06P-08001-g
	A total The first	one		1			name	Adapter-motherboard connection line