



P.O. BOX 180
VULCAN, ALBERTA
T0L 2B0

TELEPHONE: 1-403-485-2241
TOLL FREE: 1-877-485-2299
FAX: 1-403-485-2920
www.vulcancounty.ab.ca

VC FILE: 2026-04

May 19, 2026

Alan Duguid
119 Mt Assiniboine Cir SE Calgary, AB T2Z 2N7
Email: atduguid@shaw.ca

Re: Information Request – Fire Report - Travers Solar

I am responding to your records request received on May 13, 2026. The request was for general information, and we are in receipt of the \$25 fee.

We have retrieved the Incident and Investigation Reports for the March 7, 2026 fire that originated at the Travers Solar Farm. The following information was redacted from the record that can be released (see attached):

- Third party information (ATIA S. 19)
- Personal information (ATIA S. 20)

If you have any questions regarding the record, please let me know.

Sincerely,

A handwritten signature in black ink, appearing to read 'Nels Petersen'.

Nels Petersen
Chief Administrative Officer / Acting Access and Privacy Officer
cao@vulcancounty.ab.ca
403-485-2241

Public Disclosure Report

Incident Number VCES-26-0065
Incident Date 03/07/2026 15:26:08
Exposure 000

Address #SE_17_15_20_W4,
81520***2101 OR CMD2 IN
COMMAND
VULCAN COUNTY

Location Type Street address
Cross Street

Incident type	143 Grass fire	Actions Taken	Resources	Sup.	EMS	Other
Incident Begin Time	03/07/2026 15:26:08	Extinguishment by fire service personnel	Apparatus	11	0	2
Controlled		Fire control or extinguishment, other	Personnel	27	0	2
Incident End Time	03/07/2026 18:15:05	Contain fire (wildland)				

Property Details

Non Residential
Residential Units 0
Buildings Involved 0
Acres Burned < One
Acres Burned 0

On-Site Materials or Products

Storage Use

Property Use

Electric-generating plant
Mixed Use Property

Hazmat Released

None

Pre Values

Property \$ **Contents \$**

Losses

Property \$ **Contents \$**

Fire Origin Open area, outside; included are
farmland, field
Heat Source Electrical [REDACTED]
Item First Ignited Light vegetation - not crop, including
grass
Material First Ignited Plastic

Cause of Ignition

Factors Contributing to Ignition

Equipment Involved

Brand
Model
Serial
No
Year

Mobile Property Involved

Mobile Property Type
Make
VIN
#
Year
Model
Business Owner
License Plate # **State**

Equipment Power Source

Equipment Portable

Fire Suppression Factors

Officer in Charge

Tompkins

Rank/Position

District Chief/

Incident Summary: March 7, 2026, I, as on-call Chief, was made aware of a possible wildland fire southwest of Lomond at the Solar Farm. A member from Lomond Fire was going to investigate, and as he was leaving Lomond identified a large working fire in the vicinity of the Solar Farm. At that time, he asked for additional resources to be toned out. The exact location was confirmed as the Solar Farm on the south side of HWY 529 and RGE Rd 205. Unit(s) Assigned: Units from Station 19, Station 27, Station 21, Station 20, Station 17 were requested to respond with all wildland units and tenders. Upon arrival at the scene, the following conditions were observed: Location: The fire originated in the grassy area of the southwest side solar farm. Size of Fire: The fire was approximately [X acres/hectares] in size at the time of arrival. Fire Behavior: The fire was exhibiting fast-moving behavior. When I arrived on scene, it had already jumped RGE RD 205 and had already moved through the second section of solar panels to the East of RGE RD 205. Fire on the south end was moving more slowly and had not yet crossed RGE RD 205. Weather Conditions: The weather at the time of the incident was extremely windy. Topography/Access: The terrain was difficult to manage as we were unable to access the grounds around the solar farm. It was very tall, dead grass, with slight hills. Time of Day: The incident occurred during mid-afternoon. Actions Taken: Initial Assessment: After arriving, I assessed the situation and confirmed that I would need additional personnel and apparatus, so I requested Mutual Aid from Enchant and Picture Butte for their Tenders and Rapids. A unit from Vauxhall showed up, but it wasn't requested. Fire Suppression Actions: I assigned 3 Rapid units to the head of the fire on the East side of RGE RD 205. All tender units were staged at a set of grain bins east of RGE RD 205. At that time, RDFC [REDACTED] Wyatt arrived on scene, and I assigned him to the west side RGE RD 205 as sector chief. Safety Measures: It was challenging as the crew was unable to access the solar farm until the operator arrived. It was also difficult to access the fire, so crews waited and fought the fire once it reached the fence line. Containment Actions: Once the operator of the Solar Farm arrived, we were able to access inside the fence and contain the fire from spreading. Cooperation with Other Agencies: The response involved mutual aid from Enchant and Picture Butte Fire, as well as a unit from Vauxhall. Fire Behavior Monitoring: Throughout the response, fire behavior was monitored using on-the-ground observation. Outcome: The fire was called loss stop by 17:31:11. The fire size at termination was estimated at [X acres/hectares]. Conclusion: The incident was cleared, and all units returned to service. The fire did not result in any fatalities, and the damage to structures was minimal. No injuries to fire department personnel were reported. The fire was managed and contained in accordance with standard wildland fire protocols Follow-up Required: RFC will be conducting an investigation by drone for the size of the fire next week. This report is complete to the best of my knowledge [REDACTED] Tompkins Chief, Champion Fire Department Chief on Call Last edited by Tompkins, [REDACTED] at 03/08/2026 12:24:08 tend17 / tend17 Narrative Apparatus Narratives DISPATCH & RESPONSE Water Tender 17 was dispatched to provide water supply support at near lomond for a reported wildfire. The initial call indicated low water supply and tenders. Water Tender 17 responded with one personnel. Upon arrival at water supply point, Water Tender 17 was assigned to supply water to vulcan tender for filling of units. The crew immediately began positioning the unit to ensure continuous water flow for firefighting efforts. INITIAL ACTIONS & WATER SUPPLY ESTABLISHMENT Water Source Identified: tenders and portable tank at site Water Tender Operations Initiated: Water shuttle operation began with 4 tenders on scene to ensure a continuous flow of water. Water Tender 17 was tasked with supplying water to vulcan tender. SUPPORT OPERATIONS & FIRE SUPPRESSION Ongoing Water Supply: Continuous water flow provided to vulcan tender for rapid and engine water fills INCIDENT CONTROL & TERMINATION Water Supply Controlled: Water Tender 17 continued providing support until fire was marked under control. Termination of Water Tender Operations: Water Tender 17 was released from scene

rapid27

Incident Summary: At approximately ____15:38____ on ____March 7, 2026____, Vulcan County Emergency Services was requested to provide mutual aid assistance to Champion Fire Department with wildfire, The request was made by Champion Fire. The incident occurred at Travers Solar Farm. Rapid 27 responder with 3 members. Upon arrival, we reported to Champion 21-01, and responded accordingly to directions.

tend2101

Incident Summary: At approximately 15:30 on March 7th, Tender 21 was dispatched to a Wildland Fire in the area of Travers solar farm. Fire Suppression Actions: When Tender 21 arrived on scene, we were advised to head south on Range Road 205. Approximately 500 ft down Range Road 205, we encountered fast-moving flames threatening the nearby solar array. FF Ellis and PFF Payne began attacking the fire using a 38 mm hose line and hand tools. Shortly after, the flames were extinguished. Rapid 21 arrived at our location, and DC

Dahl advised us to continue south on Range Road 205 and begin suppression operations in the nearby ditches. Suppression was initially attempted using the apparatus-mounted turret; however, this was unsuccessful. FF Ellis and PFF Payne then stretched a hose reel line and began suppressing hotspots. Approximately 30 minutes later, Tender 21 required a water refill. Upon reaching the water sector, we were informed that the fire had been contained. DC Tompkins requested all units rendezvous at the water sector. After a final briefing, Tender 21 was cleared from the scene by Command. Conclusion: The incident was cleared at approximately 18:30, and all units returned to service. The fire did not result in any fatalities, and the damage to structures was minimal. No injuries to fire department personnel were reported. The fire was managed and contained in accordance with standard wildland fire protocols Signed, FF. [REDACTED] Ellis

rapid19

Incident Summary: At approximately __15:29__ on __March 7 2026__, Station __19__ was dispatched to a Wildland Fire in the area of the travers solar project . The call was reported to district chief by a passer by and rapid 19 STOKES and WEST went to investigate with Rapid 19. Rapid 19 got to the corner of hi way 845 and hi way 529 and called it in requesting a response from stations 20, 21, and 27 The exact location was confirmed as starting in the solar panels on the SE 7-15-20 W4 and going across the gravel range road 205 to 8-15-20 W4 and going through the solar panels on the NW 1/4 of the section running through the field making it into W 9-15-20 W4. Unit(s) Assigned: Rapid 19 arrived on scene and went to the head of the fire to stop and slow the spread of the fire. rapid 20 was the next driving unit and followed the same attack mode going to the head of the fire to stop and slow the spread. tender 27 arrived on scene and set the water point at the half way mark along the hi way of 529 in section 8-15-20. [REDACTED] showed up with a blade tractor and pushed a containment ridge along the edge of the fire. 20-01 arrived on scene and 19-02 handed command over Initial Conditions/Scene Overview: Upon arrival at the scene, the following conditions were observed: a very aggressive wildfire with multiple fingers running as multiple heads. the fire was aggressively burning through the solar project as the fuel levels inside the project were dry and high in volume. outside the project the file volume was less and was able to run fast but with not a lot of heat. Location: The fire was located in The exact location was confirmed as starting in the solar panels on the SE 7-15-20 W4 and going across the gravel range road 205 to 8-15-20 W4 and going through the solar panels on the NW 1/4 of the section running through the field making it into W 9-15-20 W4. Size of Fire: The fire was approximately 60 acres in size at the time of arrival but was also very dense low smoke and hard to tell. Fire Behavior: The fire was exhibiting a running fast moving fire. Weather Conditions: The weather at the time of the incident was approximately 10 above and winds out of the WSW with sustained 40 km gusting to 60. Topography: The terrain was solar panel project and running into a relatively flat crop land field with pea stubble. the area was quite soft and muddy making it difficult to move around. Access: to the solar panels was gated off but was able to get in once the [REDACTED] opened the gates. Time of Day: the incident occurred during the mid afternoon. Citizen/Incident Needs: The fire posed the following immediate threats to people and property: Structures/Property Threatened: the solar project panels and wiring were affected and threatened. harming some of the wiring but no infrastructure was actually burned to my knowledge. Evacuations: none Injuries or Health Concerns: wild land smoke exposures and some exposures to smoke from unidentified solar panels and wire that were being burned or exposed to flame. Actions Taken: Initial Assessment: Upon arrival, personnel assessed the situation and confirmed that the fire was running fast and hard to the east and the main 2 concerns were to stop the spread of the wild fire before it became to large to handle. and the second concern was to stop the spread inside of the solar project, but the protocol for fighting fire in there is to let the fire come to us until there is a representative there. Fire Suppression Actions: Firefighting personnel engaged in suppression efforts using a rapid truck with a hand-line strung through the cab for water conservation. Safety Measures: Firefighters maintained safety measures including staying away from the electrical lines in the solar project. . Air Operations: none Containment Actions: The fire was contained by extinguishing the fire with water and a containment dozer line with later disk help was created around the wild fire. Cooperation with Other Agencies: The response involved mutual aid from picture butte and enchant. as well as all Vulcan County assets Fire Behavior Monitoring: Throughout the response, fire behavior was monitored using on the ground observations Outcome: The fire was contained at approximately __17:40__ hours and fully controlled by __17:55__. The fire size at termination was estimated at 160ac in my estimations. size will be droned later Conclusion: The incident was cleared at approximately __17:59__, and all units returned to service. The fire did not result in any fatalities, and the damage to structures is undetermined but appears minimal. No injuries to fire department personnel were reported. The fire was managed and contained in accordance with standard wildland fire protocols Notes: was challenging to get access to the project and was difficult to sit and watch the fire burn up to the roads to then contain it. nobody called it in. rapid 19 went on a smoke investigation and found it and called it in although bystanders were present. [REDACTED] showed up with a dozer blade towed by a tractor, a disk and tractor , and a water truck. [REDACTED]

showed up with a tractor and water tank too Follow-up Required: FC 2 and other officers will contact the solar project to determine damages, cause, and size

rapid21

DISPATCH & RESPONSE At , 15:46 Rapid Unit 21, a pickup truck with a skid pack, was dispatched to assist Lomond Fire with a wildland fire at the Travers solar farm. The initial call indicated there was a fast moving stubble fire approaching the solar farm. Rapid Intervention Unit 21 responded with 5 personnel, including DC Dahl, FF Van Klei, JFF Van Klei, FF Luffman and FF Neufeld, and was equipped with CET wildland skid pack , 200-250-gallon tank, Pump Capacity: 265gpm at 50psi, 190gpm at 100psi, 115gpm at 150psi and 45gpm at 200psi. pump and wildland hand tools. While en route, DC Dahl contacted incident command and received an assignment for rapid intervention and deployment per NFPA 1500. Upon arrival, Rapid Intervention Unit 21 positioned itself at RR205 south of highway 529 to assist with fire suppression. **INITIAL ACTIONS & UNIT DEPLOYMENT** Assigned Role: Rapid Intervention Unit 21 was tasked with fire suppression, on the south side of the incident and was to keep the fire from crossing RR205. Wildland Fire Operations: Unit 21 engaged in initial attack using the skid pack pump to apply water or foam to the fire's edge, protecting exposures such as vital infrastructure from ember intrusion. Hand Tools deployed for line construction and mopping up hot spots along fire perimeter, particularly in the areas with solar panels due to them being energized. Water Application: Utilized hose line size 5/8" and 1" or handline to suppress the fire and cool hot spots. **ACTIVE INTERVENTION & SUPPORT** Fire Suppression Efforts: Rapid Unit 21 used its skid pack to deliver water or foam to targeted areas, reducing fire spread, especially in areas inaccessible to larger apparatus. Hotspot extinguishment continued around high-risk areas like outbuildings, vehicles, or brush that posed a threat to surrounding structures. Rapid 21 worked along the south flank of the fire and around the west end, extinguishing as we went. 2 members from Rapid 21 followed behind with hand tools and completed mop up as we went. this was continued until full fire suppression was acheved. Firefighter Rescue and Safety: If needed, Unit 21 provided support to a Rapid Intervention Team (RIT) or acted as a first responder in case of firefighter injury or distress Search & Rescue (SAR) operations: Assisted with quickly locating any downed firefighter or personnel at risk, using basic extrication tools, or providing immediate medical care. Hazardous Materials or Vehicle Accident: The unit assisted with scene safety and initial hazard assessment, providing spill containment or fire control for vehicles involved in hazardous materials incidents. Deployed fire suppression tactics using the skid pack in case of fire caused by accident, or directed hazardous materials personnel to manage the scene. **INCIDENT CONTROL & FIREGROUND SAFETY** Termination of Operations: At approximately 18:00, the fire was under control, and Rapid Intervention Unit 21 was released from active firefighting duties. The unit transitioned to rehabilitation operations or standby for additional calls. **AFTER ACTION & TERMINATION** Units Cleared Scene at approximately 18:00, returning to service or awaiting additional assignments. Debrief completed with personnel at the incident water staging area, reviewing actions taken, safety protocols, and any lessons learned.

eng2704

Incident Summary: At approximately 15:30 on March 7 . Station 27 was dispatched to a Wildland Fire in the area of Lomond's district. The call was received from 911 dispatch. Unit(s) Assigned: Engine 274 from Station 27 **Initial Conditions/Scene Overview:** Upon arrival at the scene, the following conditions were observed: **Location:** The fire was located in solar farm **Size of Fire:** The fire was approximately 10 acres in size at the time of arrival. **Fire Behavior:** The fire was exhibiting fast moving grass fire **Weather Conditions:** The weather at the time of the incident was Windy from the south west. **Topography:** The terrain was flat. **Access:** fenced solar arrays with limited access due to continuous power to solar panels. **Time of Day:** The incident occurred during afternoon. **Citizen/Incident Needs:** The fire posed the following immediate threats to people and property: **Structures/Property Threatened:** solar panels and power cables **Actions Taken:** **Initial Assessment:** Upon arrival, personnel assessed the situation and confirmed that the fire was spreading through solar farm arrays. **Fire Suppression Actions:** Firefighting personnel engaged in suppression efforts using Type 3 engine. on arrival on scene, Engine 274 reported to water sector and awaited assignment. Given the task of protecting the road passing through the middle of a solar array. Using a handline, Engine 274 applied water to road and grass on the south side to prevent fire spread. Also extinguished any fire that made to to the road. Crew was informed by IC not to apply water on solar cells or to leave the road to extinguish fires due to risk of electrocution. Engine 274 then refilled with water from water sector then patrolled with FC03 looking for hot spots. **Safety Measures:** Firefighters maintained safety measures including appropriate gear, staying clear of smoke when possible. **Containment Actions:** The fire was contained by wildland units **Cooperation with Other Agencies:** The response involved mutual aid from outside agencies **Fire Behavior Monitoring:** Throughout the response, fire behavior was monitored using on ground observations The incident was cleared at approximately 1800, and all units returned to service. The fire did not result in any fatalities, and the damage to

structures was unknown. No injuries to fire department personnel were reported. The fire was managed and contained in accordance with standard wildland fire protocols

vcmd2

Units were dispatched to the Travers Solar Farm for a reported running grass fire. While en route, a large plume of grey/white smoke was visible from Vulcan. Initial arriving units reported a large, fast-moving grass fire originating within the solar farm compound and spreading beyond the perimeter fence. The fire had crossed Range Road 205 and was spreading rapidly to the northeast and had entered another section of solar panels as well as an open stubble field. Upon arrival, District Chief Tomkins had established command. I was directed to manage suppression operations on the west side of Range Road 205. Significant activity was present on the roadway with both civilian vehicles and fire apparatus operating in the area. A tractor equipped with a disc was operating in a stubble field east of Range Road 205. At the time of arrival there was no representation from the solar facility on scene. Fire crews were actively working to extinguish flames along Range Road 205 and had begun moving inside the solar farm fencing. I instructed crews not to operate between the solar panel rows, as all solar equipment was considered live and presented an electrical hazard. Vegetation under the solar arrays consisted of dry, cured grass approximately 2–3 feet in height. Grass had been mowed between panel rows but remained unmowed directly beneath the panels. Weather conditions at the time included west winds at approximately 35 km/h with gusts to 52 km/h, temperature of 17°C, and relative humidity of 33%, contributing to rapid fire spread. I conducted a drive-around of the west side of the solar farm and observed fire actively spreading among the panel arrays and advancing north and west. Crews were instructed to remain on the solar farm access roads and focus suppression efforts on preventing fire from crossing the access roads into adjacent panel arrays. Additional resources were requested to my location, and crews were able to stop fire spread across the access roads, preventing extension into additional solar arrays. Active fire remained visible and audible in the central portion of the southwest array; however, crews were not sent beyond the first set of cables between panel rows due to electrical hazards. Solar company employees later arrived on scene with dry chemical extinguishers. They crawled beneath the cable runs and worked to extinguish remaining flames within the panel rows. Fire department crews continued extinguishment of hotspots where access was safe and feasible. Once the fire perimeter was contained, Chief Tomkins directed all units to return to the water supply point located just off Highway 529. I then accompanied Chief Tomkins in Support 1 to conduct a full drive-around of the incident area to confirm there were no remaining hotspots. One area of smoldering material was located during this check. Chief Tomkins released all remaining units except Rapid 275. Rapid 275 and I responded to the hotspot location and extinguished the remaining smoldering areas. Rapid 275 was then cleared from the scene. Following suppression activities, I met with solar facility employees to discuss the possible origin of the fire. They reported [REDACTED]

[REDACTED] Further investigation is required to determine the cause. Based on visual assessment of the burn area, it is estimated that approximately 160 acres of grassland were burned. Complications, There were several complications that were noted, the tall dry cured vegetation underneath the panels caused rapid fire spread, the above ground wiring restricted crew movement between the panels, the panels themselves restrict visibility making it tougher to detect fire location, and the panels change the wind patterns and cause unpredictable fire behavior, such as fire spread up wind or lateral to the predominant wind direction. This report is complete to the best of my knowledge. [REDACTED] Wyatt

rapid17

Incident Summary: At approximately ____4pm____ on March 7, Station ____17____ was dispatched to a Wildland Fire in the area of [describe d as crop and grassland]. Actions Taken: Upon arrival initially attached hot spots on the north east flank of the fire. Moved to range road 205 ditches on second and third tank. Fire Suppression Actions: Firefighting personnel engaged in suppression efforts using First two tanks used the monitor for fire attach, third tank used the hose reel for sod fire suppression Safety Measures: Firefighters maintained safety measures including personal protective equipment , safety zones, establishing escape routes, etc. . Containment Actions: The bulk of the fire was contained by farmer supplied disc Conclusion: The incident was cleared at approximately ____6.pm____, and all station 17 units returned to service. The fire did not result in any fatalities, the fire was managed and contained in accordance with standard wildland fire protocols Notes: Third fill [REDACTED] Godkin come in the rapid 17 and ran hose reel putting out hot spot in ditch.

tend19

DISPATCH & RESPONSE At [16:34], Water Tender [19] was dispatched to provide water supply support at SE 17-15-20 for a reported Solar farm/wildland fire. The initial call indicated water support was needed as they had a fast moving wildland fire, nearest hydrant was at the sheep lot north west of the fires location where a hydrant was accessible. Water Tender 19 responded with 1 personnel. While en route, [REDACTED] west, district

deputy Chief confirmed the need for a water shuttle operation per NFPA 1142 based on where the fire was spreading at a rapid rate and essential need for all available water as the fire was moving at a fast speed and looked to be about 100 acres. Upon arrival at 16:44, Water Tender 19 was assigned to hold a position at the fill point where tender 27 had a porta tank dropped for us to fill. The crew immediately began positioning the unit to ensure continuous water flow for firefighting efforts. INITIAL ACTIONS & WATER SUPPLY ESTABLISHMENT Water Source Identified: Hydrant North west of the fill point location and the sheep lot Water Tender Operations Initiated: Tender 19 dumped one load of water in the porta tank and filled again at the fill point where no more water was needed. SUPPORT OPERATIONS & FIRE SUPPRESSION Tank Refill Operations: Water Tender 19 was rotated with additional tenders to maintain an uninterrupted water supply. Tender 19 filled the porta tank so tender 27 could be stationary and continue flow to rapids. Coordination with Fire Suppression Teams: Communication maintained with Incident Command and fire attack units to ensure water was effectively directed to high-priority areas. INCIDENT CONTROL & TERMINATION Water Supply Controlled: Water Tender 19 continued providing support until fire was marked under control at 16:30. Termination of Water Tender Operations: At 1800, Water Tender 19 was released from water supply operations and returned to staging for rehydration/maintenance. AFTER ACTION & TERMINATION Command Terminated at 1800, transferring control to private owners/company. All units cleared the scene at [HH:MM], returning to service. Debrief completed with personnel at 1800 at the water fill point where all units were relieved to go back to respected stations.

sup01

Incident Summary: March 7, 2026, I, as on-call Chief, was made aware of a possible wildland fire southwest of Lomond at the Solar Farm. A member from Lomond Fire was going to investigate, and as he was leaving Lomond identified a large working fire in the vicinity of the Solar Farm. At that time, he asked for additional resources to be toned out. The exact location was confirmed as the Solar Farm on the south side of HWY 529 and RGE Rd 205. Unit(s) Assigned: Units from Station 19, Station 27, Station 21, Station 20, Station 17 were requested to respond with all wildland units and tenders. Upon arrival at the scene, the following conditions were observed: Location: The fire originated in the grassy area of the southwest side solar farm. Size of Fire: The fire was approximately [X acres/hectares] in size at the time of arrival. Fire Behavior: The fire was exhibiting fast-moving behavior. When I arrived on scene, it had already jumped RGE RD 205 and had already moved through the second section of solar panels to the East of RGE RD 205. Fire on the south end was moving more slowly and had not yet crossed RGE RD 205. Weather Conditions: The weather at the time of the incident was extremely windy. Topography/Access: The terrain was difficult to manage as we were unable to access the grounds around the solar farm. It was very tall, dead grass, with slight hills. Time of Day: The incident occurred during mid-afternoon. Actions Taken: Initial Assessment: After arriving, I assessed the situation and confirmed that I would need additional personnel and apparatus, so I requested Mutual Aid from Enchant and Picture Butte for their Tenders and Rapids. A unit from Vauxhall showed up, but it wasn't requested. Fire Suppression Actions: I assigned 3 Rapid units to the head of the fire on the East side of RGE RD 205. All tender units were staged at a set of grain bins east of RGE RD 205. At that time, RDFC [REDACTED] Wyatt arrived on scene, and I assigned him to the west side RGE RD 205 as sector chief. Safety Measures: It was challenging as the crew was unable to access the solar farm until the operator arrived. It was also difficult to access the fire, so crews waited and fought the fire once it reached the fence line. Containment Actions: Once the operator of the Solar Farm arrived, we were able to access inside the fence and contain the fire from spreading. Cooperation with Other Agencies: The response involved mutual aid from Enchant and Picture Butte Fire, as well as a unit from Vauxhall. Fire Behavior Monitoring: Throughout the response, fire behavior was monitored using on-the-ground observation. Outcome: The fire was called loss stop by 17:31:11. The fire size at termination was estimated at [X acres/hectares]. Conclusion: The incident was cleared, and all units returned to service. The fire did not result in any fatalities, and the damage to structures was minimal. No injuries to fire department personnel were reported. The fire was managed and contained in accordance with standard wildland fire protocols Follow-up Required: RFC will be conducting an investigation by drone for the size of the fire next week. This report is complete to the best of my knowledge [REDACTED] Tompkins Chief, Champion Fire Department Chief on Call

Rapid20

Incident Summary: At approximately _1530_____ on ___7 Mar 2026_____, Station __20__ was dispatched to a Wildland Fire to assist Lomond Fire in the area of Travers Solar farm. The call was received from 911 center. The exact location was confirmed as SE17-15-20 W4. Unit(s) Assigned: Rapid 20 from Station __20__, Stations 19, 21, 27, 17, Enchant, Vauxhall, and Picture Butte__ responded to the scene with wildland firefighting equipment Type 1 engine, water tenders, and rapid trucks. Initial Conditions/Scene Overview: Upon arrival at the scene, the following conditions were observed: Location: The fire was located in

within the solar panels and on the surrounding grassland. Size of Fire: The fire was numerous acres in size at the time of arrival. Fire Behavior: The fire was running with the wind, some flames and numerous hot spots. Weather Conditions: The weather at the time of the incident was warm, cloudy and very windy from the SW. Topography: The terrain was grassland and stubble field, rolling hills. Access: Off then highway. Solar panels were located within a fenced area with limited gate access. Time of Day: The incident occurred during daytime. Actions Taken: Initial Assessment: Upon arrival, personnel assessed the situation and confirmed that the fire was running ahead of the wind threatening to jump the highway. Tractor and dics were working to control the head of the fire. Fire Suppression Actions: Firefighting personnel engaged in suppression efforts using hand tools, water suppression and water tenders. Safety Measures: Firefighters maintained safety measures including remaining in the black and behind the wind, wearing wildland apparel. Containment Actions: The fire was contained by farmer discers, and fire apparatus wet line. Cooperation with Other Agencies: Neighboring fire departments. Outcome: The fire was contained at approximately __1800__ hours and fully controlled by __1830____. The fire size at termination was estimated at 15 acres. Conclusion: The incident was cleared at approximately _____, and all units returned to service. The fire did not result in any fatalities, and the damage to structures was [minimal/significant]. No injuries to fire department personnel were reported. The fire was managed and contained in accordance with standard wildland fire protocols Notes: Rapid 20 responded with one and picked up a Lomond member at the scene of the fire and then moved to suppression efforts on the southside of the fire. Running through one tank of water we were reassigned to the western road to control the fire moving out of the solar panels to the west. Refilling once again, we were tasked into the western portion of the solar panels to contain the fire that was coming up to an access road. When fire was extinguished was returned to command point and received a debrief and where then released from scene. The above is a true and accurate account to the best of my knowledge, [REDACTED] McDonnell Captain Champion Fire Department

tend17

DISPATCH & RESPONSE Water Tender 17 was dispatched to provide water supply support at near lomond for a reported wildfire. The initial call indicated low water supply and tenders. Water Tender 17 responded with one personnel. Upon arrival at water supply point, Water Tender 17 was assigned to supply water to vulcan tender for filling of units. The crew immediately began positioning the unit to ensure continuous water flow for firefighting efforts. INITIAL ACTIONS & WATER SUPPLY ESTABLISHMENT Water Source Identified: tenders and portable tank at site Water Tender Operations Initiated: Water shuttle operation began with 4 tenders on scene to ensure a continuous flow of water. Water Tender 17 was tasked with supplying water to vulcan tender. SUPPORT OPERATIONS & FIRE SUPPRESSION Ongoing Water Supply: Continuous water flow provided to vulcan tender for rapid and engine water fills INCIDENT CONTROL & TERMINATION Water Supply Controlled: Water Tender 17 continued providing support until fire was marked under control. Termination of Water Tender Operations: Water Tender 17 was released from seen

rapid2705

Incident Summary: Station 27 was dispatched to assist Station 19 with a Wildland Fire in the area of Travers Solar Project. The call was received from the dispatch center. The exact location was confirmed as SE-17-15-20W4 Rapid 274 responded with 4 members. Myself (District Deputy Chief [REDACTED] Schmeelke), FF [REDACTED] Wiebe, Probationary Firefighter [REDACTED] Schneider, and JrFF [REDACTED] Earl. Initial Conditions/Scene Overview: Upon arrival at the scene, the following conditions were observed: Location: The fire was located in a pea stubble field south of the solar farm on both sides of RR205. Fire Behavior: The fire was fast moving driven by a south west wind. Topography: The terrain was grassland inside the solar farm with adjacent farm fields of standing stubble. Access: No access issues to the fields but entrance inside the fence for the solar farm was restricted until units were cleared by IC Time of Day: The incident occurred during [daytime/nighttime]. Citizen/Incident Needs: The fire posed the following immediate threats the solar panels within the fenced area of the solar farm. Structures/Property Threatened: [Describe any structures, infrastructure, or communities at risk, e.g., homes, cabins, power lines]. Actions Taken: Initial Assessment: Upon arrival, Rapid 275 was assigned fire suppression on the south side of the solar farm east of RR205. Rapid 275 members worked near and along the south fence line under what was later established as South Division Command. Fire Suppression Actions: Firefighting personnel engaged in suppression efforts using hand lines and hand tools. Once suppression in our assigned area was completed Rapid 275 was reassigned under the command of FC3 Regional Deputy Chief [REDACTED] Wyatt where we were assigned to check for hot spots within the solar farm and hot spot extinguishing along RR205 in the ditch. Rapid 275 remained on hot spot extinguishment until released from scene by IC. Rapid 275 returned to Station 27 and was placed in service. This report is completed to the best of my knowledge. [REDACTED] Schmeelke.

tend27

DISPATCH & RESPONSE At 1529hrs, Water Tender 27 was dispatched to provide water supply support at LL (50.2887,-112.711) for a reported wildfire. The initial call indicated significant fire activity spreading from the field into the solar panel farm. Water Tender 27 responded with 2 personnel, including Lt.Dick & CPO.Trudel. While en route, 20-01 confirmed the need for a water shuttle operation per NFPA 1142 based on dispatch information & 360 size-up. Upon arrival, Water Tender 27 was assigned to provide water supply as well to assume water sector command. The crew immediately began positioning the units and porta tanks to ensure continuous water flow for firefighting efforts. INITIAL ACTIONS & WATER SUPPLY ESTABLISHMENT Water Source Identified: Dry hydrant located west of the sheep barn, tenders from Vulcan county (27,17,19), tenders from Enchant & Vauxall, tender from Picture Butte and a water truck from local hutterite colony. Water Tender Operations Initiated: Yes (Porta tanks x2 dropped/filled) Water shuttle operation began with 7 tenders on scene to ensure a continuous flow of water. Relay pumping established from WEST of SHEEP BARN. Water Tender 27 and one tender from MD of Taber were tasked with supplying water to suppression units. Water flow rate was stabilized, ensuring an effective supply for firefighting operations. guidelines were followed to ensure proper hose placement, pressure, and safety during the water relay. SUPPORT OPERATIONS & FIRE SUPPRESSION Ongoing Water Supply: Continuous water flow provided to rapid units for fire suppression efforts at solar farm. Coordination with Fire Suppression Teams: Communication maintained with Incident Command and fire attack units to ensure water was effectively directed to high-priority areas. INCIDENT CONTROL & TERMINATION Water Supply Controlled: Water Tender 27 continued providing support until fire was marked under control at 1900hrs. Termination of Water Tender Operations: At 1900hrs, Water Tender 27 was released from water supply operations. Tender 27 cleared scene returning to station, in service. AFTER ACTION & TERMINATION Command Terminated at 1900hrs, transferring control to property owners. All units cleared the scene at approx.; 1900hrs, returning to service. No further action required / Incident referred to investigator to follow up. CH NFAR LT.Dick

Declaration

I declare under penalty of perjury under the laws of the State that the foregoing information is true and correct.

Reporting Officer

██████ Tompkins

Rank/Position

District Chief/

Date

2026-04-22 14:54:46



Vulcan County Emergency Services

FIRE INVESTIGATION REPORT

FIRE INVESTIGATION
102 Center St - Po Box 180
Vulcan AB T0L 2B0
403 485 3123

Electrical VCES-26-0065

Location: Vulcan County Alberta

Incident Information

- **Incident Name:** Axium Solar Farm Fire
- **Incident Number:** VCES-26-0065
- **Fire Investigator:** [REDACTED] Headrick
- **Date:** March 7 2026
- **Time Reported:** 15:26:08
- **Time Arrived on Scene:**
- **Reporting Agency/Department:** 15:32:06
- **Weather Conditions:**
 - Temperature: -17 degrees Celsius
 - Wind Speed/Direction: 35Kmh Gusting to 52Kmh from West
 - Humidity: 33%
 - Barometric Pressure: 100.1 KPA and rising

Location Details

- **Solar Facility Name:** Axium Solar Farm
- **Nearest City/Town:** Village of Lomond
- **Access Route:** Range Road 210
- **Legal Land:** SE 17 15 20 W4
- **Terrain:**
 - Grassland / Prairie
 - Rolling / Flat
 - Gravel access roads
- **Vegetation/Fuel Type:**
 - Dry prairie grass
 - Pea stubble

Incident Description

- **Type of Fire:** Fire was called into District chief of Lomond station who asked his members to go out for a smoke investigation. As the members approached the solar farm they confirmed it was a working grass fire and requested multiple alarms be struck.
 - Grass fire under panels
 - Electrical equipment fire
- **Estimated Size of Fire:** The estimated size of the fire was roughly 150 acres of both grass land and pea stubble.
- **Structures/Equipment Involved:**
 - Electrical wiring

Incident #: VCES-25-0062

Investigator: [REDACTED] Headrick

Date of Fire: March 25, 2025



Vulcan County Emergency Services

FIRE INVESTIGATION REPORT


FIRE INVESTIGATION
102 Center St - Po Box 180
Vulcan AB T0L 2B0
403 485 3123

Electrical VCES-26-0065

- Fire Behavior Observed:
 - Rapid spread through dry grass
 - Wind-driven flame front
 - Spotting in grassland

4. Probable Cause

- [REDACTED]



Detailed Notes: The most probable cause of the fire was determined to be the [REDACTED]
[REDACTED]
[REDACTED] leading to rapid fire spread due to wind being in excess of 60kmh.

Response

Initial Units Dispatched: Stations 19, 20, 27, 21, 17, Enchant and picture Butte

Resources Used

Incident #: VCES-25-0062

Investigator: [REDACTED] Headrick

Date of Fire: March 25, 2025



Vulcan County Emergency Services

FIRE INVESTIGATION REPORT

FIRE INVESTIGATION
102 Center St - Po Box 180
Vulcan AB T0L 2B0
403 485 3123

Electrical VCES-26-0065

- Structural engines
- Brush trucks
- Water tenders
- Wildland crews

Fire Suppression Actions

- Grass fire attack with brush trucks
- Establish fire guard along solar rows
- Direct attack with water/foam
- Protect inverter/transformer stations

Challenges Encountered

- High winds typical of southern Alberta prairie in excess of 60KmH
- Limited access between panel rows
- Electrical hazards from energized equipment
- Dry grass fuels beneath panels
- Large, fenced facility trouble knowing where Apparatus needed to respond

Damage Assessment

- Area Burned (acres/hectares): 150 Acres of grassland and pea stubble
- Solar Panels Damaged: 5 panels sustained scorching but did not melt or ignite
- Inverter Stations Damaged: None
- Transformers Damaged: None
- Perimeter Fence Damage: metal fence no damage

Estimated Loss: \$25,000 As per Axium infrastructure manager.

Injuries / Safety

- **Firefighter Injuries:** NIL
- **Civilian Injuries:** NIL
- **Safety Concerns:**
 - Electrical hazard
 - Smoke exposure
 - Wind-driven

Environmental Impact

- Grassland habitat burned
- Soil scorching beneath arrays

Incident #: VCES-25-0062

Investigator: [REDACTED] Headrick

Date of Fire: March 25, 2025



Vulcan County Emergency Services

FIRE INVESTIGATION REPORT

FIRE INVESTIGATION
102 Center St - Po Box 180
Vulcan AB T0L 2B0
403 485 3123

Electrical VCES-26-0065

Incident Commander Summary

Incident Summary:

March 7, 2026, I, as on-call Chief, was made aware of a possible wildland fire southwest of Lomond at the Solar Farm. A member from Lomond Fire was going to investigate, and as he was leaving Lomond identified a large working fire in the vicinity of the Solar Farm. At that time, he asked for additional resources to be toned out. The exact location was confirmed as the Solar Farm on the south side of HWY 529 and RGE Rd 205.

Unit(s) Assigned: Units from Station 19, Station 27, Station 21, Station 20, Station 17 were requested to respond with all wildland units and tenders.

Upon arrival at the scene, the following conditions were observed:

Location: The fire originated in the grassy area of the southwest side solar farm.

Size of Fire: The fire was approximately [X acres/hectares] in size at the time of arrival.

Fire Behavior: The fire was exhibiting fast-moving behavior. When I arrived on scene, it had already jumped RGE RD 205 and had already moved through the second section of solar panels to the East of RGE RD 205. Fire on the south end was moving more slowly and had not yet crossed RGE RD 205.

Weather Conditions: The weather at the time of the incident was extremely windy.

Topography/Access: The terrain was difficult to manage as we were unable to access the grounds around the solar farm. It was very tall, dead grass, with slight hills.

Time of Day: The incident occurred during mid-afternoon.

Actions Taken:

Initial Assessment: After arriving, I assessed the situation and confirmed that I would need additional personnel and apparatus, so I requested Mutual Aid from Enchant and Picture Butte for their Tenders and Rapids. A unit from Vauxhall showed up, but it wasn't requested.

Fire Suppression Actions: I assigned 3 Rapid units to the head of the fire on the East side of RGE RD 205. All tender units were staged at a set of grain bins east of RGE RD 205. At that time, RDFC [REDACTED] Wyatt arrived on scene, and I assigned him to the west side RGE RD 205 as sector chief.

Safety Measures: It was challenging as the crew was unable to access the solar farm until the operator arrived. It was also difficult to access the fire, so crews waited and fought the fire once it reached the fence line.

Containment Actions: Once the operator of the Solar Farm arrived, we were able to access inside the fence and contain the fire from spreading.

Incident #: VCES-25-0062

Investigator: [REDACTED] Headrick

Date of Fire: March 25, 2025



Vulcan County Emergency Services

FIRE INVESTIGATION REPORT

FIRE INVESTIGATION
102 Center St - Po Box 180
Vulcan AB TOL 2B0
403 485 3123

Electrical VCES-26-0065

Cooperation with Other Agencies: The response involved mutual aid from Enchant and Picture Butte Fire, as well as a unit from Vauxhall.

Fire Behavior Monitoring: Throughout the response, fire behavior was monitored using on-the-ground observation.

Outcome: The fire was called loss stop by 17:31:11. The fire size at termination was estimated at [X acres/hectares].

Conclusion:

The incident was cleared, and all units returned to service. The fire did not result in any fatalities, and the damage to structures was minimal. No injuries to fire department personnel were reported. The fire was managed and contained in accordance with standard wildland fire protocols

Follow-up Required: RFC will be conducting an investigation by drone for the size of the fire next week.

This report is complete to the best of my knowledge

██████ Tompkins
Chief, Champion Fire Department
Chief on Call