2014 HYUNDAI ELANTRA		
S/N	**DESCRIPTION**	**AMOUNT(NGN)**
1	Front x Rear Brake Lining x Mechanic Workmanship	₦45,000
2	Radiator Fan, Resistor, Workmanship	₦80,000
3	Front x Rear Bumper Repair	₦60,000
4	Head Lamp Holder Repair	₦5,000
5	Front Grill Repair	₦7,000
6	Tank Cover (Priced)	₦12,000
7	Panel Beater Workmanship	₦60,000
8	Air Conditioner Fix, Compressor Fan, AC Gas, Air Filling + Workmanship	₦40,000
9	Battery Replacement (75AH Mandate Korea)	₦70,000
10	Tires(215 x 55 x 17) 4 Unit	₦96,000
11	Vulcanizer (Pending)	₦6,000
12	Windscreen x Fixing	₦100,000
	TOTAL	**₦581,000**

2019 TOYOTA CAMRY		
S/N	**DESCRIPTION**	**AMOUNT(NGN)**
1	Exhaust Turtle Neck	₦17,000
2	Welder Workmanship	₦8,000
3	Battery Replacement (75AH Mandate Korea)	₦70,000
	TOTAL	**₦95,000**