OpenARM Touch Controller bill of materials

- Protoboard
- Resistors (in the tutorial 6 x 10 M ohm have been used)
- 2 x 3.5 mm stereo audio jacks
- 2 x pieces of metal (in the tutorial 2 piezoelectric sensors have been used)
- 2 x mini vibrating motors