Event List

Supervisor enables area.

Supervisor disables area.

Supervisor sets new pH level.

Operator turns line on.

Operator turns line off.

Operator sets new bottle size.

Operator removes bottle.

Bottle drops into place.

Bottle becomes full.

pH moves out of limits.

pH moves within limits.