



Detected Defects:

- 1. Mouse bite: Small, semi-circular patterns along the edge of a PCB, typically caused by improper drilling or poor material quality. (Detected 2 times)
- 2. Missing hole: Occurs when a required hole is not drilled or punched through the PCB, often due to errors in the drilling process or issues with the drill files. (Detected 3 times)