

Defect Detection Report

Date: 2024-07-24





Detected Defects:

1. Short: An unintended connection between two points in a circuit, often caused by solder bridging, improper PCB design, or contamination during the manufacturing process. (Detected 3 times)

Built using Gradio