



Anomaly Report – Loose Connection

DJI_20241219111517_0901_T.JPG

DJI_20241219100710_0899_V.JPG



Anomaly Details

Category	Priority	Size	Loss
Loose Connection	Low	Large	24.08 kW

Temperature	Parameters	Remedial Action	Comment
74.38 °C	Voltage: 351V Current: 26A	Auto-generated action	Auto-detected anomaly

Latitude	Longitude	-	-
23.108531	84.211092	-	-

Location & QR Code



Location: 23.108531, 84.211092



Anomaly Report – Damaged Conductor

DJI_20241219110453_0110_T.JPG

DJI_20241219100554_0790_V.JPG



Anomaly Details

Category	Priority	Size	Loss
Damaged Conductor	Critical	Medium	40.79 kW

Temperature	Parameters	Remedial Action	Comment
117.75 °C	Voltage: 321V Current: 13A	Auto-generated action	Auto-detected anomaly

Latitude	Longitude	-	-
19.735375	78.45725	-	-

Location & QR Code



Location: 19.735375, 78.45725



Anomaly Report – Damaged Conductor

DJI_20241219110453_0110_T.JPG

DJI_20241219100302_0545_V.JPG



Anomaly Details

Category	Priority	Size	Loss
Damaged Conductor	Low	Small	24.13 kW

Temperature	Parameters	Remedial Action	Comment
63.33 °C	Voltage: 278V Current: 6A	Auto-generated action	Auto-detected anomaly

Latitude	Longitude	-	-
17.108885	83.296124	-	-

Location & QR Code



Location: 17.108885, 83.296124



Anomaly Report – Damaged Conductor

DJI_20241219111517_0901_T.JPG

DJI_20241219095701_0029_V.JPG



Anomaly Details

Category	Priority	Size	Loss
Damaged Conductor	Medium	Small	25.27 kW

Temperature	Parameters	Remedial Action	Comment
86.32 °C	Voltage: 288V Current: 13A	Auto-generated action	Auto-detected anomaly

Latitude	Longitude	-	-
22.961903	76.668529	-	-

Location & QR Code

Location: 22.961903, 76.668529

