


Anomaly Report – Damaged Conductor

DJI_20241219112408_1575_T.JPG

DJI_20241219100855_1048_V.JPG



Anomaly Details

Category	Priority	Size	Loss
Damaged Conductor	Medium	Large	5.86 kW

Temperature	Parameters	Remedial Action	Comment
47.22 °C	Voltage: 370V Current: 27A	Auto-generated action	Auto-detected anomaly

Latitude	Longitude	-	-
27.095195	83.002834	-	-

Location & QR Code


Location: 27.095195, 83.002834



Anomaly Report – Loose Connection

DJI_20241219110453_0110_T.JPG

DJI_20241219100616_0822_V.JPG



Anomaly Details

Category	Priority	Size	Loss
Loose Connection	Critical	Medium	12.64 kW

Temperature	Parameters	Remedial Action	Comment
53.31 °C	Voltage: 204V Current: 31A	Auto-generated action	Auto-detected anomaly

Latitude	Longitude	-	-
20.805939	82.225323	-	-

Location & QR Code



Location: 20.805939, 82.225323



Anomaly Report – Overheating Transformer

DJI_20241219111517_0901_T.JPG

DJI_20241219100710_0899_V.JPG



Anomaly Details

Category	Priority	Size	Loss
Overheating Transformer	High	Small	35.99 kW

Temperature	Parameters	Remedial Action	Comment
116.08 °C	Voltage: 367V Current: 27A	Auto-generated action	Auto-detected anomaly

Latitude	Longitude	-	-
14.509464	79.288061	-	-

Location & QR Code


Location: 14.509464, 79.288061



Anomaly Report – Damaged Conductor

DJI_20241219111447_0862_T.JPG

DJI_20241219100616_0822_V.JPG



Anomaly Details

Category	Priority	Size	Loss
Damaged Conductor	Low	Large	5.66 kW

Temperature	Parameters	Remedial Action	Comment
41.58 °C	Voltage: 203V Current: 20A	Auto-generated action	Auto-detected anomaly

Latitude	Longitude	-	-
16.196173	80.19652	-	-

Location & QR Code

Location: 16.196173, 80.19652

