Cadence Hotkeys - Layout

- ullet ${f r}
 ightarrow {f draw}$ rectangle. Select layer first.
- $\mathbf{k} \to \text{measurement rule}$.
- $k+right-click \rightarrow ruler options$.
- $\mathbf{shift} + \mathbf{k} \rightarrow \mathbf{remove}$ all rulers.
- $\mathbf{s} \to \text{stretch edge}$.
- $\mathbf{a} \to \text{align}$.
- $\mathbf{m} \to \text{move}$.
- $\mathbf{c} \to \text{copy}$.
- $\mathbf{p} \to \text{add path}$.
- $\mathbf{shift} + \mathbf{p} \rightarrow \mathbf{create}$ polygon.
- $\mathbf{f} \to \text{fit to screen}$.
- $\mathbf{g} \to \text{toggle gravity.}$
- $\mathbf{o} \to \text{create via}$.
- $\mathbf{u} \to \text{undo}$.
- $\mathbf{shift} + \mathbf{u} \to \mathbf{redo}$.
- $ctrl+p \rightarrow create pin.$
- $\mathbf{shift} + \mathbf{c} \to \mathbf{cut/chop}$ objects.
- $shift+m \rightarrow merge objects$.
- $shift+o \rightarrow rotate objects$.

- $\mathbf{shift} + \mathbf{x} \to \mathbf{descend}$ into object.
- $\mathbf{shift} + \mathbf{b} \rightarrow \mathbf{ascend}$ out of object.
- $scroll \rightarrow zoom in and out.$
- $ctrl+scroll \rightarrow move up and down.$
- $\mathbf{shift} + \mathbf{scroll} \to \mathbf{move}$ left and right.
- $\mathbf{shift} + \mathbf{click} \rightarrow \mathbf{select}$ multiple instances.
- $\operatorname{ctrl}+\operatorname{click} \to \operatorname{de-select}$ multiple instances.
- $\mathbf{shift} + \mathbf{a} \to \mathbf{select}$ all.
- $\mathbf{shift} + \mathbf{m} \to \mathbf{merge}$ layouts.
- left-click and drag \rightarrow select objects.
- right-click and drag → zoom in to region.
- center-click and drag \rightarrow drag view.
- $\mathbf{shift} + \mathbf{f} \to \mathbf{make}$ instance layout visible.
- $ctrl+f \rightarrow$ make instance layout invisible.
- $\mathbf{q} \to \text{edit parameters}$.
- $\mathbf{e} \to \text{display options}$.
- $\mathbf{shift} + \mathbf{e} \rightarrow \mathbf{layout}$ editor options.

Cadence Hotkeys - Schematic

- $\mathbf{f} \to \text{fit to screen}$.
- $\mathbf{i} \to \text{insert instance from library.}$
- $\mathbf{w} \to \text{add wire.}$
- $\mathbf{m} \to \text{move}$.
- $\mathbf{c} \to \text{copy}$.
- $\mathbf{q} \to \mathrm{edit}$ parameters.
- $l \rightarrow add label$.
- $\mathbf{u} \to \text{undo}$.
- $\mathbf{r} \to \text{rotate}$.
- $\mathbf{shift} + \mathbf{u} \to \mathbf{redo}$.
- $\mathbf{shift} + \mathbf{x} \to \mathbf{check}$ and save. Cannot undo after this.
- $scroll \rightarrow zoom in and out.$
- $ctrl+scroll \rightarrow move up and down.$

- $\mathbf{shift} + \mathbf{scroll} \rightarrow \mathbf{move}$ left and right.
- left-click and drag \rightarrow select objects.
- right-click and drag → zoom in to region.
- center-click and $drag \rightarrow drag view$.
- $\mathbf{shift} + \mathbf{e} \rightarrow \mathbf{descend}$. Double click does the same.
- $ctrl+e \rightarrow ascend.$
- $\mathbf{shift} + \mathbf{click} \rightarrow \mathbf{select}$ multiple instances.
- $\operatorname{ctrl}+\operatorname{click} \to \operatorname{de-select}$ multiple instances.
- $\mathbf{p} \to \text{add pin}$.
- $\mathbf{v} \to \text{add}$ vertical marker to graph.
- $\mathbf{h} \to \text{add horizontal marker to graph.}$
- $ctrl+e \rightarrow delete$ all markers.