SOURCE_ID: DGMS-CIR-2024-01

TITLE: Guidelines for Operation of Heavy Earth Moving Machinery (HEMM)

SOURCE_TYPE: DGMS Circular

PAGE_COUNT: 5

PUBLICATION_DATE: 2024-01-15

SYNTHETIC: true

ISSUING_AUTHORITY: Directorate General of Mines Safety, Dhanbad

---

1. Purpose: To ensure safe operation of HEMM in open cast mines.

2. Scope: Applies to all dumpers, excavators, dozers, and graders.

3. Guidelines:

3.1. Pre-shift inspection is mandatory. Brakes, steering, and lights must be checked.

3.2. Maximum speed limit for dumpers on haul roads is 30 km/h. Near loading/unloading points, it is restricted to 15 km/h.

3.3. Reverse horns and proximity sensors are mandatory for all HEMM.

3.4. Dust suppression measures, including water sprinkling, must be strictly enforced on all haul roads.

4. Compliance: Non-compliance will result in immediate suspension of operations.