

DATE Ref No. 1st Feb 2019 PES-FFL-055PL

229-7025, Tomken Road Mississauga ON L5S 1R6

Tel: 416-508-8730 Fax: 905-502-0753

Fatima Fertilizer Company Limited

E-110, Khayaban-e-Jinnah, Cantt., Lahore, Pakistan

Ph: +92 42-35909668

PO No	Incoterms	Payment terms	Shipping date		Customer ID
32264	CPT Lahore Airport	Against LC No. 0001LC25700/2019	2019-02-05		USD
S. No		Description	Qty Ordered	Qty Shipped	Extended Price
1	CVS Series "ET" Control V 667-70 ATO/Fail CLOSED & Bench Set @ 7-30 psi 1008/70 Handwheel Actu 316SST/Alloy 6 Plug, Alloy Trim: 5-3/8" Whisper III/E LCC Body. SST Tag: PCV-002 C/W CVS Series ALP-1200 6-30 psi Input, 6-30 psi Oc C/W CVS 67CFR Airset Filt	1	1	EA	
2	CVS Series 4150 pressure controller, 6-30 psi. output, 0-1500 psi, Reverse, SST Bellows. C/W CVS 67CFR Air Set Regulator, and mounting to the above valve Sour Process, Sweet instrument supply SST Tag: PIC-002		1	1	EA
3	CVS Series 670 Manual Lo C/W (Two) 0-60 psi Gauge and Regulator. Standard S	2	2	EA	
4	Filter Strainer at inlet 360AFI-1/4'-70C		1	1	EA
4a	-Aluminum Filter Assemb '-250 PSI Max Pressure -w/ DPI Indicator installed '-w/ Auto Float Drain Installed '-w/25-64-50C Disposable '-99.99% efficient at .01 n 122 - Stainless Steel Housing for 1/4" NPT Ports - 5000 PSI Max Pressure **Filter Element Sold Sep	C44 Alled Coalescing Filter Element Installed Dicron Silter	2	2	EA
5	12-57-50C Disposable Coalescing Filt - 99.99% efficient at 0.01		6	6	EA
6	FD130 -External Stainless steel F **w/ Plastic Internals Ma	oat Drain	3	3	EA
7	PCV 002 Spares: Repair Kit for 667-70 Actu Part# CVSR667X000702		1	1	EA
8	Diaphragm for 667-70 Part# CVS2N130902202		1	1	EA
9	CVS 6" ET W3B3 Alloy 6 T Part# CTK6-C3/0885	1	1	EA	
10	1 ' ' '	umatic Valve Positioner, utput. C/W mounting to above valve. er Regulator & mounting to above Valve.	1	1	EA



DATE Inv No 1st Feb 2019 PES-FFL-055PL

229-7025, Tomken Road Mississauga ON L5S 1R6

Tel: 416-508-8730 Fax: 905-502-0753

Shipped to: Fatima Fertilizer Company Limited

E-110, Khayaban-e-Jinnah, Cantt., Lahore, Pakistan Ph: +92 42-35909668

PO No	Incoterms	Payment terms	Shipping date		Customer ID
32264	CPT Lahore Airport	Against LC No. 0001LC25700/2019		2019-02-05	
S. No		Description	Quantity (EA)	Unit price	Extended Price
11	PIC 002 Spares: CVS 4150 Repair Kit-Majo Part# R4150MAJ	1	1	EA	
12	CVS 67CFR Regulator Repart# CVS67CFR-RK	1	1	EA	
13	0-1500 psi, Reverse, SST B	gulator, and mounting to the above valve	1	1	EA
		30in x 48in x 36in 1228 Lbs			
	Date of issue: 2019-0	L HABIB LIMITED PAKISTAN 90			
	PLANT. FURTHER DETA	S: SPARE PARTS FOR FERTILIZER PLANT LS ARE STRICTLY AS PER PROFORMA 55 DATED DECEMBER 28, 2018			
	We Certify that all Merchandize is of Canada origin				
	CPT LAHORE PAKISTAN -	INCOTERMS : 2010)			