HSE Risk Assessment							Reference N ^o : HSERA/002			
						Facility : The Palms Estate, Emporio Date of the assessment:				
						Mall and	'	17 /04/2021		
Ass	essors' Nam	es			Assessors' Tittle					
Mis	s Anne Ajibo	gun					HSE Officer			
	man Resourc				Employer					
Gbenga Adebiyi Daniels Who / Risk							Supervisor			
				•			Additional Control to be implemented			
No		A	II I	What is at	Current	Level	Controls	Responsible	Date of	
IN.	Location	Activity	Hazard	Risk	Controls	(High, Medium,		person	Completion	
						Low)				
1	Emporio	Casting	Inhaling cement can cause Lung diseases.	Laborers Employees	Non	High	Reusable sustainable masks should be bought for all staffs. As well as milk for anyone directly exposed to using cement.	Management	Incomplete	
2	The Palms	PPE	Exposed to danger	Everyone on site	Wearing available PPE	High	Purchase adequate PPE, Take inventory for special PPE providing universal sizes for temporary staffs and visitors	HSE and Management	Incomplete	
3	Dumpsite	Refuse dump	Clumsy environment has potential to cause harm and invite rodents to site.	Everyone on site	Routine Saturday burning	Medium	Routine burning	HSE Officer and Cleaners	17/04/2021	
4	Site Office	First Aid	III/ injured workers aren't being treated properly due to insufficient items in the first aid box	Injured workers and those exposed to potential harm due	Wearing PPE, Improvising, buying medication as victims complain	High	Report to management to buy first aid materials	Management	Incomplete	

				to site	through the				
				to site	through the				
				work	help of the				
					store				
					manager.				
5	Major	Site	Injury to self. Visitors	Visitors	PPE Weakly	High	Alcohol spray to prevent wear and	HSE Officer	14/04/2021
	Site Entry	Visitors	refuse to wear PPE,		maintenance		tear of PPE.		
			with various						
			complaints from				Visitors henceforth must follow		
			health implications				through phase 7 for their safety.	SSL	14/04/2021
			to personal reasons.						
			Passing through						
			hazardous places in				Review customer policy	Management	Incomplete
			site has potential to				,		
			cause harm.						
6	The	All	Lack of signage on	Everyone	Meetings	High	Report to management	Management	Incomplete
	Palms	activities	site causes people to	,					
	Estate,	on site	not be constantly						
	Emporio		reminded of their						
	and		environment.						
	Guzape								
7	Guzape	Fall from	Poorly Bamboo	All	Meetings	High	Another scaffold will be mounted to	HSE and	Incomplete
		height	scaffolds	Scaffolders	and PPE		bring old ones down.	Workers	
		2.0		and					
				passer-by					
8	The	Residents	In the case of fire	Residents	Non	High	Provide and teach residents how to	HSE and	Incomplete
	Plams		outbreak			6	use the fire extinguisher (class A,B,C	Management	compiete
	Estate		Jacorcan				Powder fire extinguisher)	Management	
	Lotate						1 OWACT THE EXTINGUISHELL		<u> </u>