## COST/M TO RUN SPEED CONVERSION FORMULA:

(MACHINE RATE) × 1000 = PW SPEED

FOR EXAMPLE: GLUER IS COSTED AT \$30/M IF GLUE LAP IS LESS THAN 15 INCHES, AND \$2/M FOR EACH ADDITIONAL INCH. I WILL ASSUME GLUE MACHINE RATE/HOUR IS \$30.

GLUER = \$30 STANDARDS: GLUE LAP LENGTH BLUNK WIDTH

JOINT 9999

GLUE 15 1000 = \*30/M

LENGTH 16 938 32/M