break away points, There is No-Nieed of asymptotes Poles for given Transfer function is s=-1 and s=-3 No infinite znoes (in poles to be added, Henre 8=-4. and zeroes of given Frans ber function is S=-2 and No of Zennes - No of poles, Welan use, characteristic Equation for Breakmand Given Transfer function, K(S+2)(S+4) (8+1) (8+3)