

Production Line

7 Sensor types Utrasonic
2 Controllers Ardaino
3 Motor types Servo
41 Circait design
51 Programming
51 Operation


Measure level or distance -> Quick & easy to implement



143,681



(83, 78)



range between (95 - 85)
Relse