

$$\frac{U_1}{U_2} = \frac{n_1}{n_2} = \frac{1000}{20} = \frac{50}{1}$$

$$U_1 = 220 V \implies U_2 = 4.4 V$$

Bild II 2-11 Klenspänningstransformator